This certificate does not automatically constitute authority to install the item(s).  Where the user/installer performs work in accordance with regulations of an air	USER/INSTALLER RESPONSIBILITIES		13d. Name	approved design data and are in condition for safe operation non-approved design data specified in Block 12	Certifies work specified in Blocks 11/12 was accomplished in accordance with Title 14 work, the items are approved for return to service under Title 14, code of Federal Reg. The work identified in block 11 and described in block 12 herein has been performed released to service under TCCA approval number 808-09 For work carried out please refer to our Service Breakdown Report number 45032787 SN:( AB60950 );MOD Strike:1;	12. REMARKS		10300 Engine Vibration Monitoring Unit	7.	FEDERAL OFFICE OF CIVIL AVIATION (FOCA) SWITZERLAND  4. Organisation Name and Address
tem(s).		13e. Date (dd mmm yyyy) 14d. Name	13c. Approval/Authorisation Number 14b. Auth	14	Certifies work specified in Blocks 11/12 was accomplished in accordance with Title 14, code of Federal Regulations, part 43 and with respect to that work, the items are approved for return to service under Title 14, code of Federal Regulations, part 43 and with respect to that The work identified in block 11 and described in block 12 herein has been performed in accordance with CAR 571 and is For work carried out please refer to our Service Breakdown Report number 45032787 SN:( AB60950 );MOD Strike:1;			Part No. 241-247-013-005	Meggitt SA, t/a Meggitt Sensing Systems Address: Route de Moncor 4, P.O. Box 1616, CH-1701, Fribourg, Phone: +41 (0)26 407 11 11 Fax: +41 (0)26 407 18 60	AUTHORISED RELEASE CERTIFICATE
		J. Berr	14b. Authorised Signature  VM - CS  COA - 00	A. X Part-145.A.50 Release to Service X Other regulation specified in Block 12  Certifies that unless otherwise specified in Block 12, the work identifed in Block 11 and described in Block 12 was accomplished in accordance with Part -145 and in respect to that work the items are considered ready for release to service	43 and with respect to that VM8Y694J.		1 (AB60950)	Qty Serial No.	Switzerland	SE CERTIFICATE
	14e. Date (dd mmm yyyy) 15/MAY/2012		14c. Certificate/Approval Ref No. CH.145.0251	Other regulation specified in Block 12 work identified in Block 11 and described in 5 and in respect to that work the items are	SHIP TO: AJ Walter Aviation Ltd Logistics Centre The Business Park Maydwell Ave Slinford West Sussex RH13 0AS Vereinigtes Königreich	•	INSPECTED/TES	11. Status / Work	5. Works Order/Contract or Invoice No. Notification: 350055129 PO: 179189	3. Form Tracking Number 84700212-10300

airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from





Sold to
A.J.WALTER AVIATION
Viscount House
Partridge Green
WEST SUSSEX
RH13 8RA
UNITED KINGDOM

 Page
 1 of 1

 Date
 14.05.2012

 Service notification
 350055129

Meggitt quality notification

 Service order/Report No
 45032787

 Sales order
 9953048318

 Customer PO#
 179189

Customer quality ref Customer Part#

Equipment serviced here

Item Part number/

Serial number

Mod Status/Revision

Description

241-247-013-005

AB60950

1/-

EVM 247 - Engine Vibration Monitoring Unit

Failure / complaint (as reported by customer)

For Repair / Please Repair under T&M Please quote and hold /
Flight Crew reported temporary loss of N1 Vibration indication in
flight. During ground high power runs for ENG balancing technical staff
reported "No Response" from the EVMU above 82% N1 speed / LZ-MDA / EASA
& FAA & TCCA & JCAB (will not be provided by Meggitt
SA)

Findings

Seal(s) ok and no physical damage has been noticed.

No failure detected in memory.

Self test is pass.

Unit works within specifications.

No fault found.

Materials replaced

Item Qty UOM Part Number

**Batch Number Description** 

.000

<none>

## Work performed

Incoming Inspection (Admin)
Preliminary hidden damage inspection
SB/SIL/AD status check performed
Visual Inspection
Check connectors condition
Incoming ATP Technician

Read & Analyze Internal Memory

Final ATP Technician

Unit tested and inspected iaw CMM-77-32-08 rev 01

Administration

Meggitt Sensing Systems, Meggitt SA

P.O. Box CH-1701 Fribourg Switzerland VM-P

David ]

Tel: +41 (0) 26 407 11 11 Fax: +41 (0) 26 407 17 00 www.meggittsensingsystems.com www.meggitt.com

The Meggitt SA standard purchasing terms and conditions CGA 2011-11 shall apply and are available at www.meggitt.com/commercial.