Honeywell

SERVICE REPORT

AJ WALTER AVIATION LTD

Honeywell, Inc.
Seattle - CS ERB & R&O
4150 Lind Avenue SW
RENTON WA 98057

SR NUMBER:	309154278	5004374223		TEL: 800-601-3099	FAX: 602-822-9194	
PO: 153980		CUSTOMER PART NUMBER:		CONTRACT NUMBER:		
DATE REJECTED:		DATE RECEIVED:		DATE COMPLETED:		
26 MAY 2011		27 MAY 2011		03 JUN 2011		
A/C TYPE:			A/C TAIL NUMBER:		A/C SERIAL NUMBER:	
UNK		YR-BAJ	YR-BAJ		UNK	
PACKING STATUS:		SEALS INTACT:		PHYSICAL DAMAGE:		
		no	no		NO DAMAGE FOUND	
#3 Coax U/S	AL:					
AS RECEIVED:		AS REI		LEASED:		
ART NUMBER 071-50001-8102			071-50	0001-8102		
DESCRIPTION:	TCAS ANTENNA		TCAS	TCAS ANTENNA		
SERIAL NUMBER:	30789		30789	30789		
UCN/SER:						
HW MOD STATUS:	1		1			
SW MOD STATUS:						
SOFTWARE LOAD:						
REASON FOR REMOVAL CONFIRMED: Rejection Not Confirmed			ESTIMAT	ESTIMATE SUPPLIED: Yes		
PRIMARY SHOP FINDING: Does Not Apply			WARRAN	WARRANTY: Original Warranty Expired		
YPE OF SERVICE: Unit Returned As Is			TECHNIC	TECHNICIAN: Don Engelson		
PAGE DETAILING V		ONG WITH MATERIALS USI	ED, IS ATTACHED IN F	PAGE 2.		
	ORIZED PERSON:	RETURN TO SERVICE IS NO	DATE: 6	10/1		

PAGE: 1 OF 2

Honeywen

SERVICE REPORT

AJ WALTER AVIATION LTD

Honeywell, Inc. Seattle - CS ERB & R&O 4150 Lind Avenue SW RENTON WA 98057

FAX: TEL: 602-822-9194 800-601-3099 SR NUMBER: 309154278

CONTRACT NUMBER: CUSTOMER PART NUMBER:

PO: 153980 S/N OFF P/N OFF S/N ON REQ QTY DISPOSITION DESIGNATION PART NUMBER FITTED COMMENT

Customer's TCAS Antenna is Beyond Economical Repair per Service Letter 95-01, Rev. 5. Customer denied Quote for new replacement. Returning BER TCAS Antenna in as-is/unserviceable condition as per Customer request.

PAGE: 2 OF 2