


1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2.		AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: 0000000530	
4. Organization Name and Address: MTI AVIATION INC. 13150 NW 45 AVENUE, OPALOCKA, FL, 33054, UNITED STATES 305-817-4244 FAA REPAIR STATION NO. Q8VR235Y				5. Work Order/Invoice Number: WO1021300 / RO206778				
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:			
1	OIL COOLER	UAS38551-3	1	0691	OVERHAULED			
12. Remarks : Unit OVERHAULED I/A/W CMM ATA: 24-11-05 REV: 0 DATED: 15/OCT/1996 No FAA or EASA S/B and AD's complied with at this shop visit. Full details of work carried out held on Work Order: WO 1021300 ESN#874746								
Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 Approval No. 145.6145								
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation. ☐ Non-approved design data specified in Block 12								
13b. Authorized Signature:		13c. Approval/Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		14b. Authorized Signature: 		
13d. Name (Typed/Printed):		13e. Date (dd/mm/yyyy) :		14c. Approval Certificate No.:		14d. Name (Typed/Printed): ROBERTO PEREZ		
				Q8VR235Y		14e. Date (dd/mm/yyyy) : 18/AUG/2023		
User/Installer Responsibilities								
It is important to understand that the existence of document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.								

WORK ORDER FORM

Work Order Num: WO1021300
 RO Num: R0206778
 SHIPP NA
 Date Printed: 8/18/2023 11:55:19 AM
 Num Of Items: 1

MTI AVIATION INC.
 13150 NW 45 AVENUE
 OPA LOCKA FL, 33054
 UNITED STATES
 305-817-4244
 INFO@MTIAVIATION.COM

Ship To

NEXT LEVEL AVIATION LLC
 1671 NW 144 TERRACE
 UNIT # 111
 SUNRISE FL, 33323
 UNITED STATES
 ATTN: MIKE

NEXT LEVEL AVIATION LLC
 1671 NW 144 TERRACE
 UNIT # 111
 SUNRISE FL, 33323
 UNITED STATES
 ATTN: MIKE

08VR235Y EASA.145.6145



Cust Name: NEXT LEVEL AVIATION LLC
 Incoming PN: UAS38551-3
 Serial Num.: 691
 PN Desc.: OIL COOLER
 Outgoing PN: UAS38551-3

PRELIMINARY INSPECTION

VERIFIED PN PER ID PLATE

CUSTOMER RO READS S/N:691 BUT UNIT READS:0691

Technician: DAVID HERNANDEZ

Inspector: ROBERTO PEREZ

Date: 08/10/2023

PRE TEST

UNIT PASSED ALL FUNCTIONAL TEST

Technician: DAVID HERNANDEZ

Inspector: ROBERTO PEREZ

Date: 08/10/2023

HIDDEN DAMAGE

N/A

TEARDOWN FINDINGS

UNIT WAS DISASSEMBLED, CLEANED, & INSPECTED PER MFG'S SPECS

TEAR DOWN EVALUATIONS REVEALS THE FOLLOWING DISCREPANCIES:

-Missing gasket

DUE TO TEAR DOWN FINDINGS THE UNIT WILL BE QUOTED FOR OVERHAUL.

NOTE: NICKS, DENTS, OR SCRATCHES DO NOT AFFECT FIT, FORM,

OR FUNCTION OF UNIT.

Technician: DAVID HERNANDEZ

Date: 08/10/2023

Inspector: ROBERTO PEREZ

Date: 08/10/2023

FINAL INSPECTION

N/A

Inspector: ROBERTO PEREZ

Date: 08/10/2023

CORRECTIVE ACTION

ALL DISCREPANCIES NOTED IN TEAR DOWN WERE CORRECTED.

UNIT WAS REASSEMBLED, TESTED, AND FINALIZED IAW

CMM ATA:24-11-05 REV#0 DATE:10/15/1996

UNIT RETURNED TO SERVICE OVERHAULED

Technician: DAVID HERNANDEZ

Date: 08/10/2023

Inspector: ROBERTO PEREZ

Date: 08/10/2023

MODIFICATION/SERVICE BULLETINS

NA

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS OVERHAULED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, IS APPROVED FOR RETURN TO SERVICE, AND OTHER PERTINENT DETAILS OF THE WORK ARE ON FILE AT THIS REPAIR STATION.

Approved for return to service by:



Date: 8/18/2023



MTI AVIATION INC.
13150 NW 45 AVENUE
OPA LOCKA FL 33054
UNITED STATES
305-817-4244
INFO@MTIAVIATION.COM

Q8VR235Y EASA.145.6145

Packaging Slip Id: PS(SO)-000453
Invoice Num: -
Credit Terms: NET 30
Num of Pieces: 1
Num of Items: 1
Date and Time Printed: 8/21/2023 2:47:44 PM

WO PACKAGING SLIP

Invoice Date & Time: -
WO Num: WO1021300

Shipping Terms: -
Num Of Containers: 1

Prepared By: SHIPP NA

Sold To

NEXT LEVEL AVIATION LLC
1671 NW 144 TERRACE
UNIT # 111
SUNRISE FL 33323
UNITED STATES

PO/RO Ref: RO206778
Buyer: JONOTHAN BLANCO
Sales Person:
Ship Order Num: WOS576
Ship Via: PICK UP

Line Num	PN	Part Description	Ser Num	STL Num	UOM	Cond	Qty Shipped
1	UA538551-3	OIL COOLER	691	STL-000102	EA	AR	1



Notes

Terms and Condition

Order subject to inspection at destination. Payments are to be made in U.S. Dollars, title of all goods sold shall remain with the seller until full payment is received from customer. Attorney & collections fees due to unpaid invoices will be charged to the customer. No return or refunds after 10 days from invoice date, no returns allowed without an MTI authorized RMA. All returned goods are subject to a 25% restocking fee, if material returned is missing the original teardown report and/or FAA 8130-3 the customer will be responsible for any fees incurred in recertifying the unit back to its original sold condition. These commodities may be regulated by the U.S. Government export control regulations. The above commodities shall not be shipped to any country that has an embargo placed on it by the U.S. Government or any entity on the U.S. debarred list. These commodities, technology, or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited (U.S. Department of Commerce).



0333 WED 08/23/08 16 PR 2D 4162957
NEXT LEVEL AVIATION, LLC
1671 NW 144TH TER
STE 111
FORT LAUDERDALE FL 33323-2879-36
ETP: 4 SP-PD:84-Y
9622042210008732384700773118635700