

1. Approving Competent Authority / Country CAA UK		AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. Form Tracking Number: W202008668	
4. Organization Name and Address: Avia Technique SK AeroSafety Group Avia Technique Ltd. Unit 1,3,4 & 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511		5. Work Order / Contract / Invoice Number: W202008668 R377204		11. Status / Work: Overhauled	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	
1	Fire Extinguisher	472625-1	1.00	62080EL	
12. Remarks: CMM: 26-20-85 Revision: 13 Next Overhaul/Hydrostatic Test Due: 02/2026. Last Overhaul/Hydrostatic Test: 02/2021. Checked Weight: 86.22 Lbs. Cartridge P/N: 446203. S/N: ACU2350. Service Life Start: 03/2013. Service Life End: 03/2023. Cartridge P/N: 446203. S/N: ACU2349. Service Life Start: 03/2013. Service Life End: 03/2023. Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.					
"The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under certificate no. 18QY183X"					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13b. Authorised Signature:		13c. Certificate (Approval Ref No.):		14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.	
13d. Name		13e. Date (dd/mm/yyyy):		14b. Authorised Signature: 14c. Certificate (Approval Ref No.): UK.145.00846	
14d. Name Jack West		14e. Date (dd/mm/yyyy): 26/Feb/2021			
USER / INSTALLER RESPONSIBILITIES					
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1. Approving Competent Authority / Country EASA		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1				3. Form Tracking Number: W202008668	
4. Organization Name and Address:  Avia Technique SK Aero Safety Group		Avia Technique Ltd. Unit 1,3,4 & 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511				5. Work Order / Contract / Invoice Number: W202008668 / R377204 R377204	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:		
1	Fire Extinguisher	472625-1	1.00	62080EL	Overhauled		
12. Remarks: CMM: 26-20-85 Revision: 13 Next Overhaul/Hydrostatic Test Due: 02/2026. Last Overhaul/Hydrostatic Test: 02/2021. Checked Weight: 86.22 Lbs. Cartridge P/N: 446203. S/N: ACU2350. Service Life Start: 03/2013. Service Life End: 03/2023. Cartridge P/N: 446203. S/N: ACU2349. Service Life Start: 03/2013. Service Life End: 03/2023. Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.							
13a. Certifies that the items identified above were manufactured in conformity to:		14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.					
13b. Authorised Signature:		13c. Certificate /Approval Ref No.:		14b. Authorised Signature:		14c. Certificate /Approval Ref No.:	
				 		EASA.UK.145.00846	
13d. Name		13e. Date (dd/mm/yyyy):		14d. Name		14e. Date (dd/mm/yyyy):	
				Jack West		26/Feb/2021	
USER / INSTALLER RESPONSIBILITIES							
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							



Avia Technique Ltd.
Unit 1,3,4 & 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom
RG41 2QJ
Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: W202008668

Date Printed: 20/08/2020

Page: 1

To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Ship To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Reference: R377204

Date Received: 10/08/2020

Part Number: 472625-1

Description: Fire Extinguisher

Serial Number: 62080EL

Customer Remarks:

Overhaul

HST due

Results from inspection:

Unit requires Overhaul

DOM: 06/2003.

Next Overhaul Due: 07/2018.

Cartridge P/N: 446203. S/N: ACU2350. Life Expiry: 03/2023.

P/N: 446203. S/N: ACU2349. Life Expiry: 03/2023.

Pressure switch functional tests

The Pressure Switch passed functional testing when full but may fail when removed/fully tested. In this case, the customer will be re-quoted for the full cost of a new Pressure Switch

Corrective actions:

Overhaul with reference to the correct CMM Rev

Replace Cartridges.

Inspection report generated by: Jonathan Kraty

