

1. Approving Competent Authority/Country CAA/UK		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number ARC42961	
4. Organisation Name and Address  INFLITE MRO SERVICES (Formerly Inflight (Southend) Ltd)		WAS (COMPONENTS) LTD North Hangar Aviation Way Southend-on-Sea Essex SS2 6UN United Kingdom Tel: +44(0)1702 348601 Fax: +44(0)1702 541534 Email: Web:		5. Work Order/Contract/Invoice W40290	
6. Item 1	7. Description COFFEE MAKER	8. Part No. 416-1001-23	9. Qty. 1	10. Serial No. 0987	11. Status/Work REPAIRED
12. Remarks "WP55168" REPAIRED AND TESTED I.A.W B E AEROSPACE 25-30-31 REV 4 DATED MAY 2015 TCCA No : - 816-06 -					
Return to Service in accordance with FAR 43.9. Certificate No: EGWY725K Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Title 14, Code of Federal Aviation Regulations, part 43 and in respect to that work, the items are approved for return to service. Pertinent details of the repair are on file at this repair station under order. No: W40290 Sign:  Date: FEB 15 2018					
13a. Certifies that the items identified above were manufactured in conformity to:		14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in block 12			
☐ Approved design data and are in condition for safe operation ☐ Non-approved design data specified in block 12		Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.			
13b. Authorised Signature	13c. Approval/Authorisation Number	14b. Authorised Signature 		14c. Certificate/Approval Ref. No. UK.145.00579	
13d. Name	13e. Date (dd mmm yyyy)	14d. Name A. JOHNSON		14e. Date (dd mmm yyyy) 15 Feb 2018	
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

Registered address:- Infilite House, Stansted Airport, Stansted, Essex, CM24 1RY

For and on the behalf of Infilite MRO Services Ltd

Signed: 
Date: FEB 15 2018WAS
41

Name: ASHA HASSAN

Inspection Findings:

REPORTED DEFECT : LEAKING - WARRANTY CLAIM

Fault confirmed: Failure of clamp at Solenoid to Brew Head pipework.

Unit disassembled as required, pipework to be reworked as required. Replace clamps at and around affected area, descal, reassemble and test.

Warranty accepted.

17-01-18. Job requested from 21-09-17 as unit failed on final test due to a faulty PCB which is not covered under warranty as this component did not require replacement at it's last shop visit.

All work already carried out to this unit is still free of charge, however the cost of the replacement PCB and the labour to fit and final test the unit are chargeable

To be released: Repaired and Tested IAW B E aerospace 25-30-31 rev 4 dated May 2015

WARRANTY REPAIR
FAULT - LEAKING
PLS REPAIR
REF. (OUR) WP52481

Workscope Overview:

Removed From:	Serial No:	Reg No:	Position:
Part No: 416-1001-23	Description: COFFEE MAKER	Workscope: Repair	Dept: Electrical Workshop
Serial No: 0987	Release Type: Dual		
Your Ref: W40290	Our Ref No: WP55168	Test Required: N/A	
E-Mail: yohai.nezri@ajw-aviation.com Tel: 01403 711777 Fax: 01403 712135 Attn: Mr Yohai Nezri A J Walter (Aviation) Limited The Headquarters Maydwell Avenue Slinfold West Sussex RH13 0SH United Kingdom			

Workshop Report

No: IR55633

Issue: 01

Date: 01-Sep-17

WAS (COMPONENTS) LTD: EASA Part 145: UK.145.00579:
 WAS (COMPONENTS) LTD: FAA Repair Station: EGWY725K:
 Tel: +44(0)1702 348601
 United Kingdom
 SS2 6UN
 Essex
 Southend-on-Sea
 Aviation Way
 North Hangar
 Infilite MRO Services Ltd

MRO SERVICES [Formerly Infilite (Southend) Ltd]

