Approving Competent Authority 2.			3. Form Tracking Number:
CAA.UK	AUTHORISED REL	AUTHORISED RELEASE CERTIFICATE  EASA FORM 1	W201905025
4. Organization Name and Address:	td.		5. Work Order / Contract / Invoice Number:
Avia Technique	Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ	1G41 2QJ	W201905025
SK AeroSafety Group	Pn: +441189789789, Fax: +441189794511		R355655
6. Item 7. Description:	8. Part Number:	9. Quantity: 10. Serial Number:	11. Status / Work:
Passenger Service Unit	417N3011-1401B	1.00 80103-1010	Repaired
12. Remarks: CMM: 25-23-38 Revision: 43		"The work identified	"The work identified in Block 11 and described herein has been
		to that work, the items are certificate no [80Y183X"	to that work, the items are approved for return to service under certificate no. IBOY183X"
Avia Technique have checked and verified t	Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.	•	
13a. Certifies that the items identified above were manufactured in conformity to:	e manufactured in conformity to:	14a. X Part-145.A.50 Release to Service X	Other regulation specified in Block 12
Approved design data and are in a condition for safe operation.	ion for safe operation.	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 19 was accomplished in accordance with Part 145, and in respect to	the work identified in Block 11 and
Non-approved design data specified in Block 12	ook 12	work the items are considered ready for release to service.	ervice.
13b. Authorised Signature:	13c. Certificate /Approval Ref No.:		14c. Certificate /Approval Ref No.:
		(3)	UK.145.00846
13d. Name 1:	13e. Date (dd/mmm/yyyy):	14d. Name	14e. Date (dd/mmm/yyyy):
		Steven Lewis 26	26/Sep/2019
	USER / INSTALLER	USER / INSTALLER RESPONSIBILITIES	
This certificate does not automatically constitute authority to install the item(s).	authority to install the item(s).		
Where the user/installer performs work in accord user/installer ensures that his/her Airworthiness .	Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airwort user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.	Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.	block 1, it is essential that the
Statements in blocks 13a and 14a do not constitue that one tone to the state of the	ute installation certification. In all cases aircraft m he aircraft may be flown.	Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.	tion issued in accordance with the



# Avia Technique Ltd. Unit 1,3,4 & 6 Fishponds Estate **Fishponds Road** Wokingham, Berkshire, United Kingdom

**RG41 2QJ** Ph: +441189789789, Fax: +441189794511

# **Tear Down/Inspection**

Work Order #: W201905025

**Date Printed:** 

20/05/2019

Page:

# To:

A.J. Walter Aviation Ltd. **Maydwell Avenue** The Headquarters **Slinford RH13 0AS United Kingdom** 

## Ship To:

A.J. Walter Aviation Ltd. **Maydwell Avenue** The Headquarters Slinford RH13 0AS **United Kingdom** 

Reference:

R355655

Date Received: 21/03/2019

Part Number:

417N3011-1401B

Description:

Passenger Service Unit

**Serial Number: 80103-1010** 

#### **Customer Remarks:**

"Attendant call inop. for repair and restoration - return condition: repair"

### Results from inspection:

Unit requires Repair and Recertification

**DOM: APR 2002** 

Unit received with Missing Speaker

Unit received with Damaged Overlay

Unit received with Missing Generator

### Corrective actions:

Repair and Test with reference to correct CMM

Fit replacement Generator, Overlay and Speaker

Inspection report generated by: Steven Lewis

Reference: SK-GF-005

Issue: Initial