

4. Organization Name and Address: SUMITOMO PRECISION USA, INC. 1639 FALCON DRIVE DESOTO, TEXAS 75115	5. Work Order/Contract/Invoice Number: 30144373
--	---

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	DEFLECTOR, EXHAUST	792995-3	1	N/A	
2	SPRING, HELICAL COMPRESSION	788090-1	10	N/A	NEW

12. Remarks:

THE NEW PART(S) LISTED ABOVE ARE SUBCOMPONENTS OF AN FAA PMA PART/ASSEMBLY.
 THIS PMA PART(S) IS NOT A CRITICAL COMPONENT

13a. Certifies the items identified above were manufactured in conformity to:

☒ Approved design data and are in a condition for safe operation.
☐ Non-approved design data specified in Block 12.

13b. Authorized Signature: 	13c. Approval/Authorization No.: 272792820	13d. Name (Typed or Printed): WILLIAM DENIHAN	13e. Date (dd/mm/yyyy): 07/Aug/2018
--------------------------------	---	--	--

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

