


1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 194849 CTLD 1	
4. Organization Name and Address: BP Aero Services 4965 HANSON DR. IRVING, TX 75038 USA Ph: 469-208-0060, Fax: 972-252-2009 FAA Approval Holder: 442R874B				5. Work Order/Contract/Invoice Number: 85587 Number of attached pages – 1	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	PANEL, ASSY-ACOUSTICAL AFT	338-068-411-0	3	N/A	OVERHAULED
12. Remarks: ATA: 72-23-08 E.S.N. 779481 Repair Order: ERO17462 Customer: AJ Walter Aviation Ltd See Workscope Report : 85587 All work performed in accordance with CFM56-5B Manual ID: CFMI-TP-SM.9, Revision #: 78, Revision Date: 3/15/2022					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the component is considered ready for release to Service under EASA Part 145 Approval Number: EASA.145.6427					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13b. Authorized Signature:		13c. Approval Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14b. Authorized Signature: 	
				14c. Approval/Certificate No.: 442R874B	
				14e. Date (dd/mm/yyyy): 30-Dec-2022	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1 国家 Country P.R. CHINA	2. 中国民用航空总局 CAAC ☐ 符合性 Conformity 批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG	☒ 适航性 Airworthiness Certificate Ref. No. 78887	3 证书编号			
4 单位 BP Aero Services FAA Repair Station # 442R874B 4965 HANSON DR. IRVING, TX 75038 USA Tel: 972-252-2800, Fax: 972-252-2009	5 工作单/合同单/发票 Work Order / Contract / Invoice 85587 Number of attached pages - 1					
6 序号 Item	7 内容 Description	8 件号 Part No.	9 适用性 Eligibility	10 数量 Qty	11 系列号/批号 Serial/Batch No.	12 产品状态 Status/Work
1	PANEL, ASSY-ACOUSTICAL AFT	338-068-411-0	CFM56-5B	3	N/A	OVERHAULED
13 备注 Remarks ATA: 72-23-08 E.S.N. 779481 Repair Order: ERO17462 Customer: AJ Walter Aviation Ltd See Workscope Report : 85587 All work performed in accordance with CFM56-5B Manual ID: CFMI-TP-SM.9, Revision #. 78, Revision Date: 3/15/2022						
14 新产品 New Parts 兹声明上述产品除第13项的其他规定以外，以按照上述国家适航条例进行制造检查，并且该产品（出口产品）符合经批准的设计数据和进口国提出的专用要求。 Certifies that the part(s) identified above, except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.						
15 使用过的产品 Used Parts 兹声明上述产品除第13项的其他规定以外，已按照上述国家适航条例和进口国通知的特殊要求进行了工作，该产品出于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)						
16 批准人签名 Signature 		18 批准日期 Date Dec/30/2022		19 中国民航总局授权 Issued by or on behalf of the CAAC F00100709		
17 批准人姓名(打印的) Name (Printed) Mussie Dair		AAC-038(12/94)				

Workscope Report

Work Order #: 85587

Date Printed: 12/30/2022

Time: 9:09:29 PM

Page: 1

BPAERO SERVICES

4961 HANSON DRIVE IRVING TX 75038 972-252-2800 WWW.BPAERO.COM

FAA REPAIR STATION #442R874B

To: AJ Walter Aviation Ltd THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM		Ship To: Repairs Group THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM	
Ref #: ERO17462	Phone #: +44 1403 711 777	Fax #: +44 1403 710 936	Email: stockmarket@ajw-aviation.com
Code: 12	Site: AWWL	PN: 338-068-411-0	Descr: PANEL, ASSY-ACOUSTICAL AFT
Qty: 4	Station:	Make:	Model:
CFM56-5B-9 CFM56-5B			
ESN 779481	Warranty Request N/A		
CSN	Complies With		
Entry Date: 11/28/2022	Need Date: 12/8/2022	Compl. Date: 12/30/2022	Warranty: No
			Container:

Serial Numbers:
 Inspection Findings:
 Visual / Dimensional Findings
 1 REJECTED DUE TO REPAIR 10 OUTSIDE OF BPAERO CAPABILITIES NOT SERVICEABLE NOT REPAIRABLE.
 Defects in Protective Coating.
 Erosion in area A.
 Repairs Required:
 Repair 002- Reconditioning of the Protective Coating by Anti erosion paint.
 Repair 006- Erosion Repair by Epoxy Resin Adhesive.
Corrective Actions:
 Overhauled - 8130/CAAC issued
 Repairs Performed:
 Repair 002- Reconditioning of the Protective Coating by Anti erosion paint.
 Repair 006- Erosion Repair by Epoxy Resin Adhesive.

Task Description
 RECEIVING INSPECTION
 CFM56-5B-ESM-TASK-72-23-08-100-001 - CLEANING
 CFM56-5B-ESM-TASK-72-23-08-200-001 - INSPECTION
 PART NUMBER VERIFICATION
 CFM56-5B-ESM-TASK-72-23-08-300-006 - REPAIR 006
 CFM56-5B-ESM-TASK-72-23-08-300-002 - REPAIR 002
 PHASE II FINAL INSPECTION
 FINAL CLEANING AND CONDITIONING
 FINAL INSPECTION



MB

Seq	Status
0	Complete
100	Complete
200	Complete
225	Complete
306	Complete
310	Complete
399	Complete
00000	Complete
00000	Complete
00000	Complete



BPAERO SERVICES LLC

4965 Hanson Drive Irving, TX 75038
972.252.2800 www.bpaeroservices.com
FAA Repair Station #442R874B

Date: 12/7/2022

Manufacturer: CFMI

Model: CFMI-TP-SM.9 CFM56-5B

Part Number: 338-068-411-0

Serial No: N/A

Name of Part: PANEL, ASSY-ACOUSTICAL AFT

Repair Order No: ERO17462

Work Order No: 85587 ESN 779481

Quantity: 1

Customer: AJ Walter Aviation Ltd

Cause Rejected: REJECTED DUE TO REPAIR
10 OUTSIDE OF BPAERO
CAPABILITIES NOT
SERVICEABLE NOT
REPAIRABLE.

Inspectors Signature

Inspector No:



BPA-50