

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES	2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	3. Form Tracking Number: 334798-20			
4. Organization Name and Address: Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300		5. Work Order/Contract/Invoice Number: 334798 / U16895			
6.Item:	7. Description:	8. Part Number:	9. Quantity:	10.Serial Number:	11.Status/Work:
1	TWIN CABLE ACCELEROMETER	144-171-000-031	1	AC40706	TESTED
12.Remarks:TESTED AND INSPECTED IAW CMM ATA 77-32-15 REV: 06 DATE: 01/28/2016					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA part 145 and, with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number: EASA 145.5893					
14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.					
14b. Authorized Signature: 			14c. Approval/Certificate No.: GPYR474X		
14d. Name: (Typed or Printed) Randy Jaskowski			14e. Date (dd/mm/yyyy): 17 NOV 2020		
User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1. Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with national regulations by the user/installer before the aircraft may be flown.					
FAA Form 8130-3 (02-14) FAA authorized authority per Op Specs A025 for electronic signatures IAW AC 120-78. NSN: 0052-00-012-9005					

1. 国家 CHINA		2. 中国民用航空总局 CAAC ☐ 符合性 Conformity ☒ 适航性 Airworthiness		3. 证书编号 Certificate Ref. No. 334798-20	
AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG 授权发布证书/航空认证标签					
4. 单位 Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300		5. 工作单/合同单/货单 Work Order/Contract/Invoice Number: 334798 / U16895			
6. 序号 Item:	7. 内容 Description:	8. 件号 Part Number:	9. 适用性 Eligibility:*	10. 数量 Quantity:	11. 系列号/批号 Serial/Batch Number:
1	TWIN CABLE ACCELEROMETER	144-171-000-031	NOT KNOWN	1	AC40706
12. 产品状态 Status/Work: TESTED					
13. 备注 TESTED AND INSPECTED IAW CMM ATA 77-32-15 REV: 06 DATE: 01/28/2016 Remarks:					
15. 使用过的产品 Used Parts 兹声明上述产品除第 13 项的其它规定以外, 已按照上述国家适航条例和特殊要求进行了工作, 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in Block 13, the work was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the parts(s) is (are) in condition of safe operation and considered ready for release to service. (over)					
16. 批准人 Signature:		19. 中国民航总局授权 Issued by or on behalf of the CAAC F00100391			
17. 批准人姓名 (打印的) Name (Printed)		18. 批准日期 Date			
Randy Jaskolowski		17 Nov, 2020			

AAC-038(12/94)

*参阅产品目录详细查找

*Cross-check eligibility for more details with parts catalogue

WORK ORDER FORM 100

Page No. 1



Work Order: 334798-20

Triumph Accessory Services -Grand Prairie

1038 Santerre Drive

Grand Prairie, TX 75050-1937

972/623-9300 FAX (972) 660-1580

FAA CRS No: GPYR474X

CAAC CRS No: F00100391

Customer: 012424 / AJ WALTER AVIATION LTD

Dept#: EL3

Cust RO#: U16895

Step: SHOP COMPLETE

Warranty Code: NW Qty: 1

Work Req: TEST

P/N: 144-171-000-031 / TWIN CABLE

S/N: AC40706

Mfg: VIBROM

Manual#: 9991

RevDate: 01/28/2016 Rev#: 06

ATA: 77-32-15

TEST UNDER T&M

***** COMPLY WITH CUSTOMER P.O. REQUIREMENTS *****

Date Recvd: 11/12/2020 Date Reqr: / / Date Estmtd: / /

PRELIMINARY INSPECTION: DATE: 11/12/2020

TECH: Leonardo Saldivar (esign)

NO VISIBLE ISSUES NOTED PRIOR TO CLEANING

NO A.D.'S

TEARDOWN FINDINGS:

CLEANED, INSPECTED AND BENCH CHECKED

IAW ATA 77-32-15 REV.5 DTD 1/28/2016

TECHNICIAN: Cheyenne Hargon (esign) DATE: 11/17/2020

CORRECTIVE ACTION:

CLEANED, INSPECTED AND BENCH CHECKED

IAW ATA 77-32-15 REV.5 DTD 1/28/2016

* TESTED AND INSPECTED IAW CMM ATA 77-32-15 REV: 06 DATE: 01/28/2016

TECHNICIAN: Cheyenne Hargon (esign) DATE: 11/17/2020

Test Technician: Cheyenne Hargon (esign)

DATE: 11/17/2020

Supervisor: Dwane Slusher (esign)

DATE: 11/17/2020

Final Inspection: Randy Jaskolowski (esign)

DATE: 11/17/2020

