

Inflite MRO Services Ltd
North Hangar
Aviation Way
Southend-on-Sea
Essex
SS2 6UN
United Kingdom
Tel: +44(0)1702 348601

WAS (COMPONENTS) LTD: EASA Part 145: UK.145.00579:

WAS (COMPONENTS) LTD: FAA Repair Station: EGWY725K:

Workshop Report

No: **IR56040**

Issue: 01

Date: 21-Sep-17

A J Walter (Aviation) Limited The Headquarters Maydwell Avenue Slinfold

West Sussex RH13 0SH United Kingdom

Attn: Ms Georgina May

Tel: 01403 711777

Fax: 01403 712135

E-Mail: Georgina.may@ajw-aviation.com

Your Ref: W40528 Our Ref No: WP55570 Test Required: N/A

Part No: 416-1001-23

Description: COFFEE MAKER

Serial No: 2276

Workscope: Repair

Dept: Electrical Workshop

Release Type: Dual

Removed From:

Serial No:

Reg No:

Position:

Workscope Overview:

PLEASE REPAIR UNDER WARRANTY DEFECT - BREW FUNCTION INOP

REF WP51360

Inspection Findings:

PLEASE REPAIR UNDER WARRANTY. DEFECT - BREW FUNCTION INOP.

PLEASE NOTE, UNIT RECEIVED WITHOUT A BREW CUP.

UNIT TESTED, UNIT PASSED TEST (NO FAULT FOUND). UNIT TO BE GIVEN A PRECAUTIONARY DE-SCALE.

UNIT DISASSEMBLED AS REQUIRED, CLEANED AND INSPECTED.

UNIT TO BE DE-SCALED AND FLUSHED. FIT NEW BREW CUP AND TEST UNIT

WARRANTY DENIED, NO FAULT FOUND.

UNIT TO BE RELEASED :-

REPAIRED AND TESTED IAW B E AEROSPACE 25-30-31 REV 4, DATED MAY 2015.

Signed:

For and on the behalf of Infifte MRO Services Ltd

Registered address:- Inflite House, Stansted Airport, Stansted, Essex, CM24 1RY