

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number G8334	
4. Organization Name and Address: Velocity Aerospace - Burbank, Inc. 2840 N. Ontario Street Burbank, CA 91504 Ph: 818-333-5600,				5. Work Order/Contract/Invoice Number: R385944	
Repair Station Cert. # RB1R197K					
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	LIGHTING ATTENDANT	285A1710-1	1	D06431	REPAIRED
12. Remarks: All work has been accomplished in accordance with FAA approved data: CMM: 33-11-05 Rev: 14 Dated: 12/5/2017					
Certified that the work specified in block 11/12 was carried out in accordance with EASA PART 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 approval no. EASA.145.4002. For complete details of work accomplished reference tracking number in block (3) three or as attached.					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12			14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature:		13c. Approval Authorization No.:		14b. Authorized Signature: <i>For Ramon Flores</i>	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14c. Approval/Certificate No.: RB1R197K	
				14d. Name (Typed or Printed): Jose Ramon Flores	
				14e. Date (dd/mm/yyyy): 19/Oct/2021	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

**Velocity Aerospace - Burbank, Inc.**

2840 N. Ontario Street
Burbank, CA 91504
Ph: 818-333-5600,

Repair Station: RB1R197K FAA/EASA.145.4002

RECAP**Work Order #: G8334**

Date Printed: 10/19/2021

Time: 12:03:12 PM

Page: 1

To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVE, SLINFOLD
WEST SUSSEX RH13 0AS UK
payableinvoices@ajw-group.com, UNITED
KINGDOM

Ship To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVENUE, SLINFOLD
WEST SUSSEX, RH13 0AS
UNITED KINGDOM

Ref #: R385944

Phone #: 441403711414

Fax #:

Email: chris.copestake@ajw-aviation.com

Mfg: BAE SYSTEMS

Serial #: D06431

PN: 285A1710-1

Descr: LIGHTING ATTENDANT

ATA Chapter: 33-11-05

Revision #: 14

Revision Date: 12/5/2017

Test Record: 2784

Technician: JSANDERS

Type:

Entry Date: 8/25/2021

Need Date: 10/15/2021

Compl. Date: 10/19/2021 12:02:55 F

Container:

Warranty: No

Symptoms:

WORKSCOPE: RP

REASON FOR REMOVAL

FAULTY

Faults:

COMPLAINT VERIFIED

PRELIM TEST & EXAM

Unit fails S4 ground service indicator ON test and fails S5 work indicator ON test.

TEARDOWN INSPECTION

S4 and S5 lamps burned, faceplate finish peeling,

Corrective Actions:

FINAL DISPOSITION: RP

FINAL WORK ACCOMPLISHED

Cleaned, refinished faceplate, replaced burned lamps, reassembled, functionally tested.

TEST EQUIPMENT:

ABI1073

Parts

PN

Description

Qty Issued CD

85

LAMP BURN

2

NE

Final Inspector Signature: Jose Ramon Flores Certificate number: 4372619

**Velocity Aerospace - Burbank, Inc.**

2840 N. Ontario Street
Burbank, CA 91504
Ph: 818-333-5600,

Repair Station: RB1R197K FAA/EASA.145.4002

RECAP**Work Order #: G8334**

Date Printed: 10/19/2021

Time: 12:03:12 PM

Page: 1

To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVE, SLINFOLD
WEST SUSSEX RH13 0AS UK
payableinvoices@ajw-group.com, UNITED
KINGDOM

Ship To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVENUE, SLINFOLD
WEST SUSSEX, RH13 0AS
UNITED KINGDOM

Ref #: R385944

Phone #: 441403711414

Fax #:

Email: chris.copestake@ajw-aviation.com

Mfg: BAE SYSTEMS

Serial #: D06431

PN: 285A1710-1

Descr: LIGHTING ATTENDANT

ATA Chapter: 33-11-05

Revision #: 14

Revision Date: 12/5/2017

Test Record: 2784

Technician: JSANDERS

Type:

Entry Date: 8/25/2021

Need Date: 10/15/2021

Compl. Date: 10/19/2021 12:02:55 F

Container:

Warranty: No

Symptoms:

WORKSCOPE: RP

REASON FOR REMOVAL

FAULTY

Faults:

COMPLAINT VERIFIED

PRELIM TEST & EXAM

Unit fails S4 ground service indicator ON test and fails S5 work indicator ON test.

TEARDOWN INSPECTION

S4 and S5 lamps burned, faceplate finish peeling,

Corrective Actions:

FINAL DISPOSITION: RP

FINAL WORK ACCOMPLISHED

Cleaned, refinished faceplate, replaced burned lamps, reassembled, functionally tested.

TEST EQUIPMENT:

ABI1073

Parts

PN

Description

Qty Issued CD

85

LAMP BURN

2

NE

Final Inspector Signature: Jose Ramon Flores Certificate number: 4372619

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number G8334	
4. Organization Name and Address: Velocity Aerospace - Burbank, Inc. 2840 N. Ontario Street Burbank, CA 91504 Ph: 818-333-5600,		5. Work Order/Contract/Invoice Number: R385944			
Repair Station Cert. # RB1R197K					
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	LIGHTING ATTENDANT	285A1710-1	1	D06431	REPAIRED
12. Remarks: All work has been accomplished in accordance with FAA approved data: CMM: 33-11-05 Rev: 14 Dated: 12/5/2017					
Certified that the work specified in block 11/12 was carried out in accordance with EASA PART 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 approval no. EASA.145.4002. For complete details of work accomplished reference tracking number in block (3) three or as attached.					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		13c. Approval Authorization No.:		14c. Approval/Certificate No.: RB1R197K	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy): 19/Oct/2021	
		Jose Ramon Flores			
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					