

WORK ORDER

Work Order :103021
Part Number :160100-113
Serial Number :027
ATA Number :27-41-05
Service Req. :Repair

Repair Order :RPTM-163992
Description :Stabilizer Module
Manufacturer :Moog Aircraft Gro
Revision Date :09/14/11
Date :10/18/11

FAA REPAIR STATION LZ4R354M

CONDITION REPORTED - CONFIRMATION N/A

Eicas stab trim-R primary channel confirmed.

CONDITION AS RECEIVED

VISUAL INSPECTION APPEARS NORMAL

HIDDEN DAMAGE INSPECTION

REMARKS

NONE

Receiving Clerk: Giovanni Acosta DATE: 10/18/2011

AD NOTES, Customer Specs

THERE ARE NO A.D. NOTES FOR THIS UNIT

Signature: _____



DATE: _____

10/18/2011

FORM MC10-1

REV 16

WORK ORDER

Work Order :103021
Part Number :160100-113
Serial Number :027
ATA Number :27-41-05
Service Req. :Repair

Repair Order :RPTM-163992
Description :Stabilizer Module
Manufacturer :Moog Aircraft Gro
Revision Date :09/14/11
Date :10/18/11

FAA REPAIR STATION LZ4R354M

TEARDOWN REPORT

*Pretest

Upon pretest found:

1. Nose up control valve solenoid coil has low resistance.

*Disassembly

Upon partial disassembly and inspection, the following discrepancies were found:

1. Solenoid requires replacement due to failure.
2. Seal cup and gasket plate are worn.
3. Unit will be repaired per customer request.

TECHNICIAN: Luis M Rodriguez SUPERVISOR: _____



WORK ORDER

Work Order :103021
Part Number :160100-113
Serial Number :027
ATA Number :27-41-05
Service Req. :Repair

Repair Order :RPTM-163992
Description :Stabilizer Module
Manufacturer :Moog Aircraft Gro
Revision Date :09/14/11
Date :10/18/11

FAA REPAIR STATION LZ4R354M

CORRECTIVE ACTION

1. All worn and damaged parts were replaced.
2. Unit was assembled in accordance with the manufacturer's specifications.
3. Unit passed all functional tests.

Unit repaired and certified for return to service.

Tech : Michael O'Hara Spvsr : DR Date : 04/18/12

SERVICE PERFORMED

Repaired

MAINTENANCE RELEASE

Issued with respect to job performed as checked above.
The component identified above was inspected in accordance with current regulations of the F.A.A. and is approved for return to service. Pertinent details of the repair are on file at this agency under

W.O.# 103021 Date APR 19 2012 Signed 7

WORK ORDER

Work Order :103021
Part Number :160100-113
Serial Number :027
ATA Number :27-41-05
Service Req. :Repair

Repair Order :RPTM-163992
Description :Stabilizer Module
Manufacturer :Moog Aircraft Gro
Revision Date :09/14/11
Date :10/18/11

FAA REPAIR STATION LZ4R354M

Removed Components

<u>Part Number</u>	<u>Serial Number</u>
65400	1528
65400	1541
65400	1507
65400	1537
90G97	6970H
65860	97

Installed Components

<u>Part Number</u>	<u>Serial Number</u>
65400	1854
65400	1507
65400	1537
65400	1541
90G97	6970H
65860	97

TECHNICIAN: Luis M Rodriguez DATE: 11/07/11