

1. Approving Competent Authority / Country
CAA The Netherlands

2.

AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

3. Form Tracking Number
37898217 - 01

4. Organisation Name and Address:

KONINKLIJKE FABRIEK INVENTUM B.V.
DOING BUSINESS AS
B/E AEROSPACE

GALVANIBAAN 5
3439 MG NIEUWEGEIN
THE NETHERLANDS

TEL.: +31 (0) 3060292200
FAX: +31 (0) 306036949
TRADE REGISTER NO. 30001132

5. Work Order/Contract/Invoice

37898217 SR

R261714

6. Item

7. Description

1.0

DF1075 High speed oven LH

8. Part No.

72073750

9. Qty

1

10. Serial No.

0214

11. Status/Work

MODIFIED

12. Remarks

Work performed in accordance with CMM: 25-35-11 Revision: 09
Controller with P/N: 611515 and S/N: 0878
Shop finding report ref.:37898217
Modification standard out:1 upto 4 and 7
Performed: SB_OCM1000-25-0002
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no: ZRYY936X

13a. Certifies that the items identified above were manufactured in conformity to:

☐ approved design data and are in condition for safe operation

☐ non-approved design data specified in block 12

13b. Authorised Signature

13c. Approval/Authorisation Number

13d. Name

13e. Date (dd mmm yyyy)

14d. Name

14b. Authorised Signature

B/E AEROSPACE
QC 010

14c. Certificate/Approval Ref. No.

NL.145.1150

14e. Date (dd mmm yyyy)

08 May 2015

USER/INSTALLER RESPONSIBILITIES The certificate does not automatically constitute authority to install the item(s). Where the user/installer performs works in accordance with the regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his / her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

N.P. HOANG



Passion to Innovate.
Power to Deliver.

SHOPFINDING REPORT

Order details	
REPAIR ORDER: 37898217	CUSTOMER: A J WALTER AVIATION LTD
WORK ORDER: 6918809	RECEIVING DATE: 22/Apr/2015
PURCHASE ORDER: R261714	

Repair details	
REMOVAL REASON: U/S works on ground but not in air.	FAILURE VERIFIED: Yes
FAILURE REASON: Keyboard (conformal coated) - Defective - Inoperative Key(s)	
INCOMING ITEM P/N: 72073750 S/N: 0214	MODIFICATION STANDARD Mod. in: 1 upto 4 and 7 Mod. out: 1 upto 4 and 7
INCOMING SUB-ITEM Sub P/N: 611515 Sub S/N: 0878 Manufacturing Date: 10/Jul/2000	REPAIRED AND TESTED IN ACCORDANCE WITH CMM: 25-35-11 Revision: 09
OUTGOING ITEM P/N: 72073750 S/N: 0214	SUSPECTED UNAPPROVED PARTS SUPS: No
OUTGOING SUB-ITEM Sub P/N: 611515 Sub S/N: 0878 Software Setting: CS-820-43	

Shop findings			
QTY	PART NUMBER	DESCRIPTION	DISCREPANCY / REASON / ACTION
4.00	239480	Stud	Bad Condition / Corrosion / Replaced
1.00	239694	Display protection plate	Bad Condition / Comes off / Replaced
0.00	438001011	Keyboard (conformal coated)	Defective / Inoperative Key(s) / For information only
1.00	439001210	Modification kit Keyboard	Modification / As part of a Service Bulletin / Placed
1.00	439009222	Maintenance kit D-check DF1000	Recommended / 36-42 Months or 10000-12000 Flight Hours / Replaced
1.00	611287	Nut set for safety device	Bad Condition / Corrosion / Replaced
0.00	611318	Bonding strip	Bad Condition / Contaminated / Cleaned
1.00	611561	Heating element 200V-3600W	Insulation faulty / Insulation resistance too low / Replaced
0.00	611629	Door plate	Bad Condition / Loose Component / Repaired
4.00	CS-641-03	O-ring	Required / Reassemble Action / Replaced

Modifications	
MODIFICATION	REASON
INCOMING ITEM:	STATUS

Form	Department	Email	Shopfinding report approved by		Page
PR-262-DOC-001_10	Repair station	repair_nieuwegein@beaerospace.com	Date: 08 MEI 2015	Signature: N.P. HOANG	Q.C. Dept: B/E AEROSPACE
					1 of 2
					QC 010



Passion to Innovate.
Power to Deliver.

SHOPFINDING REPORT

Order details	
REPAIR ORDER: 37898217 WORK ORDER: 6918809	CUSTOMER: A J WALTER AVIATION LTD PURCHASE ORDER: R261714
RECEIVING DATE: 22/Apr/2015	

Modifications	
MODIFICATION INCOMING SUB ITEM: SB_OCM1000-25-0002 - Introduction of a new keyboard and placard	REASON Repair automatically includes this SB
STATUS Implemented	

Remarks

Form	Department	Email	Shopfinding report approved by		Page
PR-262-DOC-001_10	Repair station	repair_nieuwegein@beaerospace.com	Date: 08 MEI 2015	Name: N.P. HOANG Signature:	Q.C. Dept: B/E AEROSPACE QC-010 2 of 2