

1. Approving Civil Aviation Authority / Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: RD 7009015	
4. Organization Name and Address: LIEBHERR-AEROSPACE SALINE, INC 1465 Woodland Drive Saline MI 48176 USA			5. Work Order/Contract/Invoice Number: L3RR193H RD 7009015		
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	Reheater	755D0000-01	1	81210-50234	OVERHAULED
12. Remarks TSN: TSO: 0 CSN: CSO: 0 Amendment: Refer to: Shop Finding Report RD 7009015 Approved data: CMM 21-54-17 Rev 2 dated 08 NOV 2019 Comments: Return to service: Work specified accomplished IAW 14CFR Part 43.13(a)(b) and/or (c)/AC 43.18 if local fabricated parts were used. Remark: AJW RO: R382600 RECORE Dual Release: Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work, the aircraft component is considered ready for release to service under EASA Part-145 Approval Number EASA.145.5439. Modification: SB 755-21-01 Rev 2 dated 16 DEC 2016 Limited life parts must be accompanied by maintenance history including total time / total cycle / time since new.					
13a Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation ☐ Non-approved design data specified in Block 12					
13b. Authorized Signature:		13c. Approval/Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14b. Authorized Signature: L3RR193H	
THOMAS JIMENEZ				14c. Approval/Certificate No.: L3RR193H	
14d. Name (Typed or Printed):		14e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy): 09 JUN 2021	
THOMAS JIMENEZ					
User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1 国家 Country 中国/REPUBLIC OF CHINA	2 中国民用航空总局 CAAC 批准放行证书/适航批准标签 符合性 Conformity ☒ 适航性 Airworthiness	3 证书编号 Certificate Ref. N°. 2021-03246
AUTHORIZED RELEASE CERTIFICATE / AIRWORTHINESS APPROVAL TAG		
4 单位 Organization: LIEBHERR-AEROSPACE SALINE, INC 1465 Woodland Drive Saline MI 48176 USA	5 工作单/合同单/货单 Work Order/Contract/Invoice RD 7009015	
6 序号 Item	7 内容 Description	8 件号 Part N°.
1	Reheater	755D00000-01
	9 适用性 Eligibility	10 数量 Qty
	Not Known	1
	11 系列号/批号 Serial/Batch N°.	12 产品状态 Status/Work
	81210-50234	OVERHAULED
13 备注 Remarks TSN: TSO: 0 CSN: 0		
Approved data: CMM 21-54-17 Rev 2 dated 08 NOV 2019 Modification: SB 755-21-01 Rev 2 dated 16 DEC 2016 Investigation Report 7009015 Remark: AJW RO: R382600 RECORE		
14 新产品 New Parts 兹声明上述产品除第13项的其它规定以外, 已按照上述国家适航条例进行制造/检查, 并且该 产品(出口产品)符合经批准的型号设计资料, 且符合进口国提出的专用要求。 Certifies that the Part(s) identified above except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.		
15 使用过的产品 Used Parts 兹声明上述产品除第13项的其它规定以外, 已按照上述国家适航条例和进口国通知的特殊要 求进行了工作, 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)		
16 批准人签名 Signature	18 批准日期 Date 09 JUN 2021	
17 批准人姓名(打印的) Name(Printed) THOMAS JIMENEZ		
19 中国民航总局授权 Issued by or on behalf of the CAAC F00100650		

SHOP FINDING REPORT

LIEBHERR REPAIR DOSSIER:	7009015	CONTACT:	Joshua Smith
RECEPTION DATE:	29 APR 2021	EMAIL:	joshua.smith@liebherr.com
CUSTOMER:	AJ Walter Aviation LTD	DATE:	09 JUNE 2021
CUSTOMER PURCHASE ORDER:	R382600		
AIRCRAFT TYPE:	A320		
AIRCRAFT REG. NUMBER:	EC-LVO		

RECEIVED UNIT

CUSTOMER REFERENCE: 755C0000-01
PART NUMBER: 755C0000-01
AMENDMENT: -
SERIAL NUMBER: 81210-50234
DESCRIPTION: Reheater
MANUFACTURING CODE: F1958
MANUFACTURING DATE: 012004

DELIVERED UNIT

CUSTOMER REFERENCE: 755D0000-01
PART NUMBER: 755D0000-01
AMENDMENT: -
SERIAL NUMBER: 81210-50234
DESCRIPTION: Reheater

TIMES & CYCLES

TSN	TSO	TSI	CSN	CSO	CSI
N/A	N/A	N/A	N/A	N/A	N/A

INSTALLATION DATE:	N/A	REMOVAL DATE:	N/A
LOG CARD EXISTS:	No	NON INCIDENT STATEM.:	No
LIFE LIMITED PARTS:	No		

APPROVED DATA: CMM 21-54-17 / REVISION 2 / 11/8/2019

MODIFICATION DOCUMENTS: SB 755-21-01 / REVISION 2 / 12/16/2016

WORK REQUESTED:	Overhaul	WORK PERFORMED:	Recore
WARRANTY REQUESTED:	No	WARRANTY DECISION:	Out of warranty

REASON FOR RETURN

Scheduled
Mod to P/N 755D0000-01
Please Overhaul under FIXED PRICE

FINDINGS AND ANALYSIS

Findings from Analysis:

- Recoring - Customer request modification to P/N 755D0000-01, requires recore.

WORK PERFORMED

- Recoring

LIFE LIMITED PARTS

N/A

SHOP FINDING REPORT APPROVED

VALIDATION DATE: 08 JUNE 2021
VALIDATED BY: Ian Shaw