

1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking Number. WO26811	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number. R275484-1	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	Handset	ST3100-21-10	1.00	352	REPAIRED
12. REMARKS The unit is repaired and tested serviceable in accordance with CMM 23-40-01, Rev 05, dated Dec 20, 2006. For detail information, please refer to Tear Down / Inspection Report.					
PRINTED FROM ELECTRONIC FILE EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17					
14a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14b. Signature 		14c. Approval Organization Number 33-12	
13b. Signature:		13c. Approved Organization Number		14d. Name (Typed or Printed) Gangjie Cui	
13d. Name (Typed or Printed):		13e. Date		14e. Date (dd/mm/yyyy) 20/Oct/2015	
Installer Responsibilities					
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					

Work Order #: WO26811

Date Printed: 20/10/2015

Customer RO: R275484-1

Page: 2

REPAIR		YES
REWORK	NO	
TIME CONTROLLED/TX		NO
RE-QUOTE:		NO

CODE: INITIAL TEST FAILURE

DETAILS: Mic audio level is low, out of specification.

CODE: CLEANING

DETAILS: Cleaning is required due to dirty.

CODE: OUT OF CALIBRATION

DETAILS: Calibration on mic audio level is performed as per CMM.

CODE: REPAIR

DETAILS: perform calibration on mic audio level per CMM and clean unit.

Corrective Actions:

CODE: REPAIRED

DETAILS: Perform calibration on mic audio level per CMM and clean unit. Unit is certified serviceable.

Work Order #: WO26811

Date Printed: 20/10/2015

Customer RO: R275484-1

Page: 1

To:
A J WALTER AVIATION LIMITED
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Phone #:

Code: AJW01

Descr: Handset

Fax #:

PN: ST3100-21-10

Serial # : 352

Email:

Qty: 1

Mfg: BECKER AVIONICS

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

CSO: N/A

CSR: N/A

P/N Out: ST3100-21-10

Serial # out: 352

Symptoms:

CODE: TEST AND RECERTIFY

DETAILS:

Faults:

CODE: QUOTE

DETAILS: PRELIMINARY INSPECTION (VISUAL):

PART MISSING: NO
DAMAGE FOUND (CID): NO
HRS/CYCLE RECEIVED: NO

ADDITIONAL REQUIREMENT:

AD, SB, MOD, SIL NO
ADD.CUST. REQUEST NO

WARRANTY REQUESTED? NO

TEST ARRIVAL:

INITIAL TEST FAIL? YES

REASON FOR REMOVAL CONFIRMED: YES

DISASSEMBLY/INSPECTION:

ANY ANOMALIES FOUND DURING DISASSEMBLY/INSPECTION NO

WORK TYPE: REPAIR

WORKSCOPE:

CALIBRATION YES
CLEANING YES
OUT OF SCOPE NO
OVERHAUL NO
PAINTING NO
PCBR NO