It is import Where the a it is essentia	13d. Name (	13b. Authori	Non-app	13a. Certifie.	"AIR TRANS	12. Remarks:		o. Item:		4. Organizati	1. Approving Authority/
ant to understand that the user/installer performs wo al that the user/installer er	13d. Name (Typed or Printed):	13b. Authorized Signature:	Non approved design data specified in Block 12	13a. Certifies the items identified above were manufactured in conformity to	SPORT COMPONENTS CE	: OVERHAULED UNIT IA TSO:00.00, CSO:00.00.	ASSY	MODI II AB		4. Organization Name and Address:	1. Approving Civil Aviation Authority/Country: FAA/United States
existence of this docur rk in accordance with the sures that his/her airwo	13e. D	13c. A	ed in Block 12	ve were manufactured	RTIFIES THAT THE WO	TAW BOEING CMI			Сотрон	Air Lyan	2.
User/Installer Responsibilities  It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.  Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1.  It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1.	13e. Date (dd/mmm/yyyy):	Approval/Authorization No:		in conformity to:	"AIR TRANSPORT COMPONENTS CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH PART-145 AND IN RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA APPROVAL CERTIFICATE NO: EASA.145.5116."	OVERHAULED UNIT IAW BOEING CMM 32-09-11, REV #19 DATED NOV 01/15. TSO:00.00, CSO:00.00.	0.00	8. Part Number:	1000	900 N. Fiesta Blvd Gilbert, AZ 85233	AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL
User/Installer Responsibilities y constitute authority to install the a orthiness authority different than th ft engine(s)/propeller(s)/article(s) fron	JASON CHEVALIER	14b. Authoriked Signature:	Block 12 was respect to that	14a. <b>X</b> 14 CFF	S CARRIED OUT IN ACCO	NOV 01/15.			480-831-1268 FAX 480-831-1314	Blvd. 233	AUTHORIZED RELEASE CERTIFICATE Form 8130-3, AIRWORTHINESS APPROVAL
ties  the aircraft engine/pi  the airworthiness of	valier	<del>l Signa</del> ture:	accomplished in acc	14 CFR 43.9 Return to Service	ORDANCE WITH PAI			9. Quantity:		Z6AR209Y	ROVAL TAG
ropeller/article. authority of the country ss authority of the coun	14e. 15	14c. <b>Z</b> (	ras accomplished in accordance with Title 14, Code of Finance, the items are approved for return to service.	rvice	RT-145 AND IN RESPEC		394*	10. Serial Number:		09Y	
/ specified in Block 1, ntry specified in block 1.	14e. Date (dd/mmm/yyyy): 15/AUG/2017	14c. Approval/Certificate No: Z6AR209Y	Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	4a. X14 CFR 43.9 Return to Service  X0ther regulation specified in Block 12  Block 12  Block 12	СТ ТО ТНАТ			11. Status/Work:		5. Work Order/Contract/Invoice Number: W0102734	3. Form Tracking Number: A50011957-2



900 N. Fiesta Blvd. Gilbert, AZ 85233 Ph: 480-831-1268 FAA Repair Station # Z6AR209Y Fx: 480-831-1314

## COMPONENT TEARDOWN/CONDITION REPORT

Customer 10176 AN Nomenclature MODULA Part Number 65-446	R ASSY	MFG BOEIN	NG 5944	CUST-PO# A5	DER# W0102734 0011957-2 ING 737-SERIES
Reason For Removal/ OVERHAUL AS REQUI DUAL RELEASE REQU	RED IAW MFG SP	ructions M PECS.	Modification	s/S.B/A.D C	ompliance
Visual Inspection P UNIT DIRTY. PAINT	Prior To Teardo CHIPPED / WOR	own:			
Preliminary Test Re TESTED IAW CURREN ALL TESTS PASSED.	T OEM/MFG SPEC	es.			
Teardown And Inspect SEALS WORN,O-RING PERFORMED NDT INS	S WORN, RETAINE	RS WORN, RIN	NGS WORN, REF	INISH REQUI	RED.
Corrective Action TO OVERHAULED UNIT IN TSO:00.00, CSO:00	AW BOEING CMM	32-09-11, F	REV #19 DATE	D NOV 01/15	
Final Disposition:	OVERHAULED				
<u>.</u>					
TECH JT JOE TREMON		SPECTOR JC	JASON CHEVA	LIER DA	TE <u>AUG/15/2017</u>
For further info co	ontact Roy F	Tyde	at 480-83	1-1268 FAX	480-831-1314
					ATC009



900 N. Fiesta Blvd. Gilbert, AZ 85233 Ph: 480-831-1268 FAA Repair Station # Z6AR209Y Fx: 480-831-1314

## COMPONENT TEARDOWN/CONDITION REPORT

mencla	10176 ture MODU	JLAR AS		MFG BOEING	WORK C CUST-PO# A	ORDER# W010273 450011957-2
		***	* PARTS	REPLACEMENT	RECORD ****	Page 1 of 1
QTY	Item #		Part	Number	Nomenclature	
8 4 8 4 4 2 4 2 2 2	2 3 6,10 7,11 8,12 11 14 14 15 13		MS28 NAS1 MS28 NAS1 NAS1 MS28 NAS1 MS28 MS21 NAS1	782-19 611-214 782-13 611-115 612-12 782-6 612-4 782-2 318-7 611-007	RING PACKING BACKUP PACKING PACKING RING PACKING RETAINER SCREW PACKING PACKING	
						ATC00