


1. Approving Civil Aviation Authority/Country <b>Transport Canada</b>	2.	<b>AUTHORIZED RELEASE CERTIFICATE FORM ONE</b>		3. Form Tracking Number. <b>WO86140</b>
--	----	--	--	--

4. Organization Name and Address.  
**AJW Technique Inc**  
7055, rue Alexander Fleming  
Saint-Laurent QC H4S-2B7  
Canada



5. Work Order, Contract or Invoice Number:  
**R363460-1**

6. Item: 7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1. CONTROLLER-ZONE TEMPERATURE	978B0000-02	1.00	978B00L0000662	INSPECTED/TESTED

12. REMARKS  
UNIT INSPECTED/ TESTED IN ACCORDANCE WITH CMM 21-63-45 REV. 5 DATED 01SEP2012.  
SEE Tear Down/Inspection Report FOR ADDITIONAL INFO.

PRINTED FROM ELECTRONIC FILE

13a. Certifies the items identified above were manufactured in conformity to: EASA Approval No.: EASA.145.7260  
Maintenance performed in accordance with FAR 43.17

- ☐ Approved design data and are in a condition for safe operation.  
☐ Non-approved design data specified in Block 12
- 14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

- ☒ CAR 571.10 Maintenance Release  
☒ Other regulation specified in Block 12

13b. Signature:	13c. Approved Organization Number	14b. Signature <i>Daniel Hebert</i>	14c. Approval Organization Number <b>33-12</b>
13d. Name (Typed or Printed):	13e. Date	14d. Name (Typed or Printed) Daniel Hebert	14e. Date (dd/mm/yyyy) 21/Aug/2019

This certificate does not constitute authority to install the part.  
Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.  
Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

Work Order: WO86140

Date Printed: 8/21/2019

Customer RO: R363460-1

Page: 1

**To:**

A J Walter Aviation Ltd.  
THE HEADQUARTERS  
MAYDWELL AVENUE  
SLINFOLD, WEST SUSSEX RH13 0AS  
UNITED KINGDOM

Code: AJW01

Fax:

Descr: CONTROLLER-ZONE TEMPERATURE

Phone:

P/N: 978B0000-02

Qty: 1

Email:

S/N: 978B00LI000662

Mfg: LIEBHERR TOULOUSE

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

CSO: N/A

CSR: N/A

P/N Out: 978B0000-02

Serial Out: 978B00LI000662

**Symptoms:**

CODE: REASON FOR REMOVAL

DETAILS: IN CMS CLASS 2 zone controller at fault every flight ZC (630HK) temp sensor CAB area 6.

**Faults:**

CODE: CUSTOMER REASON FOR REMOVAL CONFIRMATION

DETAILS: Reason for removal is not confirmed.

CODE: TEST ONLY

DETAILS: Unit tested and no fault was found, cannot duplicate the fault  
Unit consider serviceable.  
Inspection revealed no anomalies.

**Corrective Actions:**

CODE: INSPECTED/ TESTED

DETAILS: A visual inspection was done on the unit.  
Test performed per CMM 21-63-45 rev. 5 dated 1SEP2012.