


1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking Number. WO150542	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number: T42501	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	HF Antenna Coupler	792-6140-001	1.00	8061	INSPECTED/TESTED
12. REMARKS Unit tested serviceable in accordance with CMM 23-11-04 1st Revision dated Nov 13 2015. See tear down report for additional information.					
PRINTED FROM ELECTRONIC FILE					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12			
13b. Signature:		13c. Approved Organization Number		14b. Signature 	
13d. Name (Typed or Printed):		13e. Date		14c. Approval Organization Number 33-12	
				14d. Name (Typed or Printed) Hon Tak Chan	
				14e. Date (dd/mm/yyyy) 29/Nov/2023	
Installer Responsibilities					
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					

AJW TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada
www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO150542

Date Printed: 11/29/2023

Customer RO: T42501

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: HF Antenna Coupler

Phone:

P/N: 792-6140-001

Qty: 1

Email:

S/N: 8061

Mfg: ROCKWELL COLLINS

TSN: 0

TSO: N/A

TSR: 0

CSN: 0

CSO: N/A

CSR: 0

P/N Out: 792-6140-001

S/N Out: 8061

Symptoms:

CODE: REPAIR

DETAILS: PLEASE QUOTE TO TEST AND RECERTIFY. PLEASE TO REPAIR IF IT FAILS TEST.
REMOVED IN SERVICEABLE CONDITION FROM A/C REG: G-MLJL.

Faults:

CODE: INITIAL TEST FAILURE

DETAILS: Unit passed arrival test with NFF.

CODE: CLEANING

DETAILS: General cleaning to be performed.

CODE: TEST AND RECERTIFY

DETAILS: Unit to be tested and re-certified.

Corrective Actions:

CODE: INSPECTED/ TESTED

DETAILS: Performed general cleaning on unit.

Unit tested serviceable in accordance with CMM 23-11-04 1st Revision dated Nov 13 2015.