



1. Approving Competent Authority/Country: CAA UK		2. AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. Form Tracking Number: 0000000000008549103		Page 1 of 1	
4. Organisation Name and Address: Goodrich Actuation Systems Stafford Rd, Fordhouses Wolverhampton, West Midlands, WV10 7EH, England				5. Work Order/Contract/Invoice: 44296187 T34325			
6. Item:	7. Description:	8. Part No.:	9. Qty:	10. Serial No.	11. Status/Work:		
01	ROT VARIABLE TRANSFORMER	TY1931-20A	1	1200	REPAIRED		
12. Remarks: Purpose: Approval for Return to Service RETURNED FOLLOWING REPAIR AND TEST IN ACCORDANCE WITH ACMM 78-30-35 INITIAL ISSUE, DATED 31ST OCTOBER 2008. DOA REPAIR PT21M-060 INCORPORATED TSN UNKNOWN CSN UNKNOWN							
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. LF7Y5043							
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.							
14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12 was accomplished in accordance with Part 145 and in respect to that work, the items are considered ready for release to service.							
13b. Authorised Signature:		13c. Approval / Authorisation Number		14b. Authorised Signature:		14c. Certificate / Approval Ref. No. :	
				 UTASW 0614		UK. 145.00860	
13d. Name:		13e. Date (dd mmm yyyy):		14d. Name:		14e. Date (dd mmm yyyy):	
				MATTHEW WHEAT		27 MAY 2021	
USER / INSTALLER RESPONSIBILITIES							
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

1. Approving Competent Authority/Country EASA		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 0000000000008549101 Page 1 of 1	
4. Organisation Name and Address: Goodrich Actuation Systems Stafford Rd, Fordhouses Wolverhampton, West Midlands, WV10 7EH, England				5. Work Order/Contract/Invoice 44296187 T34325	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
01	ROT VARIABLE TRANSFORMER	TY1931-20A	1	1200	REPAIRED
12. Remarks Purpose: Approval for Return to Service RETURNED FOLLOWING REPAIR AND TEST, IN ACCORDANCE WITH ACMM 78-30-35 INITIAL ISSUE, DATED 31ST OCTOBER 2008. DOA REPAIR PT21M-060 INCORPORATED TSN UNKNOWN CSN UNKNOWN					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12					
14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered ready for release to service.					
13b. Authorised Signature		13c. Approval / Authorisation Number		14b. Authorised Signature  UTASW 0614	
13d. Name		13e. Date (dd mmm yyyy)		14c. Certificate / Approval Ref. No. EASA.UK.145.00860	
				14d. Name MATTHEW WHEAT	
				14e. Date (dd mmm yyyy) 27 MAY 2021	
USER / INSTALLER RESPONSIBILITIES					
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

TEARDOWN REPORT

Goodrich Actuation Systems Ltd.
Stafford Road
WOLVERHAMPTON
WV10 7EH
UNITED KINGDOM
Repair Station #LF7Y504J



UTC Aerospace Systems

Customer A J WALTER AVIATION	Cust PO T34325	Operator PO
Input Part TY1931-20A	Input Serial 1200	Qty 1.000
Output Part TY1931-20A	Output Serial 1200	Workscope RE-CERTIFY
Cust Part	Cust Serial 1200	Status/Work REPAIRED
Description ROT VARIABLE TRANSFORMER	Removal Code TEST	Failure Date
Aircraft Exempt-Aircraft applications > 8,000 kg	Engine Type	
Incoming NSN N/A	Outgoing NSN N/A	Tail No
Date Rec'd 07.05.2021	Quote Date 17.05.2021	Accept Date 17.05.2021
Ship Date	DOM 01.05.2007	Last Order Date
Sales Order 8474688	Work Order 44296187	Notification 304233035
Customer Reason for Return Commercial Controller & Customer Req'm's TEST AS PER NECESSARY EASA FORM ONE AND CAA DUAL REQUIRED, IF UNIT PASS TEST, PLEASE ISSUE CAAC ALSO NO FLIGHT HOURS GIVEN		
Certification Type EASA FORM 1, DUAL AND CAAC		
CMM Reference ACMM Number and Revision A.C.M.M. 78-30-35 REVISION INITIAL ISSUE DATED - 31ST OCT 2008		
Preliminary Inspection Receipt Survey Findings UNIT RECEIVED IN A DIRTY CONDITION AND DAMAGE FOUND TO WIRING INSULATION.		
Evaluation Inspection Test As Received (T.A.R.) Results UNIT PASSED T.A.R. SATISFACTORY, NO FUNCTIONAL FAULTS WERE FOUND.		
Work Performed Strip Observations DOA REPAIR PT21M-060(LRS8851) INCORPORATED. FUNCTIONAL CHECKS PASSED IAW A.C.M.M. FINAL INSPECTION CARRIED OUT.		

Goodrich Actuation Systems Ltd.
Stafford Road
WOLVERHAMPTON
WV10 7EH
UNITED KINGDOM
Repair Station #LF7Y504J

TEARDOWN REPORT



UTC Aerospace Systems

Work Order	44296187	Description	ROT VARIABLE TRANSFORMER	Date Rec'd	07.05.2021
Input Part	TY1931-20A	Input Serial	1200		
Cust Part		Cust Serial	1200		

Administrative Notes

Free Text

DUE TO WIRING INSULATION DAMAGE UNIT REQUIRES D.O.A. REPAIR SCHEME
PT21M-060 INCORPORATED.

Components :

Order	Material	Description	Req Qty	Issued	Reason Code	Stor Loc
44296187	PT21M-060	TEST ITEM FOR REWORK	1	1	DAMAGE	CLAS

Author :
Print name : NOT APPLICABLE
Signature:
Date:

UTASW 0614

Authorized Approval :
Print name : MATTHEW WHEAT
Signature:
Date: 27 MAY 2021

UTASW 0614

Printed on 27.05.2021 14:50:47

Page 2 of 2

Instructions for Continued Airworthiness

Document Reference: PT21M-060 ICA

Issue: 01

Unit: TY1931 / TY2000

Build Standards: TY1931-20 / TY2000-20

Serial Number: Not Applicable

Customer: Not Applicable

Repair Number: PT21M-060 LRS8851

CMM: ATA Reference 78-30-35 / 78-30-37

The above part or appliance has been repaired in accordance with data produced and approved under Goodrich Actuation Systems European Aviation Safety Agency Design Organisation Approval

The purpose of this document is to provide the instructions for continued airworthiness of the part, or appliance, in accordance with Part 21A.449

There are no additional instructions for continued Airworthiness, repaired units can be maintained in accordance with the above CMM. This sheet is provided (unsigned) for reference and traceability purposes only

The technical content of this document is approved under the authority of Goodrich Actuation Systems Design Organisation Approval ref EASA 21J.161

Prepared by _____ Date _____

Aftermarket Value Stream

Approved _____ Date _____

Head of Airworthiness