

1. Approving Competent Authority / Country LUFTFAHRT-BUNDESAMT Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number DB 90630953 1/1	
4. Organisation Name and Address: AIRBUS AIRBUS Operations GmbH Lüneburger Schanze 30 21614 Buxtehude, Germany		5. Work Order/Contract/Invoice W43412			
6. Item: 7. Description		8. Part No	9. Qty	10. Certificate	11. Status/Work
N/A	FAP LIGHT PANEL	Z150H0107110	1	150H01003433	INSPECTED TESTED
12. Remarks: see Maintenance Report No.1045032 Work performed as per: CMM 23-73-14 Rev. 06 MAY-03-2018. work accomplished: SEP-26-2018 Amendment:C.2					
The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. K30Y905Y.					
14a. ☒ Part-145.A.50 Release to Service ☒ Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.					
14b. Authority Signature: 		14c. Certificate/Approval Ref.No.: DE.145.0286			
14d. Name: Mäckelmann		14e. Date (dd/mm/yyyy): 26.Sep.2018			
USER / INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority that has/has not issued this certificate, the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

MAINTENANCE ORDER		V Activity Category		1045032 Maintenance Number		 FSCM C9072	
Customer AJW	Part Number Z150H0107110		Serial No SPEC2000 150H01003433		Amd. C,2		
Description FAP LIGHT PANEL		Quantity 1		Repair-Station BUX			
Customer Order W43412		Cust. Order Date		Work Order 1045032		Work Order Date 16.08.2018	Prio ROUTINE
Required Activities:	Test X	Repair X	Modify	Inspection X	Scrap	Overhaul	Entry Date 16.08.2018
Redelivery Date 23.08.2018		Reason for Return not possible use buttons after installation					
Operator UKN	Removal Date	AC-Reg LY-COM	AC Type A320	Station UKN	Release Certificate EASA DUALFAA	Warranty	Chargeable X
Operators Man		OEM-Man O.E.M.-M		Aviation Device YES		Package OK	
Administrator: Becker		Department: ECYS1		Phone: 40743 60685			

MAINTENANCE REPORT	Preliminary Inspection/HD1	Pre- Strip-Test YES	Cond. elec. OK	Cond. SW OK	Cond. mech. OK	BITE N/A
	Status of Removal Unjustified Removal		Tech. warranty YES		Missing Part NO	
Findings: No error detected.						
Remarks: Work performed as per: CMM 23-73-14 Rev. 06 MAY-03-2018.						
Work performed: Preliminary and hidden damage inspection performed; acceptance test successfully performed.						
Final Condition	PN_After Z150H0107110	SN_After 150H01003433		AMD_After C,2		
Tested X	Repaired	Modified	Modified internal	Cond as is	Scrapped	Overhauled
Warranty	Charge_WC C	NFF X		QA-Inspected		
Work performed staff Geiger	Work performed department ECYS3		Work performed date 26.09.2018		26. Sep. 2018 	