





101145

1. Approving Civil Aviation Authority/Country <b>Transport Canada</b>		2. <b>AUTHORIZED RELEASE CERTIFICATE FORM ONE</b>			3. Form Tracking Number: <b>W085430</b>	
4. Organization Name and Address: <b>AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada</b>					5. Work Order, Contract or Invoice Number: <b>R362695-1</b>	
						
6. Item: 7. Description: <b>1 SSFDR- SOLID STATE FLIGHT DATA REC</b>	8. Part Number: <b>980-4700-042</b>	9. Quantity: <b>1.00</b>	10. Serial/ Batch Number: <b>1387</b>	11. Status/Work: <b>REPAIRED</b>		
12. REMARKS <b>REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 31-30-40 REV29 DATED 04APR2019. FOR ADDITIONAL INFORMATION REFER TO TEARDOWNINSPECTION REPORT. U.L.B. P/N DK120/90. S/N A173770. U.L.B. EXPIRY DATE: OCT 2024</b>						
<div><div><div><b>Virgin Australia Regional Airlines</b> <b>CERTIFIED TRUE COPY</b> STAMP</div><div>Date: <u>22/02/23</u></div><div>Signature: <u>[Signature]</u></div><div></div></div><div>EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17</div></div>						
13. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12						
13b. Signature:	13c. Approved Organization Number	14b. Signature:  	14d. Name (Typed or Printed) <b>Robert Milbers</b>	14e. Date (dd/mm/yyyy) <b>19/Aug/2019</b>	14c. Approval Organization Number <b>33-12</b>	
13d. Name (Typed or Printed):						
13e. Date:						
Installer Responsibilities						
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.						

2026845

GRN	19-2-2021
DATE	19-2-2021
LOC	ES floor





# Tea Jown/Inspection Report

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7  
www.ajw-group.com

Work Order: WO85430  
Date Printed: 8/19/2019  
Customer RO: R36265-1  
Page: 1

To: A J Walter Aviation Ltd.  
THE HEADQUARTERS  
MAYDWELL AVENUE  
SLINFOLD, WEST SUSSEX RH13 0AS  
UNITED KINGDOM

Code: AJW01	Fax:	Descr: SSFDR- SOLID STATE FLIGHT DATA RECORDER
Phone:		P/N: 980-4700-042
Email:		Qty: 1
TSN: N/A	TSO: N/A	TSR: N/A
		S/N: 1387
		Mfg: HONEYWELL INTL
		CSN: N/A
		CSO: N/A
		CSR: N/A
P/N Out: 980-4700-042		Serial Out: 1387

## Symptoms:

CODE: REASON FOR REMOVAL  
DETAILS: Inspection, ACC MPD 31-002-00-11 Verify all required parameters.  
CODE: MOD/AMENDMENT STATUS AR  
DETAILS: AMENDMENT STATUS ON ARRIVAL: 7 - 11, 13, 14.

## Faults:

CODE: DOWNLOAD DATA  
DETAILS: Data downloaded, decompressed, readout analysis to be done and burned on Disc.  
CODE: CUSTOMER REASON FOR REMOVAL CONFIRMATION  
DETAILS: Reason for removal as per repair order. Unit passed computer bench tests and Underwater Locator Beacon voltage and ping tests in accordance with CMM 31-30-40 REV29 Dated 04Apr2019.  
CODE: AD, SB, MOD, SIL REQUIREMENT  
DETAILS: This Service Bulletin required for Underwater Locator Beacon replacement (90-day) due to 30 day U.L.B. no longer available requires completion.  
CODE: SERVICE BULLETIN 980-4700-31-22 Rev. 2, 6 January 2016 - Indicating/Recording Systems - Solid State Flight Data Recorder New 90 Day ULB REPAIR  
CODE: (SSFDR) - Modification (MOD) 20 to the SSFDR Optional Replacement of the 30-Day Underwater Locator Beacon (ULB) With a REPAIR  
DETAILS: The following repair(s) will be performed. Service Bulletin 980-4700-31-22 to be completed. Inspection for corrosion required. Final test required.

## Corrective Actions:

CODE: REPAIRED  
DETAILS: Service Bulletin 980-4700-31-22 completed. Unit cleaned and inspected. Tested serviceable in accordance with CMM 31-30-40 REV29 Dated 04Apr2019.  
U.L.B. P/N DK120/80, S/N AT73770.  
U.L.B. expiry date: OCT 2024

PN	Description	Reason	Qty Needed	Disposition