

1. Approving National Aviation Authority/Country: FAA/UNITED STATES		2.		3. Form Tracking Number: 056636	
4. Organization Name and Address: Aircraft Instrument & Radio Services, Inc. 1851 S. Eisenhower Ct. Wichita KS 67209				5. Work Order/Contract/Invoice Number: Same as Block #3	
6. Item:		7. Description:		8. Part Number:	
1		THRUST REVERSER RELAY LOG		65B43710-4	
13. Remarks: REFERENCE WORK ORDER REPORT FOR WORK PERFORMED. ALL WORK PERFORMED i/a/w CMM NO. 78-35-01 Rev:5 Dt:02/01/88					
MODS INSTALLED NONE					
For EASA applications: Certifies that the work specified in block 12/13 was carried out in accordance with EASA 145 and with respect to that work the aircraft component is considered ready for release to service under EASA Acceptance Certificate Number: EASA.145.4100					
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block i3.				19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
15. Authorized Signature:		16. Approval/Authorization No.:		21. Approval/Certificate No: TI2R188L	
17. Name (Typed or Printed):		18. Date (m/d/y):		22. Name (Typed or Printed): ADAM HOLSTINE	
				23. Date (m/d/y): Jan/13/2011	

User/Installer Responsibilities	
It is important to understand that the existence of this Document alone does not automatically constitute authority to install the part/component/assembly.	
Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.	
Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.	



AIRC
GROUP

Aircraft Instrument & Radio Services
1851 S. Eisenhower Ct. Wichita, KS 67209
PH: (316) 945-9820 (800) 972-7626
FAX: (316) 945-8014
FAA REPAIR STATION #T12R188L

WORK ORDER TEARDOWN

Work Order No. 056636


ORIGINAL PN: 65B43710-4
REVISED PN: 65B43710-4
DESC: THRUST REVERSER RELAY LOG
SN: D00010
MODEL:
TECH: GRANT
INSP: ADAM

BILL TO:

A J WALTERS AVIATION LTD
STAR TRADING ESTATE
PARTRIDGE GREEN, SUSSEX RH13 8RA
ENGLAND

SHIP TO:

A J WALTER AVIATION LTD
VISCOUNT HOUSE
PARTRIDGE GREEN
WEST SUSSEX, RH13 8RA
UNITED KINGDOM

Date	Cust No.	Terms	Customer Contact		Cust PO	
01/13/11	01489	NET 45 DAYS BY W/T	ROB HARRIS-DIBBEN		127439	
F.O.B.		Ship Via	Manual	Rev	Rev Dt	Box #
COLLECT		DHL INT'L AIR FREIGHT	78-35-01	5	02/01/88	
Description						Qty
Action Requested: NO SQUAWK. ADVISE COST TO REPAIR IAW MFG SPECS. Preliminary Inspection/Defects Found: PERFORMED PRELIMINARY INSPECTION AND TESTING. INSPECTED AND FUNCTIONAL TESTED IAW MFG SPECS. NO DEFECTS FOUND. UNIT MEETS MFG SPECS. Parts Required: LABOR NO PARTS REQUIRED Action Taken: BENCH CHECKED IAW MFG SPECS. INSPECTED AND FUNCTIONALLY TESTED IAW MFG SPECS. TAGGED INSPECTED. TESTED AND CERTIFIED AIRWORTHY IAW CMM 78-35-01 REV 5 DATED 2/1/88. By  Date <u>01/13/2011</u> TARIFF 8536411010						2.5 0.0