

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7 www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO83991 Date Printed: 7/8/2019 Customer RO: R360812-1

Page: 1

To:

A J Walter Aviation Ltd. THE HEADQUARTERS **MAYDWELL AVENUE** SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM

Code: AJW01

Fax:

Descr: ELAC B (ELEVATOR AILERON COMPUTER)

Phone:

P/N: 3945128216

Qty: 1

Email:

S/N: ELACVB015402

Mfg: THALES AVIONICS SAS

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

CSO: N/A

CSR: N/A

P/N Out: 3945128216

Serial Out: ELACVB015402

Symptoms:

CODE: DETAILS: REASON FOR REMOVAL FÉCTR ELAC 1 PITCH FAULT

Faults:

CODE:

INITIAL TEST FAILURE

DETAILS: On test on ATEC6 test station, unable to reproduce the failure in shop.

CODE: DETAILS: TEST AND RECERTIFY Unit tested 2X without failure.

Test & re-certification.

Corrective Actions:

CODE:

INSPECTED/ TESTED

DETAILS:

INSPECTED/TESTED SERVICEABLE PER CMM 27-93-35A REV.18 DATED APRIL 20, 2018 AND ATEC6 TEST PROGRAM

6-H7FG REL.01.