

1. Approving Civil Aviation  
Authority/Country:

2.

FAA/UNITED STATES

**AUTHORIZED RELEASE CERTIFICATE**  
FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

**256632**

4. Organization Name and Address:

Aero Accessories & Repair, Inc.

FAA CERT #77AR783B

15501 SW 29TH ST. SUITE#201

MIRAMAR, FL 33027

Ph: 954-266-1300,

5. Work Order/Contract/Invoice  
Number:

**61205**

**T42451**

FAA Approval Holder: 77AR783B

6. Item

7. Description:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

1 ACTUATOR, FLAP

793C0000-01

1

X20457

OVERHAULED

12. Remarks:

The component identified above was OVERHAULED in accordance with Federal Aviation Regulation and is approved for return to service with respect to the work performed. Pertinent details of the work accomplished are on the file at this agency under Form Tracking Number identified above.

Removed from A/C, RP-C7935

TSO: 0.00 CSO: 0

S/B and A/D: None Applicable.

OEM CMM: 27-53-67, Revision#: 6, Revision Date: 5/28/2021

**ORIGINAL**

Certifies work specified in blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA part 145 Approval Number EASA 145-6467

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No.:

14b. Authorized Signature:

14c. Approval/Certificate No.:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

**WELCEMEN B. JEANNOT**

**77AR783B**

**13-Nov-2023**

**User/Installer Responsibilities**

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

**Aero Accessories & Repair, Inc.**

FAA CERT #77AR783B  
15501 SW 29TH ST. SUITE#201  
MIRAMAR, FL 33027  
Ph: 954-266-1300,

**Work Order****Work Order #: 61205**

Date Printed: 11/13/2023

Time: 10:29:14 AM

Page: 1

**To:**

AJW AVIATION LTD.  
THE HEADQUARTERS  
MAYDWELL AVENUE  
SLINFOLD, SLI RH13 0AS  
UNITED KINGDOM

**Ship To:**

AJW AVIATION LTD.  
THE HEADQUARTERS  
MAYDWELL AVENUE  
SLINFOLD, WS RH13 0AS  
UNITED KINGDOM

Ref #: T42451

Phone #: 305 470 8007

Fax #: 441.403.710.936

Email: louise@ajw-group.com

Code: 45

Site: SH/DV

PN: 793C0000-01

Descr: ACTUATOR, FLAP

Qty: 1

Station: HYDRAULIC

Make:

Model:

Mfg: \_

Repair Manual(s): 27-53-67 Rev: 6 Rev. Date: 5/28/2021

Entry Date: 11/1/2023

Need Date:

Compl. Date: 11/13/2023 10

Warranty: No

Container:

Serial Numbers:

X20457

**RECEIVING INSPECTION**

P/N and S/N verified on unit and customer RO. No external damage noted. See RO for work scope. Technician must verify.

**PRELIMINARY INSPECTION**

P/N 793C0000-01 verified IAW Technical data Referenced above.

S/N X20457 verified through ID plate and customer RO.

TSN: UNK CSN: UNK

TSO: UNK CSO: UNK

Tech: A.M #40

**HIDDEN DAMAGE**

None noted.

**INITIAL FINDINGS**

Unit failed IAW technical data referenced above.

Reason: Leakage.

Customer Complaint: N/A

Tech: A.M #40

**TEARDOWN FINDINGS**

Unit disassembled, cleaned and inspected IAW technical data referenced above. Requires replacement of all seals packings and retainers. Rear ring gear is corroded and requires replacement. Input shaft speed sleeves are worn and will be replaced. Minor nicks, scratches, and dents do not affect fit, form, or function of the unit.

Unit will be Overhauled

Tech: A.M #40

**CORRECTIVE ACTION**

All parts listed in Teardown Report were replaced and findings listed were corrected. Unit was overhauled and tested IAW technical data reference above.

Tech: AM#40

Authorized Signature: \_\_\_\_\_

Name: WELCEMEN JEANNOT

Date: 11/13/2023



Aero Accessories & Repair, Inc.

FAA CERT #77AR783B  
15501 SW 29TH ST. SUITE#201  
MIRAMAR, FL 33027  
Ph: 954-266-1300.

# Packing Slip



SH42315

## Aero Accessories & Repair, Inc.

FAA CERT #77AR783B  
15501 SW 29TH ST. SUITE#201  
MIRAMAR, FL 33027  
Ph: 954-266-1300.

Customer: AJW AVIATION LTD.

Shipping Order: SH42315

Order: 61205

Terms: Not determined

Ship Via: FEDEX INTERNATIONAL PRIORITY

Ship Via Acc: 124277507

AWB: 704138765144

Page: 1

Date: 11/13/2023

Time: 12:57:35 PM

Ship To: AJW AVIATION LTD.

THE HEADQUARTERS  
MAYDWELL AVENUE  
SLINFOLD, WS RH13 0AS  
UNITED KINGDOM

Customer PO#: T42451

Order Total: 0

Part Number/Description	Serial Number	Qty	CD
793C0000-01 ACTUATOR, FLAP	X20457	1	OH