



1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 20220010461956Y15 343727765	
4. Organization Name and Address: Honeywell International Inc. 23500 W 105th Street Olathe KS 66061		Repair Station PR2R093L		5. Work Order/Contract/Invoice Number: T36533 343633657 Page 1 of 1	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:
001	OUTLINE ASSEMBLY MULTI-MODE RECEIVER, RM	066-50029-1201	1	RMA55B-05481	REPAIRED
12. Remarks: THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH: CMM 34-55-51 Rev 6, MAY/07/2020 TSN-TSO: UNK CSN-CSO: UNK THIS DOCUMENT HAS BEEN ISSUED ACCORDING TO AN APPROVED COMPUTER GENERATED SIGNATURE PROCEDURE MODS: 1-5 SW VERS: NA					
SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NO. EASA 145.4140					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		14c. Approval/Certificate No.: PR2R093L	
13b. Authorized Signature:		13c. Approval/Authorization No.:		14b. Authorized Signature: <i>Fatima Durant</i>	
13d. Name (Typed or Printed):		13e. Date(dd/mm/yyyy):		14d. Name (Typed or Printed): Fatima Durant	
User / Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown. NSN : 0052 - 00 - 012 - 9005					



1. 国家 Country	2. 中国民用航空总局 CAAC	☐ 符合性 Conformity	☒ 适航性 Airworthiness	3. 证书编号 20220010461959Y05 34372765	Certificate Ref. No.	
中国 China	批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG					
4. 单位 Organization	Honeywell International Inc. 23500 W 105th Street Olathe KS 66061				5. 工作单/合同单/货单 Work Order/Contract/Invoice T36533 343633657 Page 1 of 1	
6. 序号 Item	7. 内容 Description	8. 件号 Part No.	9. 适用性 Eligibility	10. 数量 Qty	11. 系列号/批号 Serial/Batch No.	12. 产品状态 Status/Work
001	OUTLINE ASSEMBLY MULTI-MODE RECEIVER, RM	066-50029-1201	NOT KNOWN	1	RMA55B-05481	REPAIRED
13 备注 Remarks THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH: CSM 34-55-51 Rev 6, MAY/07/2020 TSN-TS0: UNK CSN-CS0: UNK THIS DOCUMENT HAS BEEN ISSUED ACCORDING TO AN APPROVED COMPUTER GENERATED SIGNATURE PROCEDURE MODS: 1-5 SW MODS: 01/02 SW VERS: NA						
SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED						
14. 新产品 New Parts		15. 使用过的产品 Used Parts				
兹声明上述产品除第13项的其它规定以外， 已按照上述国家适航条例进行制造/检查， 并且该产品(出口产品)符合经批准的型号设计资料和进口国提出的专用要求。 Certifies that the part(s) identified above except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.		兹声明上述产品除第13项的其它规定以外， 已按照上述国家适航条例和进口国通知的特殊要求进行了工作， 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is(are) in condition for safe operation and considered ready for release to service. (over)				
16. 批准人签名 Signature Fatima Durant		19. 中国民航总局授权 Issued by or on behalf of the CAAC F00100519				
17. 批准人姓名 (打印的) Name (Printed) Fatima Durant		18. 批准日期 Date FEB/22/2022				

* 参阅产品目录详细查找适用性

Cross - check eligibility for more details with parts catalogue

AAC - 038(12/94)

SERVICE REPORT

AJW AVIATION LTD

SR NUMBER: 5016279331		343727765	FAA: PR2R093L	EASA: EASA.145.4140
PO: T36533	CUSTOMER PART NUMBER:		CONTRACT NUMBER: 440115439	
DATE REJECTED: 25 JAN 2022	DATE RECEIVED: 07 FEB 2022		DATE COMPLETED: 22 FEB 2022	
A/C TYPE: UNK	A/C TAIL NUMBER: UNK		A/C SERIAL NUMBER: UNK	
PACKING STATUS: No	SEALS INTACT: Intact		PHYSICAL DAMAGE: No	

REASON FOR REMOVAL:

Please test, repair and recertify as necessary FREE OF CHARGE in accordance with B737MAX DISTRIBUTION agreement, S0147450 REMOVED FROM AJW STOCK SHELF LIFE EXPIRED CONDITION PLEASE NOTE THAT WE PURCHASED THIS UNIT FROM HONEYWELL. IT WAS REMOVED FROM AIR

PART NUMBER	AS RECEIVED: 066-50029-1201	AS RELEASED: 066-50029-1201
DESCRIPTION:	OUTLINE ASSEMBLY MULTI-MODE RECEIVER,	OUTLINE ASSEMBLY MULTI-MODE RECEIVER,
SERIAL NUMBER	RMA55B-05481	RMA55B-05481
UID(MFR/SPL PNO SER/UCN)	97896 RMA55B-05481	97896 RMA55B-05481
HW MOD STATUS:	1-5	1-5
SW MOD STATUS:	01/02	01/02
SOFTWARE LOAD:	NA	NA
REASON FOR REMOVAL CONFIRMED: Rejection Confirmed		ESTIMATE SUPPLIED: No
PRIMARY SHOP FINDING: Hardware Fault Found		WARRANTY: Warranty Accepted
TYPE OF SERVICE: REPAIRED		TECHNICIAN: Curtis Walker

MAINTENANCE STATEMENT:

PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2.

SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE: _____

SIGNATURE OF AUTHORIZED PERSON: _____

Complied With

CMM/Eng Documentation: 34-55-51/Rev 6/Rev Date 07 MAY 2020;
Service Bulletins:
Customer Manuals/Documentation:

SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.

SERVICE REPORT

AJW AVIATION LTD

SR NUMBER: 5016279331		FAA: PR2R093L	EASA: EASA.145.4140
PO: T36533	CUSTOMER PART NUMBER:	CONTRACT NUMBER: 440115439	

Previously Complied With CMM/Eng Documentation: Service Bulletins: Customer Manuals/Documentation:								
Evaluation Findings Fails incoming test due to GNSS failures ID#63,44 Not Acknowledged. Replace GNSS module. Work performed / Comments to Customer Fails incoming test due to GNSS failures ID#63,44 Not Acknowledged. Installed repaired GNSS module and retested. Unit now passes all tests.								
DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SB
Exchange	GNSS MODULE	722-4374-002	06072179	722-4374-002	08103720	1		