


1. Approving Competent Authority/Country LUFTFAHRT-BUNDESAMT Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 30010211164	
4. Organisation Name and Address DIEHL Aerospace GmbH Alte Nußdorfer Straße 23 88662 Überlingen - Germany		Telephone : +49 7551 891 0 Telefax : +49 7551 891 4001 Mail address : Postfach 10 12 62, 88642 Überlingen		5. Work Order / Contract / Invoice (Delivery Note No. / Order No. / Customer PO No.) 410328020 / 320151733 / T31164	
6. Item 000010	7. Description EPSU 3214-62 W/O BAT	8. Part No. 773-881-00	9. Quantity 1	10. Serial No. 0345	11. Status/Work MODIFIED

12. Remarks

This Certificate is issued by DAs location 6 Impasse AliceGuy, 31300 Toulouse - France
Change State: AMDT -
Technical action report 50228074 describing the actual work performed is attached
Work performed according to CMM 33-51-10 REV.2.0 dated MAR 25/02
PART OF NHA EMERGENCY POWER SUPPLY (EPSU) PN 3214-62
VSIL D1347-33-053 Rev.02 dated Oct 11/2016 applied

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. B2WY697J

13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ Part-145 A.50 Release to Service Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service. ☒ Other regulation specified in block 12	
13b. Authorised Signature / Electronic Signature on File	13c. Approval/Authorisation Number	14b. Authorised Signature / Electronic Signature on File  T85299	14c. Certificate/Approval Ref. No. DE.145.0041
13d. Name	13e. Date (DD MMM YYYY)	14d. Name Nadège Amri	14e. Date (DD MMM YYYY) 12 APR 2018

USER / INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

DIEHL Aerospace		TECHNICAL ACTION REPORT		Rep.-No. : 50228074 / 0 Page : 1 / 1	
		EPSU 3214-62 W/O BAT		Sales Order : 320151733-30000	
Customer : A.J.Walter Aviation Ltd Cust.Order : T31164 Failure Report : Comp. Date in : 29.03.2018		In PN : 773-881-00 Amdt : - SN : 0345		Out PN : 773-881-00 Amdt : - SN : 0345	
Maintenance requirement : CMM 33-51-10 REV.2.0 MAR 25/02					
Complaint confirmed: NO		Work Type: Modification			
Warranty accepted: NO		Special Investigation: NO			
Removal Date:		A/C SN: 9M-MKA		A/C Pos:	
Equipment: 				MFG : 09/1992	
Customer Complaint: FOR REPAIR					
Shop finding/actions: VSIL D1347-33-053 REV02 APPLIED Defects/replacements:					
Comment:					
Date: 12.04.2018		Author: MAROC		 	

ZAC de Saint Martin du Touch
6 Imp Alice Guy
F-31300 Toulouse

Tel (33) 05 61 71 00 67
Fax (33) 05 61 30 00 98

TEST REPORT FOR EPSU WO BATTERY

Unit : Emergency Power Supply Unit
Part Number : 773-881-00
SERIAL NUMBER : 0345
Amendment : -
Manufactured By DLE : Vendor Code D1347
Date of Manufacture : 09/1992

Test in accordance with CMM : 33-51-10 Rev.2 Mar 25/02
Test Equipment : EP4-105-68 + Tools Battery 3214-31 for
Certification of Emergency Power Supply
3214-62

Visual Check:	OK
Test of teach-in:	OK
Centralized system test:	OK
Verification of the truth table:	OK
Verification of the automatic operation:	
Normal to emergency operation:	OK
Emergency to normal operation:	OK
Verification of sleep mode:	OK

Test Performed by : N. GONZALEZ

Date : 09.04.2018

Stamp : 4357

The Acceptance Inspection was performed according to the reference document. The result of the Acceptance Inspection is satisfactory.

Date :

Inspected by :

Stamp

12 AVR. 2018

[Signature]

