

1. Approving Competent Authority / Country CAA.UK		2. AUTHORIZED RELEASE CERTIFICATE EASA FORM 1				3. Form Tracking Number AT53375	
4. Organisation Name and Address: AVIA TECHNIQUE LTD Units 1 & 3, Fishponds Estate Fishponds Road, Wokingham Berkshire, England RG41 2QJ		5. Work Order / Contract / Invoice RMA80403 U10502					
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work		
1	Fire Extinguisher	74-00	One	9485	Overhauled		
12. Remarks Refer to Inspection Report I RMA80403 Reference CMM 26-24-05 Revision: I Date Of Manufacture: 02/2000 Next Overhaul/Hydrostatic Test Due: 12/2024 Checked Weight: 2.005 Kgs << Certifies that work specified in block 11/12 was carried out in accordance with FAR part 43 and in respect to that work the part(s) is (are) approved for return to service. Pertinent details of the repair are on file at this repair station under :- Order No.: U10502 Date: 02/Dec/2014 Signed   FAA Repair Station No.: I8QY183X							
Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.							
13a. Certifies that the items identified above were manufactured in conformity to: ☒ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ Part-145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.		14b. Authorised Signature 			
13b. Authorised Signature		13c. Certificate/Approval Ref. No.: UK:21G.2347		14c. Certificate/Approval Ref. No.: UK:145.00846			
13d. Name		13e. Date (dd/mm/yyyy)		14d. Name Gareth Higgs			
13e. Date (dd/mm/yyyy)		14e. Date (dd/mm/yyyy)		14e. Date (dd/mm/yyyy) 02/Dec/2014			
USER / INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

From: L.P.Houghton	To: A.J. Walter Aviation Ltd Attn: Georgia Tarling	Date: 19 November 2014
-----------------------	--	---------------------------

Subject:

INSPECTION REPORT

I RMA80403

CUSTOMER:	A.J. Walter Aviation Ltd	PART NUMBER:	74-00
CUSTOMER ORDER No.:	U10502	DESCRIPTION:	Fire Extinguisher
ADV/REJ NOTE:		SERIAL No:	9485
DATE REC.:	18/11/2014	OUR REF No.:	RMA80403
DATE MANUFACTURE:	02/2000	QUANTITY:	One

REASON FOR REJECTION / RETURN:

TEST

PRELIMINARY CHECKS:

Visual inspection carried out in accordance with the OEM CMM.

INVESTIGATION RESULTS:

Visual inspection found unit due overhaul, therefore overhaul required. Valve assembly leaking. Labels damaged. Unit otherwise satisfactory.

DETAILS OF WORK TO BE CARRIED OUT:

Fit new valve assembly and labels. Overhaul, Test and Certify with reference to the correct issue of the CMM.

LIABILITY / REMARKS:

Customer

Inspector: L.P.Houghton	Signature: <i>LPHoughton</i>	Stamp: 	Date: 19/11/2014
----------------------------	---------------------------------	--	---------------------

COP 009/002