

1. Approving Competent Authority / Country

2.

AUTHORISED RELEASE CERTIFICATE

EASA FORM 1

3. Form Tracking Number

E3256288

EASA

4. Organisation Name and Address:

Panasonic Avionics Services Singapore Pte. Ltd

5. Work order/Contract/Invoice

3256288 /
IFE800193

No: 9 Loyang Lane, Singapore 508927
Tel: 65-6381-6101 Fax: 65-6545-7484

6. Item

7. Description

TAPPING UNIT (TU)

8. Part No.

RD-FA2051-02

9. Qty.

1

10. Serial No.

E725289

11. Status / Work

INSPECTED/TESTED

12. Remarks PERTINENT DETAILS OF MAINTENANCE ACTIONS ARE HELD AT THIS FACILITY UNDER WORK ORDER NO. AS STATED ABOVE.

MODIFICATION STATUS : 1
CMM 44-26-44 Rev 5 Dated 28-Oct-11

Reference Detail Work in attached Repair Report

13a. Certifies that the items identified above were manufactured in conformity to:

- ☐ approved design data and are in condition for safe operation
☐ non-approved design data specified in block 12

14a ☒ Part-145.A.50 Release to Service

☐ Other regulation specified in block 12

14b. Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature

13c. Approval/ Authorisation Number

14b. Authorised Signature

3

14c. Certificate / Approval Ref. No.
EASA.145.0475

13d. Name

13e. Date (dd mmm yyyy)

14d. Name

LOW TECK ENG

14e. Date (dd mmm yyyy)
27 Jun 2013

USER / INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/ installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, that his/ her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must obtain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Panasonic Avionics Services Singapore Pte Ltd.
9 Loyang Lane, Singapore 508927
Tel: 65-6381-6101 Fax: 65-6545-7484

SOLD TO TRANSAERO AIRLINES
11A, ZUBOVSKY BOULEVARD
MOSCOW, 119021, RU

SHIP TO TRANSAERO AIRLINES
11A, ZUBOVSKY BOULEVARD
MOSCOW, 119021, RU

REPAIR REPORT / DELIVERY ORDER

PAGE 1 of 1

SHIP TRANSACTION:

CUSTOMER P.O. NUMBER		1189		EI-XLP		9661569		3256288	
PART NUMBER		NOMENCLATURE		TAPPING UNIT		DATE REMOVED		DATE RECEIVED	
RD-FA2051-02								13-JUN-2013	
SERIAL NUMBER		DATE OF MFG		WTY START DATE		WTY END DATE		DATE REPAIRED	
E725289		31-DEC-2010		31-DEC-2010		30-MAR-2014		21-JUN-2013	
MOD IN								SHIP DATE	

REASON FOR CUSTOMER REJECTION

INTERNAL INSPECTION: No Physical Damage, HIDDEN DAMAGE INSPECTION: NA.

EXTERNAL INSPECTION: No Physical Damage, PRELIMINARY INSPECTION: NO SEAL.

ACTUAL FAILURE / CORRECTIVE ACTION

PRETEST: PASSED, CLEANED LRU, UNIT TESTED PASSED AS PER CMM 44-26-44 REV 5, 28 OCT 2011.

MOD OUT: 1

INSPECTED BY: LOW, TECK ENG

REPAIRED BY: Ho Kian Soon, Andy

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
-------------	-------------	-----	------------	----------------	----------------	------

A/V DISTRIBUTION N A/V DISTRIBUTION NFF FEE

300.00

300.00

300.00

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

* WTY CODES
NO = Not Covered
FOC = SB covers as FOC
SHOP = Shop Wty
WARR = Mfg Wty in Effect
FIXED = Fixed Price Repair
CC = Panasonic Charged

Cost of Labor

300.00

Cost of Material

300.00

Total Cost