


1. Approving Civil Aviation
Authority/Country
Transport Canada

**AUTHORIZED RELEASE CERTIFICATE
FORM ONE**

3. Form Tracking Number.
WO66487

4. Organization Name and Address.

AJW Technique Inc
7055, rue Alexander Fleming
Saint-Laurent QC H4S-2B7
Canada



5. Work Order, Contract or
Invoice Number:
R340615-1

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	Audio Selector Panel Assembly	285T0022-40	1.00	D01119	REPAIRED

12. REMARKS

UNIT INSPECTED, REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 23-51-54 REV.38 DATED AUG22/2017.
FOR FURTHER INFORMATION REFER TEAR DOWN/INSPECTION REPORT.

PRINTED FROM ELECTRONIC FILE

EASA Approval No.: EASA 145 7260
Maintenance performed in accordance with FAR 43.17

13a. Certifies the items identified above were manufactured in conformity to:


☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

☒ CAR 571.10 Maintenance Release

☒ Other regulation specified in Block 12

13b. Signature:	13c. Approved Organization Number	14b. Signature 	14c. Approval Organization Number 33-12
13d. Name (Typed or Printed):	13e. Date	14d. Name (Typed or Printed) Sarbjit Toor	14e. Date (dd/mm/yyyy) 29/Jun/2018

Installer Responsibilities

This certificate does not constitute authority to install the part.

Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.
Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

Work Order #: WO66487

Date Printed: 6/29/2018

Customer RO: R340615-1

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Phone #:

Code: AJW01

Descr: Audio Selector Panel Assembly

Fax #:

PN: 285T0022-40

Serial # : D01119

Email:

Qty: 1

Mfg: BAE SYSTEMS CONTROLS

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

CSO: N/A

CSR: N/A

P/N Out: 285T0022-40

Serial # out: D01119

Symptoms:

CODE: REASON FOR REMOVAL

DETAILS: Back lighting U/S fitted to sim F/O position.

Faults:

CODE: CUSTOMER REASON FOR REMOVAL CONFIRMATION

DETAILS: Reason for removal is confirmed.

CODE: INITIAL TEST FAILURE

DETAILS: Initial test failure is attributed to cold solder on front panel PCB.
Output low, need calibration.

CODE: CLEANING

DETAILS: Unit very dirty, need deep cleaning.

CODE: PAINTING

DETAILS: Painting is required due to worn out paint on front panel.

CODE: OUT OF CALIBRATION

DETAILS: Perform calibration per CMM23-51-54.

CODE: REPAIR

DETAILS: Unit disassembled in over to perform cleaning, calibration and repair tasks.

Corrective Actions:

CODE: REPAIRED

DETAILS: UNIT INSPECTED, REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 23-51-54 REV.38.