

1. Approving National Aviation Authority/Country: FAA/United States		3. Form Tracking Number: 31640547			
4. Organization Name and Address: B/E Aerospace 3355 East LaPalma Ave. Anaheim, CA 92806 (B98R479N)					
6. Item: 1	7. Description: PC BOARD ASSY (348-)	8. Part Number: 4959-1	9. Eligibility: * N/A	10. Quantity: 1	11. Serial/Batch Number: 15006
13. Remarks:		12. Status/Work: Repaired			
5. Work Order/Contract/Invoice Number: C425R461					

This repair order: **4788772** Describes actual repair work in detail. All work IAW **DWG: 4959** Date: **08/31/2005** Rev: **AC**

"Certifies that the work specified in block 12/13 was carried out in accordance with EASA Part 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 Approval Number: **EASA.145.4231**"

Service Bulletins Incorporated: **IAW CMM**

14. Certifies the items identified above were manufactured in conformity to:		19. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 13	
☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 13.		Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
15. Authorized Signature:	16. Approval/Authorization No.: N/A	20. Authorized Signature: <i>[Signature]</i>	21. Approval/Certificate No.: B98R479N
17. Name (Typed or Printed): N/A	18. Date (m/d/y): N/A	22. Name (Typed or Printed): <i>Scott C. NE/100</i>	23. Date (m/d/y): Dec/01/2011

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

*Installer must cross-check eligibility with applicable technical data.

REPAIR FINDINGS ANALYSIS / TEARDOWN REPORT

FAA Repair Station#: B98R479N

Company Name: B/E Aerospace
FSC#: 60299
Address1: 3355 East LaPalma Ave.
Address2:
City St Zip: Anaheim CA 92806
Phone: 714-688-4200
Fax: 714-688-4154

Date: 12/05/2011

Customer Name: AVEOS FLEET PERFORMANCE
Address1: ATT: ACCOUNTS PAYABLE (ZIP 8067)
Address2: 2311 ALFRED-NOBEL BLVD., BAN 3
City St Zip: SAINT-LAURENT QU H4S 2B6 CA
Contact: STEVE RIVA (steve.riva@aveos.com)
Phone: 778-296-4600X545396
Fax: 912-257-4547

Information from Purchase Order

Repair Order#: C425R461	Part# from PO: 4959-1	Serial# from PO: NA
-------------------------	-----------------------	---------------------

Customer Serial# on Order:

Purchase Order Reason: UNSERVICABLE. REPAIR AS PER LATEST. (ORIG NHA: 348-19, SN 1206 MFG: 11/19/97) DADRI 4636

Information for Part Received

Repair ID#: 36645	Work Order#: 4788772	Mfr. p/n Recvd: 4959-1	Mfr. Serial# Recvd: 15006
-------------------	----------------------	------------------------	---------------------------

Initial Inspection Findings: N/A

Initial Testing Findings:

PC BOARD: PC Board, Failed; Update to Latest Rev.; Air temp control circuit failed.

Repair Administration Comments:

Warranty:

☐ Accepted ☐ Denied ☐ Partial

Reason:

Information for Part Shipped Back

Sales Order#: 31640547

Mfr. p/n Out: 4959-1	Mfr. Serial# Out: 15006
----------------------	-------------------------

Teardown and Inspection details:

PC board

PC BOARD: PC Board, Failed; Update to Latest Rev.; Air temp control circuit failed.

CMM Ref. I: 4959 Rev Date: 08/31/2005 Rev: AC

Corrective Actions:

PC board

PC BOARD: PC Board(s), Repaired;

Remarks: Replaced Terminal TB1, VR1. Test good.

Purchase Order Instructions complied with:

☐ Inspected ☒ Repaired ☐ Modified ☐ Overhauled

Replacement Parts/Services for Part Shipped Back					
Type	Item	Description	Qty/Hrs	UPR/Rate	
LABOR	510	REPAIR - ORDER RELEASE	0.00	\$0.00	
LABOR	572	PCB TECH	0.00	\$0.00	
LABOR	630	REPAIR - INSPECTION	0.00	\$0.00	
MATL	4959-1	REPAIRED/UPGRADED PC BOARD ASSY.	1.00	\$1,004.89	
Material Price: \$1,004.89			Labor Price: \$0.00		Total Price: \$1,004.89

BE AEROSPACE, INC.
 3355 EAST LA PALMA AVENUE
 ANAHEIM CA 92806
 United States
 Phone: +1.714 .688.4200
 Fax: +1.714 .688.4152



SOLD TO

158828

AVEOS FLEET PERFORMANCE

ATT: ACCOUNTS PAYABLE (ZIP 8067)

2311 ALFRED - NOBEL BLVD., BAN 3

SAINT-LAURENT QU H4S 2B6

Canada

SHIP TO

184009

AVEOS - SCM

740 COTE VERTU WEST - OVSV

BUILDING 7 GATE 2

MONTREAL INTERNATIONAL AIRPORT

DORVAL

QUEBEC H4S 1Y9

SHIP DATE

12/05/11

FED EX INTL PRIORITY

FOB Origin-3rd Party Billing

797807182696

SHIP VIA

DELIVERY TERMS

WAYBILL NUMBER

CUST LINE

ITEM

REV NO.

DESCRIPTION

ORDERED

SHIPPED

BACK ORDERED

1.000

4959-1

PC BOARD ASSY (348-)

Serial Numbers for line 1.000:

15006

ECGN No: 9A991D

FIN # 06-1209796

NLR

COUNTRY OF ORIGIN: USA

These commodities, technology of software ("Items") were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to US law is prohibited.

Schedule B # 8803.30.0030

*** END OF ORDER ***

1

1