

1. Approving National Aviation
Authority, Country:

2
FAA/United States

4. Organization Name and Address:

B/E Aerospace 3355 East LaPalma Ave. Anaheim, CA 92806 (B98R479N)

6. Item:

7. Description:

1

PC BOARD ASSY (348-)

13. Remarks:

8. Part Number:

4959-1

9. Eligibility: *

N/A

10. Quantity:

1

11. Serial/Batch Number:

29821

5. Work Order/Contract/Invoice
Number:

C425R544

12. Status/Work:

Repaired

3. Form Tracking Number:

31640546

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

This repair order: **4788771** Describes actual repair work in detail. All work IAW **DWG: 4959** Date: **08/31/2005** Rev: **AC**

"Certifies that the work specified in block 12/13 was carried out in accordance with EASA Part 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 Approval Number: EASA.145.4231"

Service Bulletins Incorporated: **IAW CMM**

14. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in a condition for safe operation.
☐ Non-approved design data specified in Block 13.

15. Authorized Signature:

N/A

16. Approval/Authorization No.:

N/A

17. Name (Typed or Printed):

N/A

18. Date (m/d/y):

N/A

19. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 13

Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

20. Authorized Signature:

[Signature]

21. Approval/Certificate No.:

B98R479N

22. Name (Typed or Printed):

Buott Carlson

23. Date (m/d/y):

Dec/01/2011

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

FAA Form 8130-3 (6-01)

*Installer must cross-check eligibility with applicable technical data.

NSN: 0052-00-012-9005

REPAIR FINDINGS ANALYSIS / TEARDOWN REPORT

Date: 12/05/2011

FAA Repair Station#: B98R479N
Company Name: B/E Aerospace
FSC#: 60299
Address1: 3355 East LaPalma Ave.
Address2:
City St Zip: Anaheim CA 92806
Phone: 714-688-4200
Fax: 714-688-4154

Customer Name: AVEOS FLEET PERFORMANCE
Address1: ATT: ACCOUNTS PAYABLE (ZIP 8067)
Address2: 2311 ALFRED-NOBEL BLVD., BAN 3
City St Zip: SAINT-LAURENT QU H4S 2B6 CA
Contact: STEVE RIVA (steve.riva@aveos.com)
Phone: 778-296-4600X545396
Fax: 912-257-4547

Information from Purchase Order

Repair Order#: C425R544 Part# from PO: 4959-1 Serial# from PO: 29821

Customer Serial# on Order:

Purchase Order Reason: NO REASON GIVEN. REPAIR AS PER LATEST. (ORIG NHA: 348-19, SN 1679 MFG: 01/19/01) DADRI 4636

Information for Part Received

Repair ID#: 36644 Work Order#: 4788771 Mfr. p/n Recvd: 4959-1 Mfr. Serial# Recvd: 29821

Date Recvd: 11/14/2011

Description: PC BOARD ASSY (348-)

Initial Inspection Findings: N/A

Initial Testing Findings:

PC BOARD: PC Board, Failed; Update to Latest Rev.; PCB circuit shorted out.

Repair Administration Comments:

Warranty:

☐ Accepted ☐ Denied ☐ Partial

Reason:

Information for Part Shipped Back

Sales Order#: 31640546

Mfr. p/n Out: 4959-1

Mfr. Serial# Out: 29821

Teardown and Inspection details:

PC board

PC BOARD: PC Board, Failed; Update to Latest Rev.; PCB circuit shorted out.

CMM Ref. 1: 4959 Rev Date: 08/31/2005 Rev: AC

Corrective Actions:

PC board

PC BOARD: PC Board(s), Repaired ;

Remarks: Replaced Terminal TB1, U12, U14. Test good.

Purchase Order Instructions complied with:

☐ Inspected ☒ Repaired ☐ Modified ☐ Overhauled

Replacement Parts/Services for Part Shipped Back

Type	Item	Description	Qty/Hrs	UPR/Rate
LABOR	510	REPAIR - ORDER RELEASE	0.00	\$0.00
LABOR	572	PCB TECH	0.00	\$0.00
LABOR	630	REPAIR - INSPECTION	0.00	\$0.00
MATL	4959-1	REPAIRED/UPGRADED PC BOARD ASSY.	1.00	\$1,004.89
Material Price: \$1,004.89				
Labor Price: \$0.00				
Total Price: \$1,004.89				

BE AEROSPAC, INC.
 3355 EAST LA PALMA AVENUE
 ANAHEIM CA 92806
 United States
 Phone: +1.714 .688.4200
 Fax: +1.714 .688.4152



SOLD TO

158828

AVEOS FLEET PERFORMANCE

ATT: ACCOUNTS PAYABLE (ZIP 8067)
 2311 ALFRED- NOBEL BLVD., BAN 3
 SAINT-LAURENT QU H4S 2B6
 Canada

SHIP TO

184009

AVEOS - SCM

740 COTE VERTU WEST - OVSU

BUILDING 7 GATE 2

MONTREAL INTERNATIONAL AIRPORT

DORVAL

QUEBEC H4S 1Y9

Canada

SHIP DATE

12/05/11

CUST LINE

ITEM

PART NUMBER

REV NO

DESCRIPTION

ORDERED

SHIPPED

BACK ORDERED

QUANTITY

795476765137

WAYBILL NUMBER

DELIVERY TERMS

FED EX INTL PRIORITY FOB Origin-3rd Party Billing

1.000

4959-1

Serial Numbers for Line 1.000:
 PC BOARD ASSY (348-)

1

1

ECCN No: 9A991D

EIN # 06-1209796

NLR

COUNTRY OF ORIGIN: USA

These commodities, technology of software ("Items")
 were exported from the United States in accordance
 with the Export Administration Regulations. Diversion
 contrary to US Law is prohibited.

Schedule B # 8803.30.0030

***** END OF ORDER *****

ORDER NUMBER: 31640546 SR
 JOB NUMBER: 3100007
 ORDER DATE: 11/14/11
 P.O.#: C425R544
 REFERENCE#: 36644 SN 29821

REMIT TO

B/E AEROSPAC, INC.
 88269 EXPEDITE WAY
 CHICAGO IL 60695-0001
 United States