

1. Approving Competent Authority/Country CAA/UNITED KINGDOM		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number. 148055	
4. Organisation Name and Address. MUIRHEAD AEROSPACE LIMITED T/A MUIRHEAD AVIONICS Muirhead Aerospace Ltd 3 The Square Heathrow Southall Lane, Southall, Middlesex UB2 5NH UNITED KINGDOM		5. Work Order/Contract/Invoice Work Order No: GA12161 Customer Order No: W30265			
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	G6074 VHF COMM CONTROL PANEL	G6074-05	1	476	Repaired
12. Remarks 14 CFR 43.9 Return to Service The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. H9EY443N					
Manual ID: 23-11-05, Revision #: 7, Revision Date: 28/02/2003					
Repair report attached reference GA12161 TCCA Approval Ref: 807-07					
Date(m/d/y): Sep/30/2015 Signed: 					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation. ☐ non-approved design data specified in block 12					
14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.					
13b. Authorised Signature:		13c. Approval/Authorisation No.		14c. Certificate/Approval Ref No. UK.145.00592	
13d. Name		13e. Date (dd mmm yyyy)		14d. Date (dd mmm yyyy) 30 Sep 2015	
					
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

MUIRHEAD AVIONICS

Muirhead Aerospace Limited

Contact Name: Customer Services

Telephone: +44 (0)20 8571 3422

Fax: +44 (0)20 8571 2336

Tear Down/Inspection

Work Order #: GA12161

Date Printed: 14-Sep-15

Work Type: Repaired

Page: 1

To:

ATTN: ADAM DUMMER
AJ WALTER (AVIATION) LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD
WEST SUSSEX RH13 0SH

Ship To:

AJ WALTER (AVIATION) LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD
WEST SUSSEX, RH13 0SH UK

Cust.PO Ref.: W30265

Cust.Code: 200382

Cust.Phone:

Cust.Fax:

Cust.Email:

Station: SOUTH

Part No. In: G6074-05

Part No. Out: G6074-05

TSO: 0

TSN: 0

TSR: 0

Description: G6074 VHF COMM CONTROL PANEL

Serial No: 476

Qty: 1

Previous WO No:

Documentation: 23-11-05

ATA No: 23-11-05

Location: GABLES SHELF

Rev. & Date: 7 28-Feb-2003

CSO: 0

CSN: 0

CSR: 0

Symptoms:

REPORT

Visual inspection - Satisfactory

Functional test - Unsatisfactory
Fault confirmed

Unit inspected and tested - Unsatisfactory - Fault confirmed - When unit gets hot display fails - Display to be replaced - Replaced

Unit assembled and tested to full spec - Satisfactory

Unrelated to previous repair - Warranty denied -

PN	Description
245-0033	LCD

Qty Needed	CD
1	NE

Disposition
Consumable