

1. Approving Competent Authority/Country CAA/UNITED KINGDOM		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1				3. Form Tracking Number 64543	
4. Organisation Name and Address OAKENHURST AIRCRAFT SERVICES LTD Claydons Lane, Rayleigh, Essex SS6 7UP Tel: 44(0)1268 741622 Fax: 44(0)1268 741650 http://www.oakenhurst.com avionics@oakenhurst.com		Trading as OAKENHURST THE AVIONICS WORKSHOP				5. Work Order/Contract/Invoice 201369	
6. Item	7. Description	8. Part No	9. Qty	10. Serial No	11. Status/Work		
1	Telephone Handset LAST ITEM	89-01-07375	1	213309	Repaired		
12. Remarks IN ACCORDANCE WITH MANUFACTURERS MANUAL No 23-73-01 REVISION Rev. 14, 12 January 2012 A J WALTER (AVIATION) LTD THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD WEST SUSSEX RH13 0SH							
DETAILED WORK CONTENT IS HELD UNDER REFERENCE NUMBER INDICATED IN BOX 5							
The described maintenance has been performed in accordance with the applicable Canadian airworthiness requirements under our approval number T.C.C.A :807-10							
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ PART-145 A.50 Release to Service Certifies that unless otherwise specified in block 12 the work identified in block 11 and described in block 12, was accomplished in accordance with PART-145 and in respect to that work the items are considered ready for release to service		14b. Authorised Signature 		14c. Certificate / Approval Ref No. UK.145.00524	
13b. Authorised Signature		13c. Approval / Authorisation Number UK-21G.2368		14d. Name Stephen Labdon		14e. Date (dd/mm/yyyy) 10/Apr/2013	
13d. Name		13e. Date (dd/mm/yyyy)					

NOTE:

USER / INSTALLER RESPONSIBILITIES

1. This certificate does not automatically constitute authority to install the item(s).
2. Where the user/installer works in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1 it is essential that the user / installer ensures that his / her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.
3. Statements 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user / installer before the aircraft may be flown.

1. Approving Competent Authority/Country CAA/UNITED KINGDOM		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1				3. Form Tracking Number 64543	
4. Organisation Name and Address OAKENHURST AIRCRAFT SERVICES LTD Claydons Lane, Rayleigh, Essex SS6 7UP Tel: 44(0)1268 741622 Fax: 44(0)1268 741650 http://www.oakenhurst.com avionics@oakenhurst.com		Trading as OAKENHURST THE AVIONICS WORKSHOP				5. Work Order/Contract/Invoice 201369	
6. Item	7. Description	8. Part No	9. Qty	10. Serial No	11. Status/Work		
1	Telephone Handset LAST ITEM	89-01-07375	1	213309	Repaired		
12. Remarks IN ACCORDANCE WITH MANUFACTURERS MANUAL No 23-73-01 REVISION Rev. 14, 12 January 2012 A J WALTER (AVIATION) LTD THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD WEST SUSSEX RH13 0SH							
DETAILED WORK CONTENT IS HELD UNDER REFERENCE NUMBER INDICATED IN BOX 5							
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate No O5KY452Y							
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ PART-145 A.50 Release to Service Certifies that unless otherwise specified in block 12 the work identified in block 11 and described in block 12, was accomplished in accordance with PART-145 and in respect to that work the items are considered ready for release to service		14b. Authorised Signature 		14c. Certificate / Approval Ref No. UK.145.00524	
13b. Authorised Signature		13c. Approval / Authorisation Number UK-21G.2368		14d. Name Stephen Labdon		14e. Date (dd/mm/yyyy) 10/Apr/2013	
13d. Name		13e. Date (dd/mm/yyyy)					

NOTE:

USER / INSTALLER RESPONSIBILITIES

1. This certificate does not automatically constitute authority to install the item(s).
2. Where the user/installer works in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1 it is essential that the user / installer ensures that his / her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.
3. Statements 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user / installer before the aircraft may be flown.

The Avionics Workshop Shop Movement Order

Av

Job No: <u>AVW WKSP 64543</u> Description: <u>Telephone Handset</u> Part No: <u>89-01-07375</u> Serial No: <u>213309</u> Customer: <u>A J WALTER (AVIATION) LTD</u> Order No: <u>201369</u> Order Responsible Person: <u>CLARE CHEESMAN</u> Customs No: _____ Customs Date: _____ Tail No / Type: <u>OK-MEI</u> End Use No: <u>EU/0903/102/13 expiry 31st</u> Currency: <u>STERLING</u>	Date Received: <u>19 March 2013</u> Date Required: _____ Manufacturer: <u>Holmco</u> Mechanic: <u>David Burton</u> Manual Ref: <u>23-73-01</u> Manual Date: <u>Rev. 14, 12 January 2012</u> Date Completed: <u>10 April 2013</u> Despatch Note No: <u>77784</u>
--	--

Work Required: CAA: ☒ FAA: ☒ C of C: ☐ TCCA: ☒ Reported Defect: Warranty: ☐
 REPAIR UNDER T&M PLEASE QUOTE AND HOLD SEE REPAIR ORDER

Despatch: <u>A J WALTER AVIATION</u>	Customer Coding <u>B</u>
--	---------------------------------

Overhauled: ☐ Repaired: ☒ Inspected - Tested: ☐ Modified: ☐

Remarks: (EASA Form 1)

THE DESCRIBED MAINTENANCE HAS BEEN PERFORMED IN ACCORDANCE WITH THE APPLICABLE AIRWORTHINESS REQUIREMENTS UNDER OUR APPROVAL NUMBER T.C.C.A :807-10

Strip Report: **Warranty:** Accepted: ☐ Denied: ☐

UNIT RECEIVED IN AVERAGE CONDITION. INTERNAL INSPECTION AND FAULT DIAGNOSIS CHECKS CARRIED OUT, UNIT FOUND TO HAVE INOPERATIVE EARPHONE AS REPORTED. MICROPHONE AUDIO FOUND TO BE OUT OF MANUFACTURER'S SPECIFICATIONS. INSPECTION FOUND REMAINING PARTS TO BE IN GOOD ORDER. EARPHONE REPLACED. UNIT REASSEMBLED AND FULL FINAL TESTING CARRIED OUT IN ACCORDANCE WITH MANUFACTURER'S C.M.M. TESTING REVEALED P.C.B. TO HAVE DRY JOINTS CAUSING INTERMITTENT MICROPHONE OPERATION. MAIN P.C.B. REFLOWN. UNIT OPERATES CORRECTLY.

Mech Sig  **Insp**  **Date** 10 APR 2013

Q.C. Comments \ Investigation (if warranty claim)

Sig _____ **Insp** _____ **Date** _____

History Report

Part No 89-01-07375

Serial No 213309

Job No AVW WKSP 64543

Warranty No

Accepted No

Date Released 10 April 2013

Customer A J WALTER (AVIATION) LTD

Work Required

Tail No OK-MEI

Despatch Note No 77784

REPAIR UNDER T&M PLEASE QUOTE AND HOLD

Reported Defect

SEE REPAIR ORDER

Strip Report

UNIT RECEIVED IN AVERAGE CONDITION. INTERNAL INSPECTION AND FAULT DIAGNOSIS CHECKS CARRIED OUT, UNIT FOUND TO HAVE INOPERATIVE EARPHONE AS REPORTED. MICROPHONE AUDIO FOUND TO BE OUT OF MANUFACTURER'S SPECIFICATIONS. INSPECTION FOUND REMAINING PARTS TO BE IN GOOD ORDER. EARPHONE REPLACED. UNIT REASSEMBLED AND FULL FINAL TESTING CARRIED OUT IN ACCORDANCE WITH MANUFACTURER'S C.M.M. TESTING REVEALED P.C.B. TO HAVE DRY JOINTS CAUSING INTERMITTENT MICROPHONE OPERATION. MAIN P.C.B. REFLOWN. UNIT OPERATES CORRECTLY.
