			3. Form Tracking Number.
2.		CERTIFICATE	WO108809
Transport Canada	TORM ONE		
4. Organization Name and Address.			5. Work Order, Contract or Invoice Number:
AJW Technique Inc		A tachnique	T3/430-1
7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7	2	recilique	344
Canada		-	11. Status (Work:
6. Item: 7. Description:	8. Part Number:	9. Quantity: 10. Sellal/Datch remisco.	INSPECTED/TESTED
	9615325070		
12. REMARKS		S AND ATEC TEST PROGRAM 6-M12J REL.03.	
INSPECTED/TESTED SERVICEABLE PER CMM 31-63-36A REV.13 DATED JUNE 10, 2013 AND ATEC TEST TWO FOR MORE INFORMATION REFER TO THE TEAR DOWN REPORT.	M 31-63-36A REV.13 DATED JUNE 10, 2018 EAR DOWN REPORT.	SANDAIRCIRGITAGO	
		Maintenance perfo	EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17
13a. Certifies the items identified above were manufactured in conformity to:	ctured in conformity to:	14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation	in Block 12, the work identified in Block accordance with Canadian Aviation
Approved design data and are in a condition for safe operation	or safe operation.	Regulations.	
Non-approved design data specified in Block 12	12	X CAR 571.10 Maintenance Release	
		■ Other regulation specified in Block 12	
130	proceed Organization Number		14c. Approval Organization Number
13b. Signature:	13C. Approved Organization I variable		33-12
13d Name (Typed or Printed): 13e. Date	Date	14d. Name (Typed or Printed) 14	14e. Date (dd/mmm/yyyy)
		Stephane Hervieux	08-Jun-2021
	Installer Re	Installer Responsibilities	
This certificate does not constitute authority to install the part.	the part. gulations of a country other than specified in	This certificate does not constitute authority to install the part. This certificate does not constitute authority to install the part. This certificate does not constitute authority to install the part. The constitute authority to install the part. The constitute does not constitute authority to install the part.	rtifications from the
country specified. Statements in blocks 13a or 14a do not constitute installation of applicable national regulations before the aircraft may be flown.	stallation certification. In all cases,the technic ay be flown.	country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases,the technical record for the aircraft must contain an installation certification issued in accordance with the Statements in blocks 13a or 14a do not constitute installation certification. In all cases,the technical record for the aircraft may be flown. applicable national regulations before the aircraft may be flown.	ification issued in accordance with the

AJW TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO108809 Date Printed: 2021-06-08 Customer RO: T34430-1

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: DISPLAY MANAGEMENT COMPUTER

Phone: +44 1403 798000

P/N: 9615325070

Qty: 1

Email: daniel.smith@ajw-aviation.com

S/N: 998256006661

Mfg: THALES

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

CSO: N/A

CSR: N/A

P/N Out: 9615325070

Serial Out: 998256006661

Symptoms:

CODE:

REPAIR

DETAILS:

PLEASE QUOTE TO TEST AND RECERTIFY. PLEASE QUOTE TO REPAIR IF IT FAILS TEST.

REMOVE IN SERVICEABLE CONDITION FROM A/C REGN: B-MAO.

Faults:

CODE:

INITIAL TEST FAILURE

DETAILS:

On test on ATEC test station, no failure to report.

CODE: DETAILS: TEST AND RECERTIFY

Tested 2X without failure. Test & re-certification.

Corrective Actions:

CODE:

INSPECTED/ TESTED

DETAILS:

INSPECTED/TESTED SERVICEABLE PER CMM 31-63-36A REV.13 DATED JUNE 10, 2015 AND ATEC TEST PROGRAM

6-M12J REL.03.