	AAC-038 (12/94)		4451428 1打印的、 批准人姓名 (打印的)	Y	Certifies that the Part(s) identified above except as otherwise specified in block 13, was (were) manufactured/inspected in accordance with the airworthing regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.	级声明上述产品除第13项的其它规定以外,已按照国家适航条例进行制 适/检查,并且该产品(出口产品)符合经批准的型号设计资料和进口国提出的 专用要求	New Parts	REF HS PO TSN-12418	Remarks See app. tim	F号 7. 内容 Item Descr 1 ACTUATOR - COMPRESSOR			1. 国家 Country
			ams	18.	) identified above exceptantured/inspected in accountry and/or in the country and with the notificate	R定以外,已按照国家适航条例进 )符合经批准的型导设计资料和i		#980652952/PO R414403, .92 H, TSR-0 H , TSO- UNK,	See attached repair report fapplicable at time of work), time or cycles in service if	7. 内容 Description ACTUATOR - ASSY HIGH PRESSURE COMPRESSOR STATOR, SECONDARY	INC. D ST K, IL 61111-5808	Authorized	2. 中国民用航空总局 批准放
			08-26-2023	. 批准日期 Date	except as otherwise specified in the in accordance with the airworthiness the case of parts to be exported outified special requirements of	(行制 #口圍提出的		CSN-7070.00 C,		8. 件号 Part No. 1020927-1			航空总局 CAAC 日符合性 Conf 批准放行证书/话航批准标签
* * 0.	FO(	S III		19. 中I Is	n the iness	数声明上 进口国通 行使用。	15. 使 Us	CSR- 0 C, CSO- UNK,	Q	9. 适用性 Eligibility* NOT KNOWN		Certificat	Cormity
*麥園严品目录详细查找适用性 * Cross-check eligibility	F00100102			中国民航总局授权 Issued by or on behalf	Certifies that the work specifications was carried out in accordance country and the notified specification for the part sidered ready for release to s	兹声明上述产品除第13项的其它规定外,已按照上述国家适航条例和 进口国通知的特殊要求进行了工作,该产品处于安全可用状态可以批准放行使用。	使用过的产品 Used Parts	details held on	ng customer P.O.	10. 数量 Qty 1		Release Certificate/Airworthiness	区 适航性 Airworthiness
for more details with parts catalogue.				lf of the CAAC	Certifies that the work specified above except as otherwise specified in the block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)	已按照上述国家适航条例和 品处于安全可用状态可以批准放		WO A092735	No. if	11. 系列号/批号 Serial/Batch No LSGCAW1697	In		ess 3. 证书编号 Certificate
talogue.					specified in the block 13 ions of the stated ng country and in safe operation and con-					12. 产品状态 Status/Work REPAIRED	工作单/合同单/货单 Work Order/Contract/Invoice v. # 5950754	3549091-1	te Ref No

1. Approving Civil Aviation Authority/Country:		3. Form Tracking Number:
FAA/United States	FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	3549092-1
	74	5. Work Order/Contract/Invoice Number:
LOVE	5808	Inv 5950754 PO 980652952/PO R414403
1 Description:  ACTUATOR - ASSY HIGH PRESSURE	COMPRESSOR STATOR, SECONDARY 1020927-1 9. Quantity:	10. Serial Number: 11. Status/Work: REPAIRED
**************************************		
Part 145 and in respect the EASA Part 145 Approval National Work instruction, time and/or cycles in s	Approval Number: "EASA.145.5027". See attached repair report in instructions used, personnel performing the work, dates of cocycles in service (if reported), and customer purchase order not cycles in service (if reported), and customer purchase order not cycles in service (if reported), and customer purchase order not cycles in service (if reported).	out in accordance with EASA by for release to service under report for maintenance records, s of completion, parts replaced order number
1 ac #980 92 H	: 2022-05-19,Fu	ails held on WO A092735
<ol> <li>Certifies the items identified above were manufactured in conformity to:</li> </ol>	14a. 🗵 14 CFR 43.9 Return to Service	X Other regulation specified in Block 12
Approved design data and are in a condition for Non-approved design data specified in black 12	Certifies that unless of and described in Block Federal Regulations, p. return to service.	herwise specified in Block 12, the work identified in Block 11 12 was accomplished in accordance with Title 14, Code of art 43 and in respect to that work, the items are approved for
d. Name(Typed or Printed);	13c. Approval Authorization No. 14b. Authorized Signature:  13c. Danield minim very: 14d. Name(Typed or Printed):	14c. Approval/Certificate No: 4451428
t is important to understand that the existence	User/Installer Responsibilities  User/Installer Responsibilities	26/AUG/2023
Where the user/installer performs work in acclock 1, it is essential that the user/installer enpecified in block 1.	Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in plack 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country pecified in block 1.	nee propener/article.  hiness authority of the country specified in the airworthiness authority of the country
Statements in blocks 13a and 14a do not constitute installation certification. In the national regulations by the user/installer before the aircraft may be flown.	n all cases, aircraft maintenance recor	ds must contain an installation certification issued in accordance with
()	AI	NSN: 0052-00-012-9005

## REPAIR REPORT SHEET 1 OF 2

: LSGCAW1697 UNIT SERIAL NO : 1020927-1 UNIT ITEM NO RECVD ITEM NO : 1020927-1 SALES ORDER NO : 3883451 TIME SINCE REPORTED: NEW 12418.92

007 - DAMAGED IN FIELD

CUSTOMER : HAMILTON SUNDST - A1724629 WORK ORDER NO : A092735 CUSTOMER ORDER NO : 980652952/PO R414403

CYCLES SINCE: NEW 7070.00 OVERHAUL N/R
OVERHAUL N/R REPAIR N/R

F.A.A. TAG NO: 3549091-1,3549092-1 STOCK CODES

REASON CODES 004 - REPLACED AT DISASSEMBL 006 - MISSING FROM FIELD

006 - MISSING

N = NEW F = NEWDC = DEPT CHRG

WOODWARD, INC.

NE = EXCH/NEW

R = REPAIR RE = EXCHANGE

RK = NOT PICKED

ZZ = NOT PICKED

WORK SCOPE: REPAIR

DESCRIPTION OF REPAIR OR	GENERAL REMARKS:	19601 1980	
ESCRIPTION OF REFFINE SE		01-AUG-	202
DISASSEMBLED BY	: N. SALGADO		
FINAL TESTED BY	: M. PRUITT, A. BARRETT, N. SALGADO	11-AUG-	
	: N. SALGADO	01-AUG-	
AD RUCV IDDIED	3 (access 6)51	27-JUL-	
VISUAL AS RECV BY	: L. JONES	11-AUG-	202
ASSEMBLED BY	: A. BARRETT, N. SALGADO	25-AUG-	
HCC BY	: M. Holcomb		
OVERHAULED [ ] REPAIRED [X]	INSPECTED [ ] TESTED [ ]		
IN ACCORDANCE WITH CMP : 75-3	1-48 ISSUE: 4 DATED: 2022-05-19		
SB'S INCORPORATED: None Requi	red		
PCW: None Required			
AD's / CN's INCORPORATED: Nor	e Required		
REPORTED PROBLEM CONFIRMED.			

WOODWARD, INC.

## REPAIR REPORT SHEET 2 OF 2

UNIT ITEM NO

UNIT SERIAL NO : LSGCAW1697

: 1020927-1

RECVD ITEM NO : \_1020927-1

SALES ORDER NO : 3883451 TIME SINCE REPORTED: NEW 12418.92

F.A.A. TAG NO: 3549091-1, 3549092-1

CUSTOMER : <u>HAMILTON SUNDST - A1724</u>629

WORK ORDER NO : A092735

CUSTOMER ORDER NO: 980652952/PO R414403

CYCLES SINCE: NEW 7070.00 OVERHAUL N/R
OVERHAUL N/R REPAIR N/R

 O RING070 W. X .489 I	1	004	N	(420)	
 O RING078 W. X .468 I	2	004	N	HEAD/ROD PACKING	
STRAP-WIRE BUNDLE	1	004	N		
FITTING5625-18 UNION	2	007	N	HEAD/ROD FITTING	
 CAP5625-18 YELLOW PLA	2	006	N	(650)	
SEAL743 ID X .200 W R	1	004	N	(270)	
SEAL742 ID X .129 W R	2	004	N	(280)	
SEAL RING-2.152 OD (GRE	1	004	N		
BEARING291 W X 2.119	1	004	N	(380)	
PISTON-ASSY ACTUATOR HP	1	007	N		
O RING082 W. X .530 I	1	004	N	(410)	
O RING103 W X 1.925 I	2	004	N	(290)	
O RING103 W. X 1.174	1	004	N	(250)	
BEARING-1.1737 W. X 1.1	1	004	N		
CAP438-20 YELLOW PLAS	2	006	N	(660)	
CAP-YELLOW EP-12	1	006	N	(670)	
 PLUG250 OD X .225 EXP	1	004	N		
PLUG250 OD X .225 EXP	1	006	N		
CLEVIS500-20 THREADED	1	007	N		
FITTING4375-20 UNION	1	007	N	PD FITTING	
FITTING438-20 90DEGEL	1	007	N	ELBOW FITTING	
RING-BACK UP PER MS9058	1	004	N	ELBOW BACK UP RING	
KIT032 OD X 18 IN. SA	4	004	N		
O RING072 W. X .351 I	1	004	N	ELBOW PACKING	
O RING072 W. X .351 I	1	004	N	PD PACKING	

r	V	$\cap$	т	ρ	C	•	
Ţ	٦	U	ι	·	S		
_	_			_	_	_	

AIRWORTHINESS APPROVAL - DIRECT SHIPMENT AUTHORIZATION.