

1. Approving Competent Authority/Country  
CAA/UNITED KINGDOM

2.

4. Organisation Name and Address

OAKENHURST AIRCRAFT SERVICES LTD  
Claydons Lane, Rayleigh, Essex SS6 7UP  
Tel: 44(0)1268 741622 Fax: 44(0)1268 741650  
<http://www.oakenhurst.com> [avionics@oakenhurst.com](mailto:avionics@oakenhurst.com)

**AUTHORISED RELEASE CERTIFICATE**  
**EASA FORM 1**

Trading as

**OAKENHURST**  
THE AVIONICS WORKSHOP

3. Form Tracking Number  
**60846**

5. Work Order/Contract/Invoice

**W14489**

6. Item	7. Description	8. Part No	9. Qty	10. Serial No	11. Status/Work
1	Rapid Water Heater LAST ITEM	1010099-6.1	1	10.86-23	Inspected/Tested

12. Remarks  
**IN ACCORDANCE WITH MANUFACTURERS MANUAL No 25-30-31.  
REVISION Rev 2 17th February 2012**

**A J WALTER (AVIATION) LTD  
VISCOUNT HOUSE  
PARTRIDGE GREEN  
WEST SUSSEX  
RH13 8RA**

**DETAILED WORK CONTENT IS HELD UNDER REFERENCE NUMBER INDICATED IN BOX 5**

**THE DESCRIBED MAINTENANCE HAS BEEN PERFORMED IN ACCORDANCE WITH THE APPLICABLE AIRWORTHINESS REQUIREMENTS UNDER OUR APPROVAL NUMBER T.C.CA :807-10**

13a. Certifies that the items identified above were manufactured in conformity to:

- ☐ approved design data and are in a condition for safe operation  
☐ non-approved design data specified in block 12

14a. ☒ PART-145.A.50 Release to Service

☒ Other regulation specified in block 12

Certifies that unless otherwise specified in block 12 the work identified in block 11 and described in block 12, was accomplished in accordance with PART-145 and in respect to that work the items are considered ready for release to service

13b. Authorised Signature

13c. Approval / Authorisation Number

**UK.21G.2368**

14b. Authorised Signature

14d. Name

**Colin Juniper**

14c. Certificate / Approval Ref No.

**UK.145.00524**

13d. Name

13e. Date (dd/mm/yyyy)

14e. Date (dd/mm/yyyy)

**22/Aug/2012**

NOTE:

**USER / INSTALLER RESPONSIBILITIES**

1. This certificate does not automatically constitute authority to install the item(s).
2. Where the user/installer works in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1 it is essential that the user / installer ensures that his / her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.
3. Statements 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user / installer before the aircraft may be flown.



1. Approving National Aviation  
Authority/Country:  
FAA/UNITED STATES

2.

4. Approved Organisation Name and Address:

OAKENHURST AIRCRAFT SERVICES LTD  
Claydons Lane, Rayleigh, Essex SS6 7UP  
Tel: 44(0)1268 741622 Fax: 44(0)1268 741650  
<http://www.oakenhurst.com> [avionics@oakenhurst.com](mailto:avionics@oakenhurst.com)

Trading as

**OAKENHURST**  
THE AVIONICS WORKSHOP

3. Form Tracking Number:

60846

5. Work Order/Contract/Invoice Number:

W14489

6. Item:

7. Description:

8. Part Number:

9. Eligibility:\*

10. Quantity:

11. Serial/Batch Number:

12. Status/Work:

1

Rapid Water Heater  
LAST ITEM

1010099-6.1

N/A

1

10.86-23

Inspected

13. Remarks:

IN ACCORDANCE WITH MANUFACTURERS MANUAL No 25-30-31.  
REVISION Rev 2 17th February 2012

A J WALTER (AVIATION) LTD  
VISCOUNT HOUSE  
PARTRIDGE GREEN  
WEST SUSSEX  
RH13 8RA

DETAILED WORK CONTENT IS HELD UNDER REFERENCE NUMBER INDICATED IN BOX 5

14. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in condition for safe operation.  
☐ Non-approved design data specified in block 13.

15. Authorized Signature:

17. Name:

16. Approval / Authorization Number:

18. Date (m/d/y):

19. Authorized Signature:

22. Name:

20. Authorized Signature:

Colin Juniper

21. Approval/Certificate No:

23. Date (m/d/y):

Aug/22/2012

NOTE:

### USER / INSTALLER RESPONSIBILITIES

1. It is important to understand that the existence of this document alone does not automatically constitute authority to install the part / component / assembly.
2. Where the user/installer performs works in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user / installer ensures that his / her airworthiness authority accepts parts / assemblies from the airworthiness authority of the country specified in block 1.
3. Statements in blocks 14 and 19 do not constitute certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user / installer before the aircraft may be flown.

\* Installer must cross-check eligibility with applicable technical data



# The Avionics Workshop Shop Movement Order

<b>Job No:</b> <u>AVW WKSP 60846</u> <b>Description:</b> <u>Rapid Water Heater</u> <b>Part No:</b> <u>1010099-6.1</u> <b>Serial No:</b> <u>10.86-23</u> <b>Customer:</b> <u>A J WALTER (AVIATION) LTD</u> <b>Order No:</b> <u>W14489</u> <b>Order Responsible Person:</b> <u>JASON CARVER</u> <b>Customs No:</b> _____ <b>Customs Date:</b> _____ <b>Tail No / Type:</b> _____ <b>End Use No:</b> <u>EU/0903/102/13 expiry 31st</u> <b>Currency:</b> <u>STERLING</u>	<b>Date Received:</b> <u>07 August 2012</u> <b>Date Required:</b> _____ <b>Manufacturer:</b> <u>Driessen</u> <b>Mechanic:</b> <u>Lewis Cronk</u> <b>Manual Ref:</b> <u>25-30-31.</u> <b>Manual Date:</b> <u>Rev 2 17th February 2012</u> <b>Date Completed:</b> <u>22 August 2012</u> <b>Despatch Note No:</b> <u>72734</u>
---	--

**Work Required:** CAA: ☒ FAA: ☒ C of C: ☐ TCCA: ☒ Reported Defect: LEAKING FROM TAP Warranty: ☒  
 PLEASE REPAIR UNDER WARRANTY (REPAIR VENDOR)

<b>Despatch:</b> A J WALTER AVIATION	<b>Customer Coding</b> <u>B</u>
---	---------------------------------

Overhauled: ☐ Repaired: ☐ Inspected - Tested: ☒ Modified: ☐

**Remarks:** ( EASA Form 1/ FAA 8130-3 )

THE DESCRIBED MAINTENANCE HAS BEEN PERFORMED IN ACCORDANCE WITH THE APPLICABLE AIRWORTHINESS REQUIREMENTS UNDER OUR APPROVAL NUMBER T.C.C.A :807-10

**Strip Report:**

UNIT RECEIVED IN GOOD CONDITION. REPORTED DEFECT 'LEAKING FROM TAP' NOT CONFIRMED. UNIT THOROUGHLY TESTED AND INSPECTED FOR EXTENDED PERIODS OF TIME WITH NO FAULTS FOUND. UNIT FUNCTIONS CORRECTLY. WARRANTY DENIED.

Warranty: Accepted: ☐ Denied: ☒

Mech Sig [Signature]

Insp [Signature]



Date 23.8.12

Q.C. Comments \ Investigation ( if warranty claim )

Sig \_\_\_\_\_

Insp \_\_\_\_\_

Date \_\_\_\_\_



# History Report

**Part No** 1010099-6.1  
**Serial No** 10.86-23  
**Job No** AVW WKSP 60846  
**Date Released** 22 August 2012  
**Work Required** PLEASE REPAIR UNDER WARRANTY (REPAIR VENDOR)  
**Reported Defect** LEAKING FROM TAP  
**Warranty** Yes  
**Accepted** No  
**Customer** A J WALTER (AVIATION) LTD  
**Tail No**  
**Despatch Note No** 72734

## Strip Report

UNIT RECEIVED IN GOOD CONDITION. REPORTED DEFECT 'LEAKING FROM TAP' NOT CONFIRMED. UNIT THOROUGHLY TESTED AND INSPECTED FOR EXTENDED PERIODS OF TIME WITH NO FAULTS FOUND. UNIT FUNCTIONS CORRECTLY. WARRANTY DENIED.

**Job No** AVW WKSP 60135  
**Date Released** 03 July 2012  
**Work Required**  
**Reported Defect** LEAKING  
**Warranty** No  
**Accepted** No  
**Customer** A J WALTER (AVIATION) LTD  
**Tail No** LY-SKW  
**Despatch Note No** 71761  
PLEASE REPAIR UNDER T&M PLEASE QUOTE & HOLD-URGENT.

## Strip Report

UNIT RECEIVED IN AVERAGE CONDITION. REPORTED DEFECT CONFIRMED, UNIT FOUND TO LEAK FROM FAUCET. FAULT TRACED TO DAMAGED AERATOR. FURTHER INSPECTION REVEALED UNIT LEAKS FROM TANK LID DUE TO PERISHED SEALING WASHER. WHITE LAMP FAILS TO ILLUMINATE DUE TO U/S BULB. UNIT FOUND TO BE HEAVILY CONTAMINATED WITH LIMESCALE INTERNALLY AND EXTERNALLY. LAMP, BULB, WASHER AND AERATOR REPLACED, UNIT CLEANED, DE-SCALED AND TESTED TO MANUFACTURER'S SPECIFICATION, UNIT FUNCTIONS CORRECTLY. REPAIR CARRIED OUT.