



Commercial Aircraft
Products Group,
Royal Inventum Facility
Galvanibaan 5
3439 MG Nieuwegein
The Netherlands
Tel. +31(0)30 6029200
Fax +31(0)30 6036949

SHOPFI

Order details

Repair order: 37082229 Customer: SR TECHNICS UK LTD
Work order: 3536674 Purchase order: 61131882

Repair details

Complaint: :Fault: no heat

PARTNUMBER	SERIALNUMBER	
P/N in: 720737-50-43-00	S/N in: 1028	M
P/N out: 720737-50-43-00	S/N out: 1028	CT
Sub P/N in: 611993	S/N in: 2381	Re
Sub P/N out: 611993	S/N out: 2381	Sc
		M
		N

Shop findings

PARTNUMBER	(DESCRIPTION, DISCREPANCY, REASON - PERFORMED)
98000001	Order/environmental costs
239712	Component A
239713	Component B
239465	Door knob clockwise lock Discoloured due to ext
239542	Door seal In bad condition due to wear and tear. -
239694	Display protection plate Required due to a defect
239748	Quick fastener Is painted due to thick painting. -
239755	Front OCM Is painted due to thick painting. - Re
239762	Adjustment pin Deformed due to unclear reasons
239842	Sealing section In bad condition due to wear and
240158	Locking plate bottom Is painted due to thick pain
240159	Locking plate up Is painted due to thick painting.

Form: Department Phone #

PR-262-DOC-001 Repair station +31.(0).30.6029.280 Repair_Nieuwege

1. Approving Competent
Authority / Country
CAA The Netherlands

2.

AUTHORISED RELEASE CERTIFICATE / E

4. ORGANISATION

B/E AEROSPACE / INVENTUM

KONINKLIJKE FABRIEK INVENTUM B.V.
ROYAL INVENTUM COMPANY
Galvanibaan 5
3439 MG NIEUWEGEIN
THE NETHERLANDS

6. ITEM 7. DESCRIPTION

8. PART NO.

1. 00 DF1075 High speed oven LH 720737-50-43-00

13. REMARKS

IF TWO PARTNUMBERS PER
ORDERLINE ARE MENTIONED
IN BLOCK 8 THESE PARTS
ARE EQUIVALENT

Royal Inventum certifies that all work specified in block 12/13 was carried out in
that work the aircraft component is considered ready for release to service under E

14. Certifies that the items identified above were manufactured in conformity to:

- ☐ approved design data and are in condition for safe operation
- ☐ non-approved design data specified in block 13

15. Authorised Signature

16. Approval / Authorisation Number NL.21G.2150

17. Name

18. Date (D/M/Y)



Commercial Aircraft
Products Group,
Royal Inventum Facility
Galvanbaan 5
3439 MG Nieuwegein
The Netherlands
Tel. +31(0)30 6029200
Fax +31(0)30 6036949

SHOPFINDING REPORT

240791 Connector, cover Missing due to unclear reasons. - Added
241037 Sticker keyboard Required due to a defective part. - Replaced
430007039 Baffle plate Discoloured due to a defective part. - Replaced
439001137 Modification kit DF1000/1075 Requires modification due to a defective part. - Implemented
611438 Frame assy Is painted due to thick painting. - Replaced
612744 Door assy DF1000 LH Is painted due to thick painting. - Replaced

Remarks:

Modifications

SB-25-1107 Additional instructions for the 3-Phase Safety Device - Inspected
SB_1000-25-0001 IMPLEMENTATION OF IMPROVED POWER MODULE / MOTOR / FAN - Modified
SB_1000-25-0001 Implementation of improved power module/motor fan - Modified

Form:	Department	Phone #	Email:	Approved by	Page
PR-262-DOC-001	Repair station	+31.(0).30.6029.280	Repair_Nieuwegein@beaerospace.com	Date: 13 FEB 2009 Signature: [Signature] Q.C. Dept.: INVENTUM 010 Ac DEPT.	2 of 2