


1. Approving Competent Authority / Country CIVIL AVIATION AUTHORITY United Kingdom		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number BA30505577	
4. Organisation Name and Address  British Airways Ely Meadow, Talbot Green, Pontyclun, Cardiff CF72 8XL				5. Work Order/Contract/Invoice 4343755 U11984	
6. Item	7. Description	8. Part number	9. Qty	10. Serial No.	11. Status/Work
1.	ACTUATOR TEMP CONT VALVE	2022522-5	1	N/A  14/1/16	Repaired
12. REMARKS : Batch No 0005192460 SERIAL No 14116. PRE-TEST AND INSPECTION CARRIED OUT, UNIT WAS OPERATING BUT WAS NOISY AND SLOW DUE TO WORN MOTOR SPRING TENSION WASHER AND INCORRECT MOTOR SHIMMING. MOTOR REPAIRED, SPRING TENSION WASHER AND SHIMS RENEWED. TESTED TO SPEC I.A.W. ATA 21-51-22 (VEND REV 13). UNIT RELEASED UNDER TCCA APPROVAL No 808-04. U725640 30.03.2016 Original Manufacturer : HONEYWELL INT INC CMM:21-51-22-13					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12					
13b. Authorised Signature		13c. Approval/Authorisation Number		14a. ☒ PART-145.A.50 Release to service ☒ Other Regulation specified in block 12	
13d. Name		13e. Date(dd/mm/yyyy)		14b. Authorised Signature  14c. Certificate/Approval Ref. no. UK.145.00142	
USER/INSTALLER RESPONSIBILITIES		14d. Name U725640 Russell Williams BAAE 310 CRS		14e. Date(dd/mm/yyyy) 30.Mar.2016	
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

2. AUTHORISED RELEASE CERTIFICATE

EASA FORM 1

1. Approving Competent Authority / Country
CIVIL AVIATION AUTHORITY
United Kingdom

3. Form Tracking Number
BA30505577

4. Organisation Name and Address
British Airways Avionics Engineering.
Ely Meadow, Talbot Green,
Pontyclun, Cardiff CF72 8XL

5. Work Order/Contract/Invoice
4343755
U11984

BRITISH AIRWAYS

6. Item	7. Description	8. Part number	9. Qty	10. Serial No.	11. Status/Work
1.	ACTUATOR TEMP CONT VALVE	2022522-5	1	N/A 14116	Repaired

12. REMARKS : Batch No 0005192460

SERIAL No 14116. PRE-TEST AND INSPECTION CARRIED OUT, UNIT WAS OPERATING BUT WAS NOISY AND SLOW DUE TO WORN MOTOR SPRING TENSION WASHER AND INCORRECT MOTOR SHIMMING. MOTOR REPAIRED, SPRING TENSION WASHER AND SHIMS RENEWED. TESTED TO SPEC I.A.W. ATA 21-51-22 (VEND REV 13).
UNIT RELEASED UNDER TCCA APPROVAL NO 808-04.

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. BT7Y404J

U725640 30.03.2016 Original
Manufacturer : HONEYWELL INT INC CMM:21-51-22-13

13a. Certifies that the items identified above were manufactured in conformity to:

- ☐ approved design data and are in condition for safe operation
☐ non-approved design data specified in block 12

14a. ☒ PART-145.A.50 Release to service ☒ Other Regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with PART 145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature	13c. Approval/Authorisation Number
13d. Name	13e. Date (dd/mm/yyyy)

14b. Authorised Signature
14c. Certificate/Approval Ref. no.
UK.145.00142

14d. Name U725640
Russell Williams BAAE 310 CRS
14e. Date (dd/mm/yyyy) 30.Mar.2016

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Component Strip Report

Customer: AJW AVIATION

The Headquarters, Maydown Avenue
Slinfold, West Sussex
RH13 0AS

Part Number: 2022522-5:70210 Serial Number:
Description: ACTUATOR TEMP CONT VALVE
Repair Order Number: U11984 Order Number: 4343755
Equipment Number: Batch Number: 0005192460 Warranty Requested:

Customer WORK REQUIRED :

Date of Receipt: 14.03.2016
Reason for Removal:
Removal Code: W461 FO
Reason for removal: PLEASE TEST AND REPAIR.

Date Serviceable: 30.03.2016
SERIAL No 14116. PRE-TEST AND INSPECTION CARRIED OUT, UNIT WAS OPERATING
BUT WAS NOISY AND SLOW DUE TO WORN MOTOR SPRING TENSION WASHER AND
INCORRECT MOTOR SHIMMING. MOTOR REPAIRED, SPRING TENSION WASHER AND
SHIMS RENEWED. TESTED TO SPEC I.A.W. ATA 21-51-22 (VEND REV 13).
UNIT RELEASED UNDER TCCA APPROVAL No 808-04.

Warranty Decision:

Tested ☐	Repaired ☒	Overhauled ☐	Inspected ☐
Re-manufactured ☐	New ☐	Modified ☐	

Certification Number: BA000030505577