Combined Inventory Receipt & Dispatch Check Sheet

THIS DOCUMENT MAY <u>ONLY</u> BE COMPLETED BY A PERSON THAT HAS RECEIVED TRAINING AND BEEN ISSUED WITH AN INSPECTORS STAMP



B&H Warehouse Reference	Received Date	Boxtop Job Number
W120 79	8/24/15	

A visual inspection has been performed on this unit and the following information checked: Päperwork Check √ if on RECEIPT if on DISPATCH Original Release Documents Trace Documentation X OEM Certification X DG Declaration K MSDS (Material Safety Data Sheet) X Shelf Life Applicable K Material Certification / ATA 106 4 X US (unserviceable) Tag X Reason for Removal Stated on Tag Packing Slip Original Certificates Returned **Unused Statement** RECEIPT DISPATCH Physical Checks to be completed √ ves / × no √ ves / × no Part Number on Unit Matches Paperwork Serial Number on Unit Matches Paperwork Description on Unit Matches Paperwork All Paperwork carries the same part & serial number Blanks fitted to ALL ports FOD evident in ports / connectors Static Sensitive Warranty labels INTACT Following MUST be completed on Receipt AND dispatch √ if on <u>RECEIPT</u> √ if on DISPATCH Interior packaging sufficient to secure unit and weight of unit Component wrapped in static sensitive bubble / pouch Exterior packing condition acceptable for weight of unit Photos Taken - Package Exterior Photos Taken - Item and packaging Photos Taken - Component(s) Photos Taken - Data Plates and Connectors OnTrack Updated Other (Specify) Customer advised / pre-alert sent Completed by (Trained Inspector Stamp) 9388M



PRECISION AERO TECHNOLOGY

3333 EAST SPRING STREET

LONG BEACH CA 90806-6826

P-562-595-6055

UNITED STATES F-562-595-8416

TAITACTOR

COMMERCIAL INVOICE		
Cust P.O. R271169	Work Order: 8118182	Pg:1/1
For:	Ship To:	
AJ WALTER AVIATION LTD THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM Tel.: 1-403-711777 Fax: -1-403-710936	B&H WORLDWIDE INC 8000 NW 25TH STREET SUITE 300 DORAL, FL 33122 USA Tel.: 1 305 471 0444	
Your P.O. No. : R271169	Technician : NOEL NUCUM	
PartNumber : D92550032002	Inspector : PETER SAXEN	
Description : REFUEL PANEL ASSY	Aircraft Number : OE-IDU	
Serial No. : AF4100		
Qty : 1 UM : EA		
Cond : RP		
Order Date : Aug-11-2015	Ship Via : FEDEX STD	O/M D/D
S.O. No. :8124790 Line No.:1	Ship Via : FEDEX STD Incoterms : FOB ORIGIN	
Terms ; NET 30	micoternia 11 OD OMON	<u> </u>
Estimated Lead Time:	1 Days	· · · · · · · · · · · · · · · · · · ·
Our Contact : Linda Rubio Email: LRubio@pat-pag.com		
Work Requested: REPAIR		
Charges & Description	Quantity Cond Unit Price UM	Ext. Price
PARTS & MATERIALS [(I) Installed, (E) Exchanged, (R) Removed, (S) Scrapped		Ext. 1 noc
(I) [1] 387 LAMP, 28V AC/DC	1 EA NE	
LANII , 200 AOIDO		\$ 6.00
		ψ 0.00
Labor		\$ 875.00
Miscellaneous		\$ 15.00
S/N: AF4100 SCHEDULE B: 8803300010 ECCN: 7A994 NLR(No License Required)		Ψ 10.00
	Sub Total:	\$ 896.00
Please remit payment by wire transfer: Fifth Third Bank - 38 Fountain Square Plaza, Cincinnati, OH 45263 Account # 7460494169, S.W.I.F.T: FTBCUS3C		
THESE COMMODITIES, TECHNOLOGY OR SOFTWARE WERE EXPORTED FROM THE UNI- ACCORDANCE WITH THE EXPORT ADMINISTRATION REGULATIONS. DIVERSION CONTR- LAW PROHIBITED.	TED STATES IN LARRY TO US	
DECLARE ALL THE INFORMATION CONTAINED IN THIS INVOICE TO BE TRUE AND CORF		
SIGNATURE OF EXPORTER DATE,	Total: [USD]	^ \$896.00

dopyright (c) PENTAGON 2000 Software, Inc.

ORIGIN ID:LGBA (562) 595-6 SORIYA KHIEV PRECISION AERO TECHNOLOGY 3333 E. SPRING STREET #300 (562) 595-6055

LONG BEACH, CA 908062448 UNITED STATES US

SHIP DATE: 21AUG15 ACTWGT: 3.8 LB CAD: 732758/CAFE2807 DIMS: 12x10x10 IN BILL RECIPIENT

TO

12x11x11 8000 NW 25TH STREET 2/1 SULTE 300 DORAL FL 33122 (130) 547-1044 PO: R271169 **B&H WO/RLDWIDE INC**



FedEx Express

TRK# 6370 0558 9060

MON - 24 AUG AA STANDARD OVERNIGHT

Part # 156148-434 RIT2.01/15

33122 FL-US



 Approving Civil Aviation 6. Item: FAA/UNITED STATES the [product/article] is considered ready for release to service under EASA Part 145 Approval No. Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Organization 12. Remarks: Referencing manual No. 28-25-55 Revision: 17 Revision Date: JAN 01 2013 Name and Address: Full details of work carried out are in the work order number found in Block 5. Authority/Country: Description: REFUEL PANEL ASSY PRECISION AERO TECHNOLOGY 3333 EAST SPRING STREET LONG BEACH, CA 90806-6826 UNITED STATES AUTHORIZED RELEASE CERTIFICATE Part Number: FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG I Sig. Ayelexay ilise. idane ((elevamental/yyyyy) D92550032002 User/Installer Responsibilities 14a. X 14d. Name (Typed or Printed): 14b. Authorized Signature: FAA Certificate: DQ3R458L Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. 9. Quantity: 14 CFR 43.9 Return to Service EA Peter Saxen 10. Serial Number: AF4100 × EASA.145.4052 Work Order/Contract/Invoice Number: Form Tracking Number: Other regulation specified in Block 12 14c. Approval/Certificate No.: 14e. Date (dd/mmm/yyyy): 11. Status/Work 8118182 R271169 21 Aug 2015 DQ3R458L REPAIRED

FAA Form 8130-3 (02-14)

national regulations by the user/installer before the aircraft may be flown.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the

Block I, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in



PRECISION AERO TECHNOLOGY

3333 EAST SPRING STREET LONG BEACH CA 90806-6826

LONG BEACH CA 90806-68. UNITED STATES

P-562-595-6055

F-562-595-8416

Technician NOEL NUCUM NOEL NUCUM NOTE NOT	Close	:		_	Incoterms : Accou	ınt No. [A1	4148]
Coust P.O.	Normal Technician Inspector	NOEL NUC PETER SA			THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUS UNITED KINGDOM Tel.: 1-403-711777	3	AS
Dur Ref : LINDA Desc : REFUEL PANEL ASSY Trace To : Stock : S/N : AF4100 Tag Date : Shop : DIVISION 1 MFG : Manual : 28-25-55 Varr Claim : No Qty : 1 Cond As: RP Revision : 17 / Jan-01-2013 Completed P/N : D92550032002 S/N As : AF4100 Into Bin Loc : Company : 8 Division : Department : Order Date : Aug-11-2015 Received Date: Aug-11-2015 Due Date : Aug-16-2015 Print Date : Aug-21-2015 WORK GRDER No. 8118182 Reported By Customer PLEASE TEST. Preliminary Insp. RECEIVED UNIT VERY DIRTY AND FOUND LAMPS FAULTY. Corrective Action CLEANED AND INSPECTED UNIT. REPLACED ALL LAMPS. PERFORMED DETAILED FUNCTIONAL TESTS I.A.W. CMM 28-25-55. Wo's and S/B's							
Dur Ref : LINDA Desc : REFUEL PANEL ASSY Trace To : Stock : S/N : AF4100 Tag Date : Shop : DIVISION 1 MFG : Manual : 28-25-55 Varr Claim : No Qty : 1 Cond As: RP Revision : 17 / Jan-01-2013 Completed P/N : D92550032002 S/N As : AF4100 Into Bin Loc : Company : 8 Division : Department : Drder Date : Aug-11-2015 Received Date: Aug-11-2015 Due Date : Aug-16-2015 Print Date : Aug-21-2015 WORK ORDER NO 8118182 Reported By Customer PLEASE TEST. Preliminary Insp. RECEIVED UNIT VERY DIRTY AND FOUND LAMPS FAULTY. Corrective Action CLEANED AND INSPECTED UNIT. REPLACED ALL LAMPS. PERFORMED DETAILED FUNCTIONAL TESTS I.A.W. CMM 28-25-55. W/D's and S/B's		:R271169				Note	:
Stock : S/N : AF4100 Tag Date : Shop : DIVISION 1 MFG : Manual : 28-25-55 Warr Claim : No Qty : 1 Cond As: RP Revision : 17 / Jan-01-2013 Completed P/N: D92550032002 S/N As : AF4100 Into Bin Loc : Company : 8 Division : Department : Drder Date : Aug-11-2015 Received Date: Aug-11-2015 Due Date : Aug-16-2015 Print Date : Aug-21-2015 WORK ORDER No. 8118182 Reported By Customer PLEASE TEST. Preliminary Insp. RECEIVED UNIT VERY DIRTY AND FOUND LAMPS FAULTY. Corrective Action CLEANED AND INSPECTED UNIT. REPLACED ALL LAMPS, PERFORMED DETAILED FUNCTIONAL TESTS I.A.W. CMM 28-25-55. A/D's and S/B's	Our Ref		D	esc: REFUEL PANE			
Warr Claim : No Qty : 1 Cond As:RP Revision : 17 / Jan-01-2013 Completed P/N: D92550032002 S/N As : AF4100 Into Bin Loc : Company : 8 Division : Department : Order Date : Aug-11-2015 Received Date: Aug-11-2015 Due Date : Aug-16-2015 Print Date : Aug-21-2015						Tag Date	=
Completed P/N: D92550032002 S/N As: AF4100 Into Bin Loc: Company: 8							
Company :8 Division : Department : Order Date : Aug-11-2015 Received Date: Aug-11-2015 Due Date : Aug-16-2015 Print Date : Aug-21-2015 WORK ORDER NO 8118182 Reported By Customer PLEASE TEST. Preliminary Insp. RECEIVED UNIT VERY DIRTY AND FOUND LAMPS FAULTY. Corrective Action CLEANED AND INSPECTED UNIT. REPLACED ALL LAMPS. PERFORMED DETAILED FUNCTIONAL TESTS I.A.W. CMM 28-25-55. A/D's and S/B's					Cond As: RP	Revision	: 17 / Jan-01-2013
Corrective Action CLEANED AND INSPECTED UNIT. REPLACED ALL LAMPS, PERFORMED DETAILED FUNCTIONAL ESTS I.A.W. CMM 28-25-55, WORK ORDER No. 3118182 Print Date : Aug-16-2015 Print Date : Aug-21-2015 Due Date : Aug-16-2015 Print Date : Aug-16-2015 Due Date : Aug-16-2015 Print Date : Aug-18-2015 Print Date : Aug-16-2015 Print Date : Aug-16-2015 Print Date : Aug-16-2015 Print Date : Aug-18-2015 Print Date : Aug-16-2015 Print Date : Aug-18-2015 Print D				/N As : AF4100		into Bin Lo	oc:
WORK ORDER No. 8118182 Reported By Customer PLEASE TEST. Preliminary Insp. RECEIVED UNIT VERY DIRTY AND FOUND LAMPS FAULTY. Corrective Action PLEANED AND INSPECTED UNIT. REPLACED ALL LAMPS. PERFORMED DETAILED FUNCTIONAL TESTS I.A.W. CMM 28-25-55. AD's and S/B's					· _ 		
Reported By Customer PLEASE TEST. Preliminary Insp. RECEIVED UNIT VERY DIRTY AND FOUND LAMPS FAULTY. Corrective Action CLEANED AND INSPECTED UNIT. REPLACED ALL LAMPS. PERFORMED DETAILED FUNCTIONAL TESTS I.A.W. CMM 28-25-55. VD's and S/B's	Order Date	: Aug-11-2015					Print Date : Aug-21-2015
Reported By Customer PLEASE TEST. Preliminary Insp. RECEIVED UNIT VERY DIRTY AND FOUND LAMPS FAULTY. Corrective Action CLEANED AND INSPECTED UNIT. REPLACED ALL LAMPS. PERFORMED DETAILED FUNCTIONAL RESTS I.A.W. CMM 28-25-55. (ID) S and S/B'S			e i ragi artisat y republike para te sept Bere i transporte e i ragioni i ragioni Bere i transporte e i ragioni i ragioni i ragioni	WORK ORDE	R No 8118182	The Tell Miles.	Magnetic Control of Control of the second of
		<u> </u>				** ***	

Authorized Signature :

Copyright (c) PENTAGON 2000 Software, Inc.

















