

1. Approving Competent Authority / Country LUFTFAHRT-BUNDESAMT Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1			3. Form Tracking Number DB 90637076 1/1	
4. Organisation Name and Address: AIRBUS AIRBUS Operations GmbH Lüneburger Schanze 30 21614 Buxtehude, Germany				5. Work Order/Contract/Invoice R347120		
6. Item	7. Description	8. Part No.	9. Qty	10. Serial-No.	11. Status/Work	
N/A	FAP	Z131H0711115	1	131H04000514	MODIFIED	
12. Remarks: see Maintenance Report No.1045890 Work performed as per: C.M.M. 23-74-17 Rev.05 Jul-18-2017, C.M.M. 23-74-18 Rev.10 Nov-21-2017 and ECN Z131H0711115 amd.:A, iss.:A. work accomplished: NOV-07-2018 Amendment:A						
The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. K30Y905Y.						
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12			14a. ☒ Part-145.A.50 Release to Service ☒ Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.			
13b. Authorised Signature:			14b. Authorised Signature: 			
13c. Approval/Authorisation Number:			14c. Certificate/Approval Ref.No.: DE.145.0286			
13d. Name:			14d. Name: Mäckelmann			
13e. Date (dd/mm/yyyy):			14e. Date (dd/mm/yyyy): 08.Nov.2018			
USER / INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

MAINTENANCE ORDER		V Activity Category		1045890 Maintenance Number		 FSCM C9072	
Customer AJW	Part Number Z131H0411115			Serial No SPEC2000 131H04000514		Amd.	
	Description CIDS FWD.ATTND.PNL.			Quantity 1		Repair Station BUX	
Customer Order R347120		Cust. Order Date 24.09.2018		Work Order 1045890		Work Order Date 01.10.2018	
Prio ROUTINE							
Required Activities:	Test X	Repair X	Modify X	Inspection X	Scrap	Overhaul	Entry Date 01.10.2018
Redelivery Date 08.10.2018							
Reason for Return SOME AREA NOT SHOW ON DISPLAY SCREEN Mod. to Z131H0711115 amd.:A for new LCD.							
Operator UKN	Removal Date 21.08.2018	AC-Reg TC-OCF	AC Type A330	Station UKN	Release Certificate EASA DUALFAA	Warranty	Chargeable X
	Operators Man		OEM-Man O.E.M.-M		Aviation Device YES		Package OK
Administrator: Sell		Department: ECYS1			Phone: 040 743 51261		

MAINTENANCE REPORT	Preliminary Inspection/HDI	Pre- Strip-Test YES	Cond. elec. BAD	Cond. SW OK	Cond. mech. OK	BITE N/A
	Status of Removal Confirmed Removal		Tech. warranty YES		Missing Part NO	

Findings:
**The LC display was defective (some area show no display screen).
 The panel light test was faulty, because IC10 on LAMM-Board was defective.
 New spareparts for the LC display were no longer available.
 A modification to the new PNR Z131H0711115 amd.:A. is the repairsolution.
 The unit had some small scratches with no effect on further function.**

Remarks:
**Work performed as per: C.M.M. 23-74-17 Rev.05 Jul-18-2017,
 C.M.M. 23-74-18 Rev.10 Nov-21-2017 and ECN Z131H0711115 amd.:A, iss.:A.**

Work performed: **Preliminary- and hidden damage inspection performed.
 IC10 on LAMM board PCB changed.
 Unit modified to PNR: Z131H0711115 amd.:A, new name: "FAP".
 Acceptance test successfully performed.
 New PIM: PNR:Z141H0340110, AMD:A, SNR:141H03001111, (DB 90637010 1/1).
 Scrapped PIM panel: PNR:Z141H0240110, AMD: - , SNR:00537.**



Final Condition	PN_After Z131H0711115			SN_After 131H04000514			AMD_After A
	Tested X	Repaired X	Modified X	Modified internal	Cond as is	Scrapped	Overhauled
	Warranty_Charge_WC C			NFF		QA-Inspected 08. Nov. 2018	
Work performed staff Sperhake		Work performed department ECYS3		Work performed date 07.11.2018			