



61930999

1. Approving Competent Authority / Country LBA / Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 21703787 00000001	
4. Organisation Name and Address: Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany				5. Work Order/Contract/Invoice 61930999	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work
01	PANEL AY LIGHT CONTROL		1	D01830	REPAIRED
12. Remarks A.J. Walter (Aviation) Ltd. R404750 ATA 3111 TPR MK-No. 20 Pack Code 00 Resp. Workshop 33422031 Workshop Station HAM305 Opr. Hours Cycle Opr. Day TT UNKNOWN UNKNOWN UNKNOWN TSO UNKNOWN UNKNOWN UNKNOWN TSC UNKNOWN UNKNOWN UNKNOWN TSF 0 0 0 TASK PERFORMED IN ACCORDANCE WITH CMM 33-11-13 REV. 11 / CMDS 33-11-13 ISSUE 006					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12					
13b. Authorised Signature		13c. Approval / Authorisation Number		14a. ☒ Part-145.A.50 Release to Service ☒ Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work the items are considered ready for release to service.	
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorised Signature 424422  14d. Name Christian Zitzke	
				14c. Certificate / Approval Ref. Number DE.145.0001	
				14e. Date (dd mmm yyyy) 17 Feb 2023	


EASA FORM 1 - Issue 3

USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



61930999

1. Approving Competent Authority / Country CAA UK		AUTHORISED RELEASE CERTIFICATE CAA FORM 1				3. Form Tracking Number 21703787 000000001																				
4. Organisation Name and Address  Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany		8. Part No. 233T4244-303		9. Qty. 1	10. Serial No. D01830	11. Status / Work REPAIRED																				
6. Item 01		7. Description PANEL AY LIGHT CONTROL		5. Work Order / Contract / Invoice 61930999																						
12. Remarks ATA 3111 TP R MK-No. 20 Pack Code 00 Resp. Workshop 33422031 Workshop Station HAM305																										
A.J. Walter (Aviation) Ltd. R404750 <table><thead><tr><th></th><th>Opr. Hours</th><th>Cycle</th><th>Opr. Day</th></tr></thead><tbody><tr><td>TT</td><td>UNKNOWN</td><td>UNKNOWN</td><td></td></tr><tr><td>TSO</td><td>UNKNOWN</td><td>UNKNOWN</td><td></td></tr><tr><td>TSC</td><td>UNKNOWN</td><td>UNKNOWN</td><td>UNKNOWN</td></tr><tr><td>TSF</td><td>0</td><td>0</td><td>0</td></tr></tbody></table> TASK PERFORMED IN ACCORDANCE WITH CMM 33-11-13 REV. 11 / CMDS 33-11-13 ISSUE 006								Opr. Hours	Cycle	Opr. Day	TT	UNKNOWN	UNKNOWN		TSO	UNKNOWN	UNKNOWN		TSC	UNKNOWN	UNKNOWN	UNKNOWN	TSF	0	0	0
	Opr. Hours	Cycle	Opr. Day																							
TT	UNKNOWN	UNKNOWN																								
TSO	UNKNOWN	UNKNOWN																								
TSC	UNKNOWN	UNKNOWN	UNKNOWN																							
TSF	0	0	0																							
☒ Further details of work performed are attached either in a Workshop Report reference number, see block 3 and 5 or in other applicable documents.																										
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ Part -145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.																								
13b. Authorised Signature		13c. Approval / Authorisation Number		14b. Authorised Signature 424422 <i>Christian Zitzke</i>																						
13d. Name		13e. Date (dd mmm yyyy)		14c. Certificate / Approval Ref. Number UK.145.01408																						
				14d. Name Christian Zitzke																						
				14e. Date (dd mmm yyyy) 17 Feb 2023																						

USER / INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Workshop Report

Customer Order No. R404750	 Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany	61930999 Certificate Ref. No. 21703787 00000001
Part No. as received 233T4244-303	Serial No. as received D01830	Work Order/Contract/Invoice 61930999
Part No. as dispatched 233T4244-303	Serial No. as dispatched D01830	Description PANEL AY LIGHT CONTROL
Reason for removal RFR: OBSERVER MAP LIGHT OUT OF ORDER/FAILED		Responsible Workshop 33422031
Findings Reason of removal confirmed. R1 push/pull switch inoperative.		Modification Status according to Mod-Label
Action Inspected, repaired and tested Lighting Control Panel Assembly. Replaced Rheostat R1. Passed functional test IAW CMM. Outgoing condition: Unit shows wear and tear in area LIGHTING PANEL R2 Knob in form of two paint blemishes. These are cosmetic issues only. Form, fit and function are not affected.		See Unit Mod-Label if equipped
The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.		Name 424422, Christian Zitzke
		Date (dd mmm yyyy) 17 Feb 2023

RFID-Smartlabel

61930999



Ident-Tag Barcode

Ident-Tag**Lufthansa Technik**Form Tracking Number
21703787 00000001

Work Order / Contract / Invoice

Description
PANEL AY LIGHT CONTROLPart. No.
233T4244-303

Eligibility

Quantity
1Status / Work
REPAIREDSerial-/Batch No.
D01830

Remarks

TP R MK-No. 20
FSCM 89954 ATA

Resp. Workshop 33422031 Workshop Station HAM305

Packaging Code: 00

Installed on (Information is only required in case of installation only)

PNR NHA

SNR NHA

Position/FIN No. NHA

Station

A/C-Registration

RemovedPNR¹SNR¹Position/FIN No.¹Station¹A/C-Registration¹

Unit Barcode No.

Removed from NHA (Information is only required in case of part change on next higher assy)

PNR NHA

SNR NHA

Position/FIN No. NHA

Reason for Removal¹☐ 22 UnscheduledComplaint No.¹ or WO-Reference¹☐ 11 ScheduledFailure Description¹ (Please write in capital letters only)CCI-ID²Stamp or ID Number + Signature^{1/2}Date¹Special Investigation Tag exists ☐ Yes**Please send back to:**(unless other return location is agreed)LUFTHANSA TECHNIK AG
c/o Lufthansa Technik Logistik Services GmbH
Warenannahme / Goods Receiving
Weg beim Jaeger 193
22335 HAMBURG-FUHLSEBUETTTEL
Deutschland

(LTLS-Information: Use this box for ZID)

¹ Mandatory entries without using CCI-Mask² Mandatory entries using CCI-Mask