



1. APPROVING COMPETENT AUTHORITY/COUNTRY CAA/UK		2. AUTHORISED RELEASE CERTIFICATE CAA FORM 1			3. FORM TRACKING NUMBER MR/MD00074	
4. ORGANISATION NAME AND ADDRESS:  Triumph Aerospace Operations UK, Ltd. t/a Triumph Integrated Systems-Fluid Power & Actuation Meteor Business Park Cheltenham Road East GLOUCESTER GL2 9QL UNITED KINGDOM		5. Work Order / Contract / Invoice Customer PO : W48648 SRO : S000003345				
6. ITEM	7. DESCRIPTION	8. PART NO.	9. QTY	10. SERIAL NO.	11. STATUS/WORK	
1	MLG DOOR ACTUATOR	114122015	1.00	TA1812625	REPAIRED	
12. REMARKS: Unit Repair IAW CMM 32-31-35 Rev. 24. inline with EI 122207 Iss. 02. TSN: Unknown		The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under FAA certificate no. 715Y200D				
13a. Certifies that the items identified above were manufactured in conformity to: approved design data and are in a condition for safe operation non-approved design data specified in block 12 14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service						
13b. Authorised Signature	13c. Approval/Authorisation Number : UK.21G.2691	14b. Authorised Signature 		14c. Certificate/Approval Ref No UK.145.01375		
13d. Name	13e. Date :	14d. Name COGDON		14e. Date (dd mmm yyyy) 18 MAY 2021		
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certifications. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown						

1. APPROVING COMPETENT AUTHORITY/COUNTRY EASA		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1			3. FORM TRACKING NUMBER MR/ME00074	
4. ORGANISATION NAME AND ADDRESS:  Triumph Aerospace Operations UK, Ltd. t/a Triumph Integrated Systems-Fluid Power & Actuation Meteor Business Park Cheltenham Road East GLOUCESTER GL2 9QL UNITED KINGDOM		5. Work Order / Contract / Invoice Customer PO : W48648 SRO : S000003345				
6. ITEM	7. DESCRIPTION	8. PART NO.	9. QTY	10. SERIAL NO.	11. STATUS/WORK	
1	MLG DOOR ACTUATOR	114122015	1.00	TA1812625	REPAIRED	
12. REMARKS: Unit Repair IAW CMM 32-31-35 Rev. 24. inline with EI 122207 Iss. 02. TSN: Unknown						
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12 14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service						
13b. Authorised Signature		13c. Approval/Authorisation Number : UK.21G.2691		14b. Authorised Signature		14c. Certificate/Approval Ref No UK.145.01375
13d. Name		13e. Date (dd mmm yyyy)		14d. Name		14e. Date (dd mmm yyyy) 18 MAY 2021
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certifications. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown						

Workshop Report

Customer Order No. W48648	Description MLG DOOR ACTUATOR	 Triumph Triumph Integrated Systems - Actuation & Control, Meteor Business Park, Gloucester, GL2 9QL
Part No. As Received 114122015	Serial No. As Received TA1812625	
Part No. As Despatched 114122015	Serial No. As Despatched TA1812625	SRO S000003345
Teardown Report: TAR IAW CMM 32-31-35 REV 24 Unit Failed extend length. Strip IAW CMM 32-31-35 REV 24 Assessed IAW CMM 32-31-35 REV 24 Bearing rotation found within housings, bonding plate damaged, eye end inner bearing housing dimensions out of limits. Bearings, Eye End fitting and bonding plate to be replaced.		
Modification Status REPAIRED		
Name C OGDON	Signed 	Date 18 MAY 2021