

1. Approving Competent Authority / Country LUFTFAHRT-BUNDESAMT Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number DB 90489218 1/1	
4. Organisation Name and Address: AIRBUS AIRBUS Operations GmbH Cabin Electronics Lüneburger Schanze 30 21614 Buxtehude, Germany				5. Work Order/Contract/Invoice R278818	
6. Item	7. Description	8. Part No.	9. Qty	10. Serial-No.	11. Status/Work
N/A	FLIGHT ATTND PANEL	Z133H031951A	1	133H03000462	INSPECTED TESTED
12. Remarks: see Maintenance Report No.1027869 Work performed as per: CMM 23-77-12 Rev. 12 MAR-17-2015. work accomplished: DEC-18-2015 Amendment:A,1 The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. K30Y905Y.					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ Part-145.A.50 Release to Service ☒ Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.			
13b. Authorised Signature:		13c. Approval/Authorisation Number:		14c. Certificate/Approval Ref.No.: DE.145.0286	
13d. Name:		13d. Date (dd/mm/yyyy):		14d. Name: Straub 14e. Date (dd/mm/yyyy): 22.Dec.2015	
USER / INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1 国家 Country China		2. 中国民用航空总局 CAAC ☐ 符合性 Conformity ☒ 适航性 Airworthiness 批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG		3 证书编号 Certificate Ref. No. DB 90489214	
4 单位 Organization 		AIRBUS Operations GmbH Cabin Electronics Lüneburger Schanze 30 21614 Buxtehude, Germany		5 工作单/合同单/货单 Work Order/Contract/Invoice R278818	
6 序号 Item		7 内容 Description		8 件号 Part No.	
0001		FLIGHT ATTND PANEL		Z133H031951A	
		9 适用性 Eligibility		A319	
		10 数量 Qty		1	
		11 系列号/批号 Serial/Batch No.		133H03000462	
		12 产品状态 Status/Work		INSPECTED TESTED	
13 备注 Remarks see Maintenance Report No.1027869 Work performed as per: CMM 23-77-12 Rev. 12 MAR-17-2015. work accomplished: DEC-18-2015 Amendment:A.1					
14 新产品 New Parts 兹声明上述产品除第13项的其它规定以外, 已按照上述国家适航条例进行制造/检查, 并且该 产品(出口产品)符合经批准的型号设计资料和进口国提出的专用要求。 Certifies that the Part(s) identified above except as otherwise specified in block 13 was(were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.					
16 批准人签名 Signature		18 批准日期 Date		22.Dec.2015	
17 批准人姓名(打印的) Name(Printed)		Straub DA_K_6			
19 中国民航总局授权 Issued by or on behalf of the CAAC				F049000446	

*参阅产品目录详细查找适用性

Cross-check eligibility for more details with parts catalogue

批准放行证书/适航批准标签

AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG

使用者/安装者职责

USER/INSTALLER RESPONSIBILITIES

- (1)必须明确：本文件并不批准零件/组件/部件可以装到有关产品上。
- (2)当使用者/安装者使用的是所在国适航局的条例，而不是本表第1项中所指国家适航局的条例时，使用者/安装者必须保证所在国的适航当局能接受所指国家适航当局批准出口的零件/组件/部件。
- (3)表中第14项、第15项的陈述，并不说明本表是安装批准。在所有情况下，航空器使用前，航空器使用者/安装者应把按本国适航条例颁发的安装批准放入维修记录中。

(1) It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

(2) Where the user/installer works in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1 it is essential that the user/installer ensure that his/her Airworthiness Authority accepts parts/components/assemblies from the Airworthiness Authority of the country specified in block 1.

(3) Statements 14 and 15 do not constitute installation certification. In all cases the aircraft maintenance record must contain an installation certification issued in accordance with the national regulation by the user/installer before the aircraft may be flown.

MAINTENANCE ORDER		V Activity Category		1027869 Maintenance Number		FSCM C9072		 AIRBUS	
Customer AJW	Part Number Z133H031951A			Serial No SPEC2000 133H03000462			Amd.		
	Description FLIGHT ATTND PANEL			Quantity 1			Repair-Station BUX		
Customer Order R278818		Cust. Order Date 13.11.2015		Work Order 1027869		Work Order Date 26.11.2015		Prio ROUTINE	
Required Activities:	Test X	Repair	Modify	Inspection X	Scrap	Overhaul	Entry Date 25.11.2015	Redelivery Date 01.12.2015	
Reason for Return F/CTL ELAC 1 FAULT									
Operator TAI	Removal Date 26.10.2015	AC-Reg N492TA	AC Type A320	Station	Release Certificate AAC038/EDUAL	Warranty	Chargeable X		
		Operators Man		OEM-Man O.E.M.-M	Aviation Device YES		Package OK		
Administrator: Seckerdieck		Department: ECYS1			Phone: (0)40 743 54998				

MAINTENANCE REPORT	Preliminary Inspection/HDI	Pre- Strip-Test YES	Cond. elec. OK	Cond. SW OK	Cond. mech. OK	BITE N/A
	Status of Removal Unjustified Removal		Tech. warranty YES		Missing Part NO	
Findings: No error detected. Note: The FAP was modified by customer as per SB Z133H-23-004 and SB Z133H-23-005. For this reason the actual FAP Amendment: A,1. There are small deformations on the back of the rear casing without effect on the FAP function.						
Remarks: Work performed as per: CMM 23-77-12 Rev. 12 MAR-17-2015.						
Work performed: Preliminary and hidden damage inspection performed; the internal flashcard replaced; acceptance test successfully performed.						
49 261 Geiger						
Final Condition	PN_After Z133H031951A		SN_After 133H03000462		AMD_After A,1	
	Tested X	Repaired	Modified	Modified internal	Cond as is	Scrapped
	Warranty_Charge_WC C		NFF X		QA-Inspected 22. Dez. 2015	
Work performed staff Geiger		Work performed department ECYS3		Work performed date 18.12.2015		