



1. Approving Civil Aviation Authority/Country: FAA/United States		2.		AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 20210009206708Y15 341303974	
4. Organization Name and Address: Honeywell International Inc. 13051 66th Street Plant 4 Largo, FL 33773				Repair Station KE2R949K		5. Work Order/Contract/Invoice Number: 550224202 341303973 Page 1 of 1		11. Status / Work: REPAIRED	
6. Item:		7. Description:		8. Part Number:		9. Quantity:		10. Serial Number:	
001		MODAL SUPPRESSION ACCEL - ASSEMBLY AND I		HG2280AB01		1		56063077	
12. Remarks: THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH: CMM 27-20-03 Rev 5, JAN/31/2019 TSN/CSN: 12259.42/9197									
SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NO. EASA 145.4538									
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.				14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.					
13b. Authorized Signature:				13c. Approval/Authorization No.:				14b. Authorized Signature: <i>Quynh-Thu Halvorson</i>	
13d. Name (Typed or Printed):				13e. Date(dd/mm/yyyy):				14c. Approval/Certificate No.: KE2R949K	
13d. Name (Typed or Printed): Quynh-Thu Halvorson				13e. Date(dd/mm/yyyy): 18/APR/2021				14e. Date(dd/mm/yyyy): 18/APR/2021	
User / Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown. FAA FORM 8130 - 3 (02-14)									

NSN : 0052 - 00 - 012 - 9005



1. 国家 Country 中国 China	2. 中国民用航空总局 CAAC ☐ 符合性 批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG	3. 证书编号 20210009206709Y05 341303974	Airworthiness 适航性 ☒ 符合性		Certificate Ref. No.	
4. 单位 Organization Honeywell International Inc. 13051 66th Street Plant 4 Largo, FL 33773	5. 工作单/合同单/货单 Work Order/Contract/Invoice 550224202 341303973 Page 1 of 1					
6. 序号 Item 001	7. 内容 Description MODAL SUPPRESSION ACCEL - ASSEMBLY AND I	8. 件号 Part No. HG2280AB01	9. 适用性 Eligibility NOT KNOWN	10. 数量 Qty 1	11. 系列号/批号 Serial/Batch No. 56063077	12. 产品状态 Status/Work REPAIRED
13 备注 Remarks THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH: CMM 27-20-03 Rev 5, JAN/31/2019 TSN/CSN: 12259.42/9197						
SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED						
14. 新产品 New Parts 兹声明上述产品除第13项的其它规定以外，已按照上述国家适航条例进行制造/检查，并且该产品(出口产品)符合经批准的型号设计资料和进口国提出的专用要求。 Certifies that the part(s) identified above except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and / or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.		15. 使用过的产品 Used Parts 兹声明上述产品除第13项的其它规定以外，已按照上述国家适航条例和进口国通知的特殊要求进行了工作，该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is(are) in condition for safe operation and considered ready for release to service. (over)				
16. 批准人签名 Signature 		18. 批准日期 Date APR/18/2021				
17. 批准人姓名 (打印的) Name (Printed) Quynh-Thu Halvorson		19. 中国民航总局授权 Issued by or on behalf of the CAAC F00100463				

SERVICE REPORT

Clearwater Commercial Op SPEX

SR NUMBER: 5015426410		341303974	FAA: KE2R949K	EASA: 145.4538
PO: 550224202	CUSTOMER PART NUMBER:		CONTRACT NUMBER:	
DATE REJECTED: 07 JAN 2021	DATE RECEIVED: 19 FEB 2021		DATE COMPLETED: 18 APR 2021	
A/C TYPE: UNK	A/C TAIL NUMBER:		A/C SERIAL NUMBER:	
PACKING STATUS:	SEALS INTACT: Intact		PHYSICAL DAMAGE: No	
REASON FOR REMOVAL: SPEX - MAINTENANCE MESSAGE 27-14152 ACTIVE STORED. GROUND SYSTEM TEST NG. CAAC TAG				
PART NUMBER	AS RECEIVED: HG2280AB01		AS RELEASED: HG2280AB01	
DESCRIPTION:	MODAL SUPPRESSION ACCEL - ASSEMBLY		MODAL SUPPRESSION ACCEL - ASSEMBLY	
SERIAL NUMBER	56063077		56063077	
UID(MFR/SPL PNO SER/UCN)	65507 56063077		65507 56063077	
HW MOD STATUS:	MOD 1		MOD 1	
SW MOD STATUS:				
SOFTWARE LOAD:				
REASON FOR REMOVAL CONFIRMED: Rejection Confirmed			ESTIMATE SUPPLIED: No	
PRIMARY SHOP FINDING: Hardware Fault Found			WARRANTY:	
TYPE OF SERVICE: REPAIRED			TECHNICIAN: David Alvarez	
MAINTENANCE STATEMENT: PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2.				
SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE: _____				
SIGNATURE OF AUTHORIZED PERSON: _____				
Complied With CMM/Eng Documentation: 27-20-03/Rev 5/Rev Date 31 JAN 2019; Service Bulletins: Customer Manuals/Documentation:				
SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.				

SERVICE REPORT

Clearwater Commercial Op SPEX

SR NUMBER: 5015426410

FAA:
KE2R949K

EASA:
145.4538

PO:
550224202

CUSTOMER PART NUMBER:

CONTRACT NUMBER:

Previously Complied With

CMM/Eng Documentation:

Service Bulletins:

Customer Manuals/Documentation:

Evaluation Findings

Voltage Position fault found.

Work performed / Comments to Customer

A) Performed Incoming ATP. Voltage Position fault found. Replace Accel CCA. Removed Accel S/N 73420067, installed new S/N 74300980.

B) Replaced Chassis S/N 60484 with new S/N 100221 due to SPEX.

C) Device has passed all certification tests.

D) Passed power isolation test.

TSN/CSN: 12259.42/9197

DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SB
Replace	PLATE, INFORMAT	10068381-102		10068381-102		1		
Replace	CCA, ACCEL	26021119-104	74300980	26021119-104	73420067	1		
Replace	ASSEMBLY, CHASS	26022169-101	100221	26022169-101	60484	1		
Replace	COVER, CHASSIS	26021460-101		26021460-101		1		
Replace	PLATE, IDENTIFI	26004528-115		26004528-115		1		

MEASUREMENT DESCRIPTION	MEAS. VALUE (DECIMAL)	MEAS. VALUE (HH:MM)
Time Since Repair		0:00
Cycles Since Repair		