

1. Approving Civil Aviation  
Authority/Country:

2.

FAA/UNITED STATES

4. Organization Name and Address:

Silver Wings Aerospace

FAA # 9ARR711Y

25400 S.W. 140 AVENUE

PRINCETON, FL 33032

Ph: 305-258-5950, Fax: 305-258-5953

FAA Approval Holder: 9ARR711Y

3. Form Tracking Number:

175484

5. Work Order/Contract/Invoice  
Number:

341091 / R412433

6. Item

7. Description:

1 MODULE, WINDOW AND PITOT HEAT

8. Part Number:

233A3201-305

9. Quantity:

1

10. Serial Number:

D00449

11. Status/Work:

TESTED

12. Remarks:

Tested in accordance with Bae Systems CMM 30-09-05, Revision # 42, Revision Date 10/23/2017. No AD's or SB's were performed at this visit. Full details of work carried out per work order no. 341091 TSN: Unknown, TSO: Unknown

Silver Wings Aerospace, Inc. certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 approval no. EASA.145.6394

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No:

14b. Authorized Signature:

14c. Approval/Certificate No:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

Octavio Rodriguez

23/Jun/2023

#### User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.





**Silver Wings Aerospace**  
FAA # 9ARR711Y  
25400 S.W. 140 AVENUE  
PRINCETON, FL 33032  
Ph: 305-258-5950, Fax: 305-258-5953  
sales@silverwingsaerospace.com

## Tear Down/Inspection

Work Order #: 341091

Date Printed: 6/23/2023

Page: 1

### Customer:

ATTN: Charlotte Walls  
AJ WALTER AVIATION LIMITED  
The Headquarters  
Maydwell Avenue  
Slinfold, West Sussex, UK RH13 0AS  
UNITED KINGDOM

### Ship To:

AJ WALTER AVIATION LIMITED  
B&H Doral  
1523 NW 82 Ave  
Doral, FL 33126

**Part Number:** 233A3201-305

**Serial Number:** D00449

**Description:** MODULE, WINDOW AND PITOT HEAT  
**Customer R/O:** R412433

### Symptoms:

Customer Request

Work Requested: BENCHTEST  
Discrepancy/Reason for Removal: NONE REPORTED  
Note: N/A

### Faults:

#### Preliminary Inspection

Verified P/N as 233A3201-305 IAW BAE Systems CMM 30-09-05, Revision 42, Revision Date 23/Oct/2017.  
Verified S/N as D00449 IAW ID plate and customer's repair order.  
Visual Inspection: Unit received in good condition  
TSN: Unk  
CSN: Unk  
TSO: Unk  
CSO: Unk

#### Pre-test

Unit passed functional test, tested IAW BAE Systems CMM 30-09-05, Revision 42, Revision Date 23/Oct/2017.  
Customer complaint verified: N/A.

#### Hidden Damages

N/A

#### Teardown Findings

Unit cleaned and inspected IAW BAE Systems CMM 30-09-05, Revision 42, Revision Date 23/Oct/2017.  
No defects noted  
AJW has no specialized work instructions.  
\*\* Bench Test Estimate \*\*

#### AD & SB Status

AD 2012-24-08 does not apply to this unit.

### Corrective Actions:

#### Corrective Action

Performed services listed under teardown findings.  
The unit was Bench Tested IAW BAE Systems CMM 30-09-05, Revision 42, Revision Dated 23/Oct/2017.

#### Modifications

N/A

23 JUN 2023



**SILVER WINGS  
AEROSPACE**  
A WENCOR COMPANY

**Silver Wings Aerospace**  
FAA # 9ARR711Y  
25400 S.W. 140 AVENUE  
PRINCETON, FL 33032  
Ph: 305-258-5950, Fax: 305-258-5953  
sales@silverwingsaerospace.com

## **Tear Down/Inspection**

Work Order #: 341091

Date Printed: 6/23/2023

Page: 2

### Additional Comments

N/A.

### Assets

002392, 002393, 003421, 001244, 00335, 002356, 004024

23 JUN 2023