



## PACKING LIST

PURITAN-BENNETT WEMAC DIVISION  
18475 PACIFIC STREET  
FOUNTAIN VALLEY, CA 92708

TELEPHONE: 1-714-962-8874

B TRI STAR AEROSPACE INC  
I PO BOX 542468  
L DALLAS TX  
L

S TRI STAR AEROSPACE INC  
H 2527 WILLOWBROOK ROAD  
I DALLAS, TX  
P

T 75354  
O

T 75220  
O

BILL TO CUSTOMER NO. 800922-00

SHIP TO CUSTOMER NO. 800922-00

8535299	0	8/14/98	1
V 4673AV INV# 85740651			
UPS COLL			
22 #	2		FACT
		NET 30 DAYS	
10-29-98	PKB	Robyn	

1	002000-06	CLAMP WIRE ASSEMBLY CUST. PART: 2000-6 S	2000	2000			
2	002000-15	CLAMP WIRE ASSEMBLY S  SALES ORDER SPECIAL INSTRUCTIONS: NOTE: PLEASE REFERENCE INVOICE NUMBER ON THE CHECK(S) WHEN REMITTING PAYMENT. THANK YOU.	2000	2000			

ALL CLAIMS MUST BE MADE WITHIN 24 HOURS AFTER RECEIPT OF THIS MERCHANDISE

RECEIVED  
BY X

DATE  
RECEIVED

12,800.00

Walter Aviation  
Scan and copy  
Copy 3 - held only held by AJW  
Copy 4 - retained  
Copy 5 - held only held by AJW  
Sign at  
Stamp Number AJW  
Date 8/12/2011

### **CERTIFICATE OF COMPLIANCE**

THIS IS TO CERTIFY THAT THE PARTS FURNISHED ON THIS ORDER HAVE BEEN FUNCTIONALLY TESTED IN ACCORDANCE WITH STANDARD PROCEDURES SET UP BY THE WEMAC DIVISION. MATERIAL AND/OR PARTS FURNISHED ON THIS ORDER HAVE BEEN MANUFACTURED IN ACCORDANCE WITH ALL APPLICABLE INSTRUCTIONS AND SPECIFICATIONS AND CONFORM TO FAA/CAA TYPE CERTIFICATION. PHYSICAL AND CHEMICAL DATA WHICH PERTAINS TO THIS ORDER ARE AVAILABLE FOR INSPECTION.

WE HEREBY ASSUME THE RESPONSIBILITY THAT ALL PARTS SHIPPED WILL BE IN COMPLIANCE WITH THE ABOVE CERTIFICATION.

WEMAC DIVISION  
NELLCOR PURITAN BENNETT  
PURITAN-BENNETT AERO SYSTEMS CO.  
18475 PACIFIC STREET  
FOUNTAIN VALLEY, CA 92708

BY



JAMES J. ALLINGER  
QUALITY CONTROL MANAGER