

1. 国家 CHINA	Country:	2. 中国民用航空总局 CAAC 授权发布证书/航空认证标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG	X 适航性 Airworthiness	3. 证书编号 Certificate Ref. No. 292034-18
4. 单位 Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300	Organization:	Repair Station# F00100391	5. 工作单/合同单/货单 Work Order/Contract/Invoice Number: 292034 / ERO15560	
6. 序号 Item:	7. 内容 Description:	8. 件号 Part Number:	9. 通用性 Eligibility:*	10. 数量 Quantity:
1	FITTING ASSY-THRUST	310A1036-1	NOT KNOWN	1
11. 系列号/批号 Serial/ Batch Number:	12. 产品状态 Status/Work: OVERHAULED			
13. 备注 OVERHAULED IAW CMM ATA 71-21-13 REV: 59 DATE: 11/01/2017 TSN/CSN: UNKNOWN TSO/CSO: 0 Remarks: ESN: 721138				
15. 使用过的产品 Used Parts 兹声明上述产品除第 13 项的其它规定以外, 已按照上述国家适航条例和特殊要求进行了工作, 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in Block 13, the work was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the parts(s) is (are) in condition of safe operation and considered ready for release to service. (over)				
16. 批准人 Signature:		18. 批准日期 Date 21 Aug, 2018		
17. 批准人姓名 (打印的) Name (Printed)		James T. Magnussen		
AAC-038(12/94)				
*参阅产品目录详细查找			*Cross-check eligibility for more details with parts catalogue	

WORK ORDER FORM 100

Page No. 1

Triumph Accessory Services -Grand Prairie

1038 Santerre Drive

Grand Prairie, TX 75050-1937

972/623-9300 FAX (972) 660-1580

FAA CRS No: GPYR474X



Work Order: 292034-18

CAAC CRS No: F00100391

Customer: 012424 / AJ WALTER AVIATION LTD

Cust RO#: ERO15560

Step: SHOP COMPLETE

Dept#: EMT

Work Req: OH

Warranty Code: NW Qty: 1

P/N: 310A1036-1 / FITTING ASSY-THRUST

S/N: N/A

Mfg: BOEING

Manual#: 310A1020 RevDate: 11/01/2017 Rev#: 59

ATA: 71-21-13

OH UNDER ENG RP

***** COMPLY WITH CUSTOMER P.O. REQUIREMENTS *****

Date Recvd: 08/16/2018 Date Reqr'd: / / Date Estmtd: / /

PRELIMINARY INSPECTION: DATE: 08/16/2018 TECH: Miguel O. Ambersley (esign)
NO VISIBLE ISSUES NOTED PRIOR TO CLEANING

NO ADS

TEARDOWN FINDINGS:

CLEANED AND INSPECTED TO O/H CONDITION IAW ATA 71-21-13

REV. 59 DTD 11/01/2017.

NO DISCREPANCIES FOUND

TECHNICIAN: Jesse C. Patton (esign) DATE: 08/17/2018

CORRECTIVE ACTION:

OVERHAULED IAW ATA 71-21-13 REV. 59 DTD 11/01/2017.

* OVERHAULED IAW CMM ATA 71-21-13 REV: 59 DATE: 11/01/2017

* TSN/CSN: UNKNOWN TSO/CSO: 0

* ESN: 721138

TECHNICIAN: Jesse C. Patton (esign) DATE: 08/20/2018

MODIFICATION/SERVICE BULLETINS/AD's:

N/A

Test Technician: DATE: / /

Supervisor: Leonardo Saldivar (esign)

DATE: 08/21/2018

Final Inspection: James T. Magnussen (esign)

DATE: 08/21/2018

ADDITIONAL COMMENTS:

(1) N/A

(2)



WORK ORDER FORM 100

Page No. 2

Triumph Accessory Services -Grand Prairie

1038 Santerre Drive

Grand Prairie, TX 75050-1937

972/623-9300 FAX (972) 660-1580

FAA CRS No: GPYR474X



Work Order: 292034-18

CAAC CRS No: F00100391

Customer: 012424 / AJ WALTER AVIATION LTD

Cust RO#: ERO15560

Step: SHOP COMPLETE

Dept#: EMT

Work Req: OH

Warranty Code: NW Qty: 1

P/N: 310A1036-1 / FITTING ASSY-THRUST

S/N: N/A

Mfg: BOEING

Labor Task Control#



2. Authority/Country: FAA/UNITED STATES		3. Form Tracking Number: 292034-18	
4. Organization Name and Address: Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300		5. Work Order/Contract/Invoice Number: 292034 / ERO15560	
6. Item: 7. Description:		8. Part Number:	9. Quantity:
1	FITTING ASSY-THRUST	310A1036-1	1
10. Serial Number:		11. Status/Work:	
N/A		OVERHAULED	
12. Remarks: OVERHAULED IAW CMM ATA 71-21-13 REV: 59 DATE: 11/01/2017 TSN/CSN: UNKNOWN TSO/CSO: 0 ESN: 721138			
Certifies that the work specified in block 11/12 was carried out in accordance with EASA part 145 and, with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number: EASA 145.5893			
14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
14b. Authorized Signature: 		14c. Approval/Certificate No.: GPYR474X	
14d. Name: (Typed or Printed) James T. Magnussen		14e. Date (dd/mm/yyyy): 21 AUG 2018	
User/Installer Responsibilities			
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs the work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1. Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with national regulations by the user/installer before the aircraft may be flown.			
FAA Form 8130-3 (02-14)			
FAA authorized authority per Op Specs A025 for electronic signatures IAW AC 120-78.			
NSN: 0052-00-012-9005			