


1. Approving Civil Aviation Authority / Country: FAA/United States		2. Authorized Release Certificate FAA Form 8130-3, Airworthiness Approval Tag		3. Form Tracking Number: 145967	
4. Organization Name and Address: Aviation Instruments Repair Specialists, Inc. A.I.R.S./14316 Commerce Way Miami Lakes, FL 33016 U.S.A. Phone: (305) 887-5600 Fax: (305) 820-0931				5. Work Order / Contract / Invoice Number: WR42300	
6. Item:		7. Description:		8. Part Number:	
1		AUDIO CONTROL PANEL		5145-1-79	
9. Quantity:		10. Serial Number:		11. Status/Work:	
1ea.		10514		REPAIRED	
12. Remarks: REPAIRED in accordance with CMM: 23-50-86 Revision: 2 Date: 3/22/2011 Full details of work carried out per work order no. 145967 Modification Level: N/A Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the AUDIO CONTROL PANEL is considered ready for release to service under EASA Part 145 approval no. EASA.145.5033. No applicable A.D. or S.B. Required. ECCN#9A991D.					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.					
13b. Authorized Signature: Not Applicable		13c. Approval/Authorization No.: Not Applicable		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13d. Name (Typed or Printed): Not Applicable		14b. Authorized Signature: 		14c. Approval/Certificate No.: VTBR433V	
		14d. Name (Typed or Printed): Elio Kocijancic		14e. Date (dd/mm/yyyy): 18/Jul/2018	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

TearDown/Inspection Form

Aviation Instruments Repair Specialists, Inc.

A.I.R.S./14316 Commerce Way

Miami Lakes, FL 33016

U.S.A.

Phone: (305) 887-5600 Fax: (305) 820-0931

C.R.S. No.: VTBR433V

Work Order: 145967

Date: July/18/2018

Phone: (305) 887-5600

Fax: (305) 820-0931

Sold To:

A J WALTER AVIATION

The Headquarters, Maydown Ave. Slinfold

West Sussex RH13 0SH, UK

Ship To:

A J WALTER AVIATION LIMITED

THE HEADQUARTERS MAYDWELL AVENUE

SLINFOLD, WEST SUSSEX RH13 0SH

Part Number: 5145-1-79

Serial: 10514

Manufacturer: AVTECH

Description: AUDIO CONTROL PANEL

Model:

Purchase Order: WR42300

Service Performed: REPAIRED

Data used: Manual Number: 23-50-86 Revision: 2 Date: 3/22/2011

TearDown/Inspection Data

1. Removal: NO BACKGND LIGHT

Inst.: No Instructions. Possible warranty consideration.

2. Initial Inspection Findings

Appearance: Normal on Visual Inspection

Corrosion: No Corrosion Noted

Loose or Missing Parts: No Loose or Missing Parts

Physical Damage: Edgelight Assy, Jack Bracket

Mod. Level: N/A

3. Teardown

Disassembly: Normal

Cleaning: Normal Cleaning

Painting: Normal Painting

Assembly: Normal Assembly

4. Test

Operation: Operation I/A/W Mfg. Specs

Was Complaint Verified: Yes

Mods. Completed: None

5. Final

Warranty Accepted: No

Final Test and Inspection:

Final Inspection Normal

T.S.O.:

A.T.A.: 23-50-86

A.D. S.B. NO A.D. / S. B. REQUIRED

Work Done: UNIT FOUND WITH BACKGROUND LIGHTING INTERMITTENT, FOUND DEFECTIVE EDGE LIGHT ASSEMBLY AND JACK BRACKET. UNIT WAS INSPECTED, DISASSEMBLED, CLEANED, REPLACED DEFECTIVE COMPONENTS, AND ASSEMBLED. REPAIRED I/A/W MFG. SPECS. TESTED OPERATION AND FOUND READY TO RETURN TO SERVICE. NO APPLICABLE SB OR A/D'S ON FILE. ATA 23-50-86. ECCN#9A991D. WORK BY JESUS PADRON.

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work

Order No.: 145967

Inspector's Name: Elio Kocijancic

Certificate No. 2569075

Technician: Jesus Padron

Signature: _____

Date: July/18/2018

Form CRS-3