

Approving Competent Aviation Authority / Country: United Kingdom Civil Aviation Authority		2 AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number: L 1881068	
Organisation Name and Address: Panasonic Panasonic Avionics Corporation Quadrant House, Heron Drive, Parlaunt Road, Langley Berks, SL3 8XP, UK				5. Work Order/Contract/Invoice 184288	
7. Description PCU		8. Part No. RD-AX6740-54		9. Qty. 1	
		10. Serial No. D913493		11. Status / Work REPAIRED	
Remarks LRU CONFORMED IAW CMM 44-23-04 REV 18 DTD FEB 12.					
14a. ☒ PART 145.A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. UZVY163X. Panasonic Avionics Corporation internal reference SR 2857452 ☐ Certifies the items identified above were manufactured in conformity to approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12					
14b. Authorised Signature: 		14c. Certificate/Approval reference No: UK.145.00297			
14d. Name Mick White				14e. Date (dd mmm yyyy) 03-AUG-2012	

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Panasonic

Panasonic Avionics CorporationQuadrant House, Heron Drive, Parlaunt Road,
Langley Berks, SL3 8XP, UK.

Tel: +44(0) 1753 741450 Fax: +44(0) 1753 741481

REPAIR REPORT / DELIVERY ORDERSOLD TO **AJ WALTER AVIATION**
VISCOUNT HOUSE
PARTRIDGE GREEN
WEST SUSSEX, ENGLAND RH13 8RA, GBSHIP TO **AJ WALTER AVIATION**
VISCOUNT HOUSE
PARTRIDGE GREEN
WEST SUSSEX, ENGLAND RH13 8RA, GB

PAGE 1 of 1

SHIP TRANSACTION:

CUSTOMER P.O. NUMBER 184288		CUSTOMER 1001	TAIL NO. XA-VOE	CUST PROD REF 6285340	SERVICE REQUEST 2857452	
PART NUMBER RD-AX6740-54		NOMENCLATURE PCU			DATE REMOVED	DATE RECEIVED 20-JUL-2012
SERIAL NUMBER D913493		DATE OF MFG 31-JUL-2008	WTY START DATE 14-JUL-2008	WTY END DATE 13-JUL-2011	DATE REPAIRED 28-JUL-2012	SHIP DATE
MOD IN 0						
REASON FOR CUSTOMER REJECTION	PLUG BROKEN INSIDE					
INTERNAL INSPECTION	No Physical Damage - DIRTY.					
EXTERNAL INSPECTION	Physical Damage - DIRTY. SHEARED BACK COVER - WORN FIXING SCREW - MINOR SCRATCHES ON FRONT COVER NO ACTION TAKEN -					
ACTUAL FAILURE / CORRECTIVE ACTION	CUSTOMER COMPLAINT CONFIRMED.REPLACED INTERMITTENT JACK SOCKETS, FIXING SCREW & BACK COVER. UNIT CLEANED AND TESTED - PASSED ALL FUNCTIONAL TESTS. ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 44-23-04 REV 18 DTD FEB 12.					

MOD OUT: 0

INSPECTED BY: **Mick White**REPAIRED BY: **PATEL, ASHOK**

PART NUMBER	DESCRIPTION	C			
R6KF298YA	BACK COVER				
R6XSNBP19UWK	TERMINAL SCREW,STEEL				
R5J1D24ZA	JACK	1			
R5J1D23ZA	JACK	1			

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.*** WTY CODES** NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged