



1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 32643	
4. Organization Name and Address: 1ST CHOICE AEROSPACE 3361 Enterprise Way, Miramar, FL 33025, Fax: 954/430-6601, 954/430-6600			5. Work Order/Contract/Invoice Number: 32643 / T33219		
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
001	T495 WIRING HARNESS	CA170-00	1	YC020282-P	REPAIRED
12. Remarks: This item was Repaired I/A/W Manual # CMM 77-21-14, Revision # 5 Revision Date 30/Sep/2011 AD NO 2007-03-15 IS NO APPLICABLE PER S/N. NO SB'S INSTALLED. REMOVED SERVICEABLE FROM ESN: 779338.					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 Approval no. EASA.145.6610 14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.					
			14b. Authorized Signature: 		14c. Approval/Certificate No.: 9QAR940B
			14d. Name: (Typed or Printed) LUIS MANUEL		14e. Date (dd/mm/yyyy): 29/Oct/2019
User/Installer Responsibilities It is important to understand that the existence of this Document alone does not automatically constitute authority to install the aircraft/engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts aircraft engine(s)/propeller(s)/article(s) from the Airworthiness Authority of the country specified in block 1. Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with national regulations by the user/installer before the aircraft may be flown.					

WORK ORDER FORM 100

Page No. 1

1ST CHOICE AEROSPACE

3361 Enterprise Way
Miramar, FL 33025
Fax: 954/430-6601
954/430-6600

FAA CRS No: 9QAR940B

WORK ORDER: 32643-19

Customer: AJW001 / AJ WALTER AVIATION

Dept#:INS

Location:FNL

Cust RO#: T33219

Step:CLOSED

Warranty Code: 00 / 0

Mfg:ESTERLESTERLINE

Goodthru AD#2007-03-15

Outgoing CA170-00 / T495 WIRING

S/N: YC020282-P

Incoming P/N: CA170-00		
Incoming S/N: YC020282-P		
Incoming Work Req.: BC		Outgoing Work Req: RE
Manual#: 0190	RevDate: 30/Sep/2011 Rev#: 5	ATA: 77-21-14
Tools: A1010, A0933, A0063, A0002, A1145, A1566, A1567, A1568		
Reason/Rm: PLEASE QUOTE FOR TEST/RECERT-IF IT FAILS TEST PLEASE QUOTE TO REPAIR AND HOLD FOR A RESPONSE REMOVED SERVICEABLE FROM ESN:779338.PLEASE TEST UNDER T AND M QUOTE AND HOLD. Date Recvd: 16/Oct/2019 Date Reqr: 28/Oct/2019 Date Estmtd:		
PRELIMINARY INSPECTION: DATE: 23/Oct/2019 INSPECTOR: LAM VERIFIED P/N AND S/N WITH R/O. RECEIVED UNIT OUT OF ITS ORIGINAL SHAPE. MISSING PLUGS. CONTAMINATED EXTERNALLY WITH GREASE.		
PRE TEST (Yes/No): Y DATE: 23/Oct/2019 INSPECTOR: LAM UNIT PASSED FUNCTIONAL TEST, HOWEVER UNIT FAILED ORIGINAL SHAPE TEST		
HIDDEN DAMAGE: NONE NOTED		
TEARDOWN FINDINGS: TROUBLESHOOTING REVEALED UNIT OUT OF ITS ORIGINAL SHAPE AND MISSING PLUGS. AD #2007-03-15 IS NOT APPLICABLE DUE TO THE EGT HARNESS IS NOT LISTED IN ATTACHED TABLE. RESHAPED TO ORIGINAL FORM, PARTS, AND REMOVAL OF THE CONTAMINATION IS REQUIRED. UNIT REQUIRES REPAIR. REPAIR QUOTE TECHNICIAN:JCB DATE: 23/Oct/2019 INSPECTOR: LAM		
FINAL INSPECTION BEFORE ASSEMBLY: DATE: INSPECTOR: N/A		
CORRECTIVE ACTION: THIS UNIT WAS CLEANED, INSPECTED, REPAIRED AS NECESSARY, AND FUNCTIONALLY TESTED IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS. AD# 2007-03-15 IS NOT APPLICABLE PER S/N. TECHNICIAN:JCB DATE: 28/Oct/2019 INSPECTOR: LAM		

Printed 29/Oct/2019

15:34:49

ALAM-PC #

Labor Task Control#



WORK ORDER FORM 100

Page No. 2

1ST CHOICE AEROSPACE

3361 Enterprise Way
Miramar, FL 33025
Fax: 954/430-6601
954/430-6600

FAA CRS No: 9QAR940B
WORK ORDER: 32643-19

Customer: AJW001 / AJ WALTER AVIATION

Dept#:INS

Location:FNL

Cust RO#: T33219

Step:CLOSED

Warranty Code: 00 / 0

Mfg: ESTERL ESTERLINE

Goodthru AD#2007-03-15

Outgoing CA170-00 / T495 WIRING

S/N: YC020282-P

MODIFICATION/SERVICE BULLETINS:

*AD NO 2007-03-15 IS NO APPLICABLE PER S/N.

*NO SB'S INSTALLED.

*REMOVED SERVICEABLE FROM ESN: 779338.

AD No: 2007-03-15

Test Data Used: ATA:77-21-14 REV#5 30SEP2011

Test Technician: JCB

DATE: 28/Oct/2019

Final Inspection:LAM

DATE: 29/Oct/2019

ADDITIONAL COMMENTS:

AT THE END OF THE S/N HAS A -P AND IS NOT PART OF THE S/N PER CHECKSUM

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE
FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF
THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by LUIS MANUEL

Date 29/Oct/2019

Printed 29/Oct/2019

15:34:49

ALAM-PC #

Labor Task Control#

wcpstrn